

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
University-wide

	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty Spaces	Occupied Spaces	% Occupied
			am	am	am	am	pm	pm	pm	pm	pm	pm			
University of California, San Diego	A	1963	1356	971	645	477	408	403	397	441	532	658	397	1566	80%
	B	5072	2370	1441	901	668	710	772	754	895	1299	1994	668	4404	87%
	S	7205	4267	3306	2570	1962	1714	1636	1712	2003	2354	2980	1636	5569	77%
	Visitor	711	434	295	200	166	149	145	144	174	197	189	144	567	80%
	Reserved	282	191	167	130	110	109	112	104	108	116	139	104	178	63%
	Allocated	1618	1086	784	521	407	468	466	462	489	586	739	407	1211	75%
	Accessible	327	233	194	160	143	144	147	147	158	188	209	143	184	56%
	UC Vehicle	365	140	164	157	151	149	152	155	146	137	131	131	234	64%
	Service Yard	157	76	54	52	46	48	46	49	54	69	82	46	111	71%
	Loading	118	77	59	50	39	38	43	34	41	39	42	34	84	71%
	Total	17818	10230	7435	5386	4169	3937	3922	3958	4509	5517	7163	3922	13896	78%

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
By Location

Location	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty Spaces	Occupied Spaces	% Occupied
			am	am	am	am	pm	pm	pm	pm	pm	pm			
La Jolla Campus	A	1731	1243	887	586	435	367	357	356	398	485	589	356	1375	79%
	B	3905	2034	1220	781	577	607	644	606	709	998	1527	577	3328	85%
	S	7205	4267	3306	2570	1962	1714	1636	1712	2003	2354	2980	1636	5569	77%
	Visitor	702	431	293	199	166	148	144	144	173	196	186	144	558	79%
	Reserved	154	101	84	68	58	59	57	57	59	64	74	57	97	63%
	Allocated	1175	833	604	445	355	384	383	401	426	498	612	355	820	70%
	Accessible	281	216	184	153	135	137	137	139	150	173	190	135	146	52%
	UC Vehicle	354	135	159	152	144	143	146	148	140	131	126	126	228	64%
	Service Yard	141	72	52	50	42	46	44	47	51	64	74	42	99	70%
	Loading	114	75	59	49	39	38	43	34	40	39	42	34	80	70%
	Total	15762	9407	6848	5053	3913	3643	3591	3644	4149	5002	6400	3591	12171	77%
Medical Center Hillcrest	A	232	113	84	59	42	41	46	41	43	47	69	41	191	82%
	B	1167	336	221	120	91	103	128	148	186	301	467	91	1076	92%
	S														
	Visitor	9	3	2	1	0	1	1	0	1	1	3	0	9	100%
	Reserved	128	90	83	62	52	50	55	47	49	52	65	47	81	63%
	Allocated	443	253	180	76	52	84	83	61	63	88	127	52	391	88%
	Accessible	46	17	10	7	8	7	10	8	8	15	19	7	39	85%
	UC Vehicle	11	5	5	5	7	6	6	7	6	6	5	5	6	55%
	Service Yard	16	4	2	2	4	2	2	2	3	5	8	2	14	88%
	Loading	4	2	0	1	0	0	0	0	1	0	0	0	4	100%
	Total	2056	823	587	333	256	294	331	314	360	515	763	256	1800	88%

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
By Area

Area	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak				
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
Scripps Institution of Oceanography	A																
	B	107	66	38	20	8	13	15	13	13	19	30	8	99	93%		
	S	148	117	82	54	36	31	36	28	31	34	47	28	120	81%		
	Visitor	5	5	5	4	3	3	2	3	4	4	5	2	3	60%		
	Reserved	3	1	1	1	0	0	1	1	1	1	1	0	3	100%		
	Allocated	481	370	288	222	159	148	170	185	207	226	267	148	333	69%		
	Accessible	26	21	21	19	19	18	18	18	19	19	20	18	8	31%		
	UC Vehicle	13	5	5	5	5	4	3	3	3	3	3	3	10	77%		
	Service Yard	8	5	4	5	4	4	5	5	5	6	6	4	4	50%		
	Loading	9	7	7	5	4	3	1	3	4	5	5	1	8	89%		
Total	800	597	451	335	238	224	251	259	287	317	384	224	576	72%			
West Campus	A	1620	1190	853	558	410	337	326	323	364	448	545	323	1297	80%		
	B	3170	1670	961	562	380	402	437	396	486	721	1153	380	2790	88%		
	S	4335	1818	1394	1050	784	673	654	716	886	1054	1349	654	3681	85%		
	Visitor	697	426	288	195	163	145	142	141	169	192	181	141	556	80%		
	Reserved	151	100	83	67	58	59	56	56	58	63	73	56	95	63%		
	Allocated	422	292	216	176	161	148	143	157	165	180	205	143	279	66%		
	Accessible	213	169	146	124	109	107	109	112	118	137	148	107	106	50%		
	UC Vehicle	341	130	154	147	139	139	143	145	137	128	123	123	218	64%		
	Service Yard	121	59	43	41	34	37	35	37	40	50	58	34	87	72%		
	Loading	102	65	49	42	32	33	39	28	33	31	34	28	74	73%		
Total	11172	5919	4187	2962	2270	2080	2084	2111	2456	3004	3869	2080	9092	81%			
East Campus	A	111	53	34	28	25	30	31	33	34	37	44	25	86	77%		
	B	628	298	221	199	189	192	192	197	210	258	344	189	439	70%		
	S	2722	2332	1830	1466	1142	1010	946	968	1086	1266	1584	946	1776	65%		
	Visitor																
	Reserved																
	Allocated	272	171	100	47	35	88	70	59	54	92	140	35	237	87%		
	Accessible	42	26	17	10	7	12	10	9	13	17	22	7	35	83%		
	UC Vehicle																
	Service Yard	12	8	5	4	4	5	4	5	6	8	10	4	8	67%		
	Loading	3	3	3	2	3	2	3	3	3	3	3	2	1	33%		
Total	3790	2891	2210	1756	1405	1339	1256	1274	1406	1681	2147	1256	2534	67%			
Medical Center Hillcrest	A	232	113	84	59	42	41	46	41	43	47	69	41	191	82%		
	B	1167	336	221	120	91	103	128	148	186	301	467	91	1076	92%		
	S																
	Visitor	9	3	2	1	0	1	1	0	1	1	3	0	9	100%		
	Reserved	128	90	83	62	52	50	55	47	49	52	65	47	81	63%		
	Allocated	443	253	180	76	52	84	83	61	63	88	127	52	391	88%		
	Accessible	46	17	10	7	8	7	10	8	8	15	19	7	39	85%		
	UC Vehicle	11	5	5	5	7	6	6	7	6	6	5	5	6	55%		
	Service Yard	16	4	2	2	4	2	2	2	3	5	8	2	14	88%		
	Loading	4	2	0	1	0	0	0	0	1	0	0	0	4	100%		
Total	2056	823	587	333	256	294	331	314	360	515	763	256	1800	88%			

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
SIO South	A															
	B															
	S															
	Visitor															
	Reserved	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated	207	141	83	50	28	26	36	35	37	42	61	26	181	87%	
	Accessible	7	5	5	4	3	3	3	3	3	3	4	3	4	4	57%
	UC Vehicle	11	4	4	4	4	3	2	2	2	2	2	2	9	82%	
	Service Yard Loading	5	3	2	3	2	2	3	3	4	4	4	2	3	60%	
	8	6	6	4	4	3	1	3	4	4	4	1	7	88%		
Total	239	159	100	65	41	37	45	46	50	55	75	37	202	85%		
SIO West	A															
	B	102	63	35	18	7	10	13	11	11	17	29	7	95	93%	
	S															
	Visitor															
	Reserved															
	Allocated	22	8	2	0	0	0	2	1	2	3	6	0	22	100%	
	Accessible	4	4	4	4	4	4	4	4	4	4	4	4	0	0%	
	UC Vehicle															
	Service Yard Loading	1	1	1	1	0	0	0	0	0	1	1	0	1	100%	
Total	129	76	42	23	11	14	19	16	17	25	40	11	118	91%		
SIO Hillside	A															
	B	2	1	1	1	0	1	0	0	0	0	0	0	2	100%	
	S	148	117	82	54	36	31	36	28	31	34	47	28	120	81%	
	Visitor	5	5	5	4	3	3	2	3	4	4	5	2	3	60%	
	Reserved	2	1	1	1	0	0	1	1	1	1	1	0	2	100%	
	Allocated															
	Accessible	6	6	6	6	6	6	6	6	6	6	6	6	0	0%	
	UC Vehicle															
	Service Yard Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
Total	164	131	96	67	46	42	46	39	43	46	60	39	125	76%		
Aquarium	A															
	B	3	2	2	1	1	2	2	2	2	2	1	1	2	67%	
	S															
	Visitor															
	Reserved															
	Allocated	252	221	203	172	131	122	132	149	168	181	200	122	130	52%	
	Accessible	9	6	6	5	6	5	5	5	6	6	6	5	4	44%	
	UC Vehicle	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
	Service Yard Loading	2	1	1	1	1	1	1	1	0	1	1	0	2	100%	
Total	268	231	213	180	140	131	141	158	177	191	209	131	137	51%		
Theater District	A															
	B															
	S															
	Visitor															
	Reserved															
	Allocated	15	8	4	2	1	2	1	1	1	1	1	1	14	93%	
	Accessible															
	UC Vehicle															
	Service Yard Loading															
Total	15	8	4	2	1	2	1	1	1	1	1	1	14	93%		

Neighborhood	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty	Occupied	%
			am	am	am	am	pm	pm	pm	pm	pm	pm	Spaces	Spaces	Occupied
Revelle College	A	237	195	140	91	69	50	48	53	51	57	57	48	189	80%
	B	343	242	161	79	23	7	12	16	21	40	72	7	336	98%
	S	247	0	0	0	0	0	0	0	0	2	7	0	247	100%
	Visitor	40	27	17	5	4	3	3	3	2	3	5	2	38	95%
	Reserved	4	2	1	1	1	1	0	0	0	1	1	0	4	100%
	Allocated	24	21	18	14	13	12	10	9	7	10	14	7	17	71%
	Accessible	24	17	13	11	10	9	8	8	10	13	14	8	16	67%
	UC Vehicle	13	3	4	3	2	4	4	3	4	4	5	2	11	85%
	Service Yard	36	11	9	7	5	5	5	4	7	11	13	4	32	89%
	Loading	6	4	4	2	1	2	2	0	1	1	2	0	6	100%
Total		974	522	367	213	128	93	92	96	103	142	190	92	882	91%
Muir College	A	277	212	151	78	38	17	13	14	27	47	54	13	264	95%
	B	282	125	51	4	0	1	2	3	14	39	66	0	282	100%
	S	477	0	0	0	0	0	0	0	5	5	21	0	477	100%
	Visitor	122	48	20	1	1	1	2	1	6	5	3	1	121	99%
	Reserved	20	14	12	11	8	8	8	10	8	9	10	8	12	60%
	Allocated	87	69	53	43	37	26	21	35	40	42	46	21	66	76%
	Accessible	25	16	11	6	4	3	4	6	10	12	13	3	22	88%
	UC Vehicle	6	2	1	0	1	1	2	1	1	1	0	0	6	100%
	Service Yard	16	9	6	7	4	6	5	7	8	10	10	4	12	75%
	Loading	24	12	7	4	3	1	4	3	3	2	2	1	23	96%
Total		1336	507	312	154	96	64	61	80	122	172	225	61	1275	95%
Marshall College	A	96	73	45	14	4	8	6	5	12	26	36	4	92	96%
	B	293	135	70	18	3	4	8	4	12	34	60	3	290	99%
	S	55	0	0	0	0	0	0	0	1	0	0	0	55	100%
	Visitor	48	34	14	6	3	3	5	3	4	6	7	3	45	94%
	Reserved	10	7	5	5	5	7	5	5	5	5	4	4	6	60%
	Allocated														
	Accessible	13	11	10	6	4	4	4	4	5	9	9	4	9	69%
	UC Vehicle	2	0	0	0	0	1	0	0	0	1	1	0	2	100%
	Service Yard	9	5	4	4	5	4	4	4	5	6	5	4	5	56%
	Loading	8	4	3	2	0	1	1	0	2	2	1	0	8	100%
Total		534	269	151	55	24	32	33	25	46	89	123	24	510	96%
North Campus	A	160	143	134	122	115	108	107	106	106	108	119	106	54	34%
	B	926	631	462	364	305	325	338	305	327	381	500	305	621	67%
	S	1909	1364	1098	855	665	577	558	604	706	810	961	558	1351	71%
	Visitor	141	123	107	91	84	85	85	84	89	91	94	84	57	40%
	Reserved	15	10	9	6	6	7	8	5	7	7	8	5	10	67%
	Allocated	101	47	16	13	10	13	11	12	13	16	18	10	91	90%
	Accessible	46	41	36	35	31	32	34	33	33	34	36	31	15	33%
	UC Vehicle	14	9	8	9	8	6	9	7	7	9	9	6	8	57%
	Service Yard	8	6	4	5	3	3	5	5	4	5	5	3	5	63%
	Loading	12	10	8	8	9	9	10	9	8	8	8	8	4	33%
Total		3332	2384	1882	1508	1236	1165	1165	1170	1300	1469	1758	1165	2167	65%
Warren College	A	154	122	80	44	30	25	22	22	25	26	37	22	132	86%
	B	156	37	4	2	1	0	1	0	2	8	21	0	156	100%
	S	220	0	0	0	0	0	0	0	0	0	2	0	220	100%
	Visitor	18	8	5	2	3	1	3	0	3	1	1	0	18	100%
	Reserved	24	19	17	12	9	8	7	7	8	7	8	7	17	71%
	Allocated														
	Accessible	13	11	10	9	7	6	6	7	7	9	9	6	7	54%
	UC Vehicle														
	Service Yard	8	6	4	4	4	3	4	3	4	4	6	3	5	63%
	Loading	11	7	7	7	4	3	3	1	3	3	2	1	10	91%
Total		604	210	127	80	58	46	46	40	52	58	86	40	564	93%

Neighborhood	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty Spaces	Occupied Spaces	% Occupied	
			am	am	am	am	pm	pm	pm	pm	pm	pm				
Campus Services Complex	A															
	B	104	1	0	0	0	2	0	1	10	26	49	0	104	100%	
	S	88	0	0	0	0	0	0	0	0	1	0	0	88	100%	
	Visitor	36	12	13	14	16	12	11	9	12	15	10	9	27	75%	
	Reserved	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
	Allocated	38	29	31	30	30	27	27	26	27	28	32	26	12	32%	
	Accessible	9	3	2	2	2	3	4	4	4	5	5	2	7	78%	
	UC Vehicle	280	105	130	123	116	115	115	121	113	104	99	99	181	65%	
	Service Yard	12	4	2	2	1	3	2	3	3	3	4	1	11	92%	
	Loading	5	3	3	3	2	3	2	2	3	2	3	2	3	60%	
Total	573	158	182	175	168	166	162	167	173	185	203	158	415	72%		
Roosevelt College	A	196	161	143	101	69	50	45	41	53	71	85	41	155	79%	
	B	249	179	74	20	4	4	9	6	14	36	67	4	245	98%	
	S	722	2	0	0	0	3	1	4	11	23	51	0	722	100%	
	Visitor	107	72	64	52	34	23	20	28	33	47	39	20	87	81%	
	Reserved	10	1	2	2	3	3	3	4	3	4	5	1	9	90%	
	Allocated	43	40	33	28	27	26	26	26	25	28	29	25	18	42%	
	Accessible	28	26	26	25	24	25	24	25	24	25	25	24	4	14%	
	UC Vehicle	17	7	8	9	9	8	8	9	9	5	5	5	12	71%	
	Service Yard	5	4	4	4	3	3	2	2	2	3	2	2	3	60%	
	Loading	21	16	14	11	11	9	11	11	9	8	10	8	13	62%	
Total	1398	508	368	252	184	154	149	156	183	250	318	149	1249	89%		
School of Medicine	A	390	233	141	101	82	76	83	80	85	101	135	76	314	81%	
	B	626	290	139	75	44	59	66	61	84	142	277	44	582	93%	
	S	617	452	296	195	119	93	95	108	163	213	307	93	524	85%	
	Visitor	76	39	22	11	9	9	7	8	16	18	15	7	69	91%	
	Reserved	25	18	14	11	8	8	8	8	11	11	13	8	17	68%	
	Allocated	43	30	25	19	18	22	22	22	25	25	26	18	25	58%	
	Accessible	24	20	18	14	12	12	13	14	13	15	18	12	12	50%	
	UC Vehicle	8	3	2	2	2	3	4	3	2	3	3	2	6	75%	
	Service Yard	11	6	4	3	3	3	3	3	3	3	5	3	8	73%	
	Loading	5	2	1	3	1	2	3	1	2	2	2	1	4	80%	
Total	1825	1093	662	434	298	287	304	308	404	533	801	287	1538	84%		
University Center	A	110	51	19	7	3	3	2	2	5	12	22	2	108	98%	
	B	191	30	0	0	0	0	1	0	2	15	41	0	191	100%	
	S															
	Visitor	109	63	26	13	9	8	6	5	4	6	7	4	105	96%	
	Reserved	42	28	22	18	17	16	16	16	15	18	23	15	27	64%	
	Allocated	71	48	36	27	25	20	25	26	27	30	39	20	51	72%	
	Accessible	31	24	20	16	15	13	12	11	12	15	19	11	20	65%	
	UC Vehicle	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
	Service Yard	16	8	6	5	6	7	5	6	4	5	8	4	12	75%	
	Loading	10	7	2	2	1	3	3	1	2	3	4	1	9	90%	
Total	581	260	132	89	77	71	71	68	72	105	164	68	513	88%		
East Campus Academic	A															
	B	136	126	122	121	118	116	117	117	118	120	124	116	20	15%	
	S	2613	2236	1750	1399	1075	938	875	899	1018	1196	1507	875	1738	67%	
	Visitor															
	Reserved															
	Allocated															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
Total	2749	2362	1872	1520	1193	1054	992	1016	1136	1316	1631	992	1757	64%		

Neighborhood	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty	Occupied	%	
			am	am	am	am	pm	pm	pm	pm	pm	pm	Spaces	Spaces	Occupied	
Health Sciences	A	111	53	34	28	25	30	31	33	34	37	44	25	86	77%	
	B	492	172	99	78	71	76	75	80	92	138	220	71	421	86%	
	S	109	96	80	67	67	72	71	69	68	70	77	67	42	39%	
	Visitor Reserved															
	Allocated	272	171	100	47	35	88	70	59	54	92	140	35	237	87%	
	Accessible	42	26	17	10	7	12	10	9	13	17	22	7	35	83%	
	UC Vehicle															
	Service Yard	12	8	5	4	4	5	4	5	6	8	10	4	8	67%	
	Loading	3	3	3	2	3	2	3	3	3	3	3	2	1	33%	
Total		1041	529	338	236	212	285	264	258	270	365	516	212	829	80%	
Medical Center Hillcrest	A	232	113	84	59	42	41	46	41	43	47	69	41	191	82%	
	B	1167	336	221	120	91	103	128	148	186	301	467	91	1076	92%	
	S															
	Visitor Reserved	9	3	2	1	0	1	1	0	1	1	3	0	9	100%	
	Allocated	128	90	83	62	52	50	55	47	49	52	65	47	81	63%	
	Accessible	443	253	180	76	52	84	83	61	63	88	127	52	391	88%	
	UC Vehicle	46	17	10	7	8	7	10	8	8	15	19	7	39	85%	
	Service Yard	11	5	5	5	7	6	6	7	6	6	5	5	6	55%	
	Loading	16	4	2	2	4	2	2	2	3	5	8	2	14	88%	
Total		2056	823	587	333	256	294	331	314	360	515	763	256	1800	88%	

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
By Lot

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P001	A														
	B														
	S														
	Visitor: Meter														
	Reserved	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: SIO	15	4	1	0	0	1	0	1	1	1	2	0	15	100%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total	15	4	1	0	0	1	0	1	1	1	2	0	15	100%
	Accessible	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
UC Vehicle	3	1	1	2	2	1	0	1	1	1	1	0	3	100%	
Service Yard	2	1	1	1	1	1	1	2	2	2	2	1	1	50%	
Loading	3	1	1	1	1	1	1	1	1	1	1	1	2	67%	
Total	25	7	4	4	4	4	2	5	5	5	6	2	23	92%	
P002	A														
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated: SIO	46	44	42	38	28	22	24	25	27	26	29	22	24	52%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total	46	44	42	38	28	22	24	25	27	26	29	22	24	52%
	Accessible														
UC Vehicle															
Service Yard															
Loading															
Total	46	44	42	38	28	22	24	25	27	26	29	22	24	52%	
P003	A														
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated: SIO	72	53	22	8	0	3	10	6	5	10	15	0	72	100%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total	72	53	22	8	0	3	10	6	5	10	15	0	72	100%
	Accessible	4	3	3	3	2	2	2	2	2	2	3	2	2	50%
UC Vehicle															
Service Yard	1	1	0	1	0	0	1	0	1	1	1	0	1	100%	
Loading	1	1	1	1	1	1	0	1	1	1	1	0	1	100%	
Total	78	58	26	13	3	6	13	9	9	14	20	3	75	96%	
P005	A														
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
UC Vehicle															
Service Yard															
Loading	2	2	2	1	1	0	0	1	2	1	1	0	2	100%	
Total	2	2	2	1	1	0	0	1	2	1	1	0	2	100%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P006	A															
	B															
	S															
	Visitor: Meter Reserved	14	7	1	0	0	0	0	0	0	1	1	5	0	14	100%
Allocated: SIO																
Allocated:																
Allocated:																
Allocated: Total	14	7	1	0	0	0	0	0	0	1	1	5	0	14	100%	
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total	14	7	1	0	0	0	0	0	0	0	1	1	5	0	14	100%
P007	A															
	B															
	S															
	Visitor: Meter Reserved	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: LG	32	14	9	4	0	0	1	2	2	2	6	0	32	100%	
	Allocated: SIO															
	Allocated:															
	Allocated:															
	Allocated: Total	33	14	9	4	0	0	1	2	2	2	6	0	33	100%	
Accessible																
UC Vehicle	8	3	3	2	2	2	2	1	1	1	1	1	7	88%		
Service Yard	2	1	1	1	1	1	1	1	1	1	1	1	1	50%		
Loading	1	1	1	1	1	1	0	0	0	0	0	0	1	100%		
Total	44	19	14	8	4	4	4	4	4	4	4	8	4	40	91%	
P008	A															
	B															
	S															
	Visitor: Meter Reserved															
	Allocated: SIO	27	19	8	0	0	0	1	1	1	2	4	0	27	100%	
	Allocated:															
	Allocated:															
Allocated: Total	27	19	8	0	0	0	1	1	1	2	4	0	27	100%		
Accessible	2	2	2	1	1	1	1	1	1	1	1	1	1	50%		
UC Vehicle																
Service Yard																
Loading	1	1	1	0	0	0	0	0	0	1	1	0	1	100%		
Total	30	22	11	1	1	1	2	2	2	4	6	1	29	97%		
P010	A															
	B															
	S															
	Visitor: Meter Reserved															
	Allocated: SIO	22	8	2	0	0	0	2	1	2	3	6	0	22	100%	
Allocated:																
Allocated:																
Allocated: Total	22	8	2	0	0	0	2	1	2	3	6	0	22	100%		
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total	22	8	2	0	0	0	2	1	2	3	6	0	22	100%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P011	A	24	16	7	1	1	2	1	1	1	2	5	1	23	96%
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
UC Vehicle															
Service Yard															
Loading	1	1	1	1	0	0	0	0	0	1	1	0	1	100%	
Total		27	19	10	4	3	4	3	3	3	5	8	3	24	89%
P012	A	40	31	23	16	6	5	7	6	8	10	14	5	35	88%
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
UC Vehicle															
Service Yard															
Loading															
Total		42	33	25	18	8	7	9	8	10	12	16	7	35	83%
P013	A	38	16	5	1	0	3	5	4	2	5	10	0	38	100%
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		38	16	5	1	0	3	5	4	2	5	10	0	38	100%
P014	A	99	78	54	33	23	23	28	22	22	25	33	22	77	78%
	B		4	4	3	3	3	2	3	3	3	4			
	S		4	4	3	3	3	2	3	3	3	4			
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible	4	4	4	4	4	4	4	4	4	4	4	4	0	0%	
UC Vehicle															
Service Yard															
Loading															
Total		107	86	62	40	30	30	34	29	29	32	41	29	78	73%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P016	A	2	1	1	1	0	1	0	0	0	0	0	0	0	2	100%
	B	49	39	28	21	13	8	8	6	9	9	14	6	43	88%	
	S	1	1	1	1	0	0	0	0	1	1	1	0	1	100%	
	Visitor: Meter	2	1	1	1	0	0	1	1	1	1	1	0	2	100%	
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	2	2	2	2	2	2	2	2	2	2	2	2	2	0	0%
UC Vehicle	1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
Service Yard																
Loading																
Total		57	45	34	27	16	12	12	10	14	14	19	10	47	82%	
P017	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated: BA	240	209	191	162	123	115	125	140	157	169	188	115	125	52%	
	Allocated: BAB	12	12	12	10	8	7	7	9	11	12	12	7	5	42%	
	Allocated:															
	Allocated:															
	Allocated: Total	252	221	203	172	131	122	132	149	168	181	200	122	130	52%	
Accessible	9	6	6	5	6	5	5	5	6	6	6	5	4	44%		
UC Vehicle																
Service Yard																
Loading																
Total		261	227	209	177	137	127	137	154	174	187	206	127	134	51%	
P018	A															
	B	3	2	2	1	1	2	2	2	2	2	1	1	2	67%	
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
UC Vehicle	2	1	1	1	1	1	1	1	0	1	1	0	2	100%		
Service Yard																
Loading																
Total		7	4	4	3	3	4	4	4	3	4	3	3	4	57%	
P101	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total	8	5	3	2	3	3	3	2	4	5	5	2	6	75%	
	Accessible															
UC Vehicle																
Service Yard																
Loading																
Total		8	5	3	2	3	3	3	2	4	5	2	6	75%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P102	A	163	156	133	79	23	5	9	13	16	21	32	5	158	97%	
	B	243	0	0	0	0	0	0	0	0	1	6	0	243	100%	
	S	14	10	6	2	1	1	1	2	1	1	3	1	13	93%	
	Visitor: Meter Reserved	7	7	6	5	4	4	3	3	4	4	6	3	4	57%	
	Allocated: RIB	13	12	10	8	8	7	5	5	3	5	7	3	10	77%	
	Allocated: SCP															
	Allocated:															
	Allocated:															
	Allocated: Total	20	19	16	13	12	11	8	8	7	9	13	7	13	65%	
	Accessible	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
UC Vehicle Service Yard Loading																
Total	442	187	157	96	38	19	20	25	26	34	56	19	423	96%		
P103	A	178	86	28	0	0	2	3	3	4	18	39	0	178	100%	
	B															
	S															
	Visitor: Meter Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total	2	2	1	1	1	1	1	1	1	1	1	1	1	50%	
	Accessible															
	UC Vehicle Service Yard Loading															
Total	180	88	29	1	1	3	4	4	5	19	40	1	179	99%		
P104	A	232	194	138	90	69	50	48	53	51	56	57	48	184	79%	
	B															
	S															
	Visitor: Meter Reserved	22	14	10	2	2	1	1	1	1	1	1	1	21	95%	
	Allocated: RIB	4	2	1	1	1	1	0	0	0	1	1	0	4	100%	
	Allocated: SCP															
	Allocated:															
	Allocated:															
	Allocated: Total	10	7	6	5	3	3	2	3	3	4	4	2	8	80%	
	Accessible															
UC Vehicle Service Yard Loading	3	2	2	1	0	1	1	0	1	1	1	0	3	100%		
Total	271	219	157	99	75	56	52	57	56	63	64	52	219	81%		
P105	A															
	B															
	S															
	Visitor: Meter Reserved	15	8	4	2	1	2	1	1	1	1	1	1	14	93%	
	Allocated: LJP															
	Allocated:															
	Allocated:															
	Allocated: Total	15	8	4	2	1	2	1	1	1	1	1	1	14	93%	
	Accessible															
	UC Vehicle Service Yard Loading															
Total	15	8	4	2	1	2	1	1	1	1	1	1	14	93%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P106	A															
	B															
	S	4	0	0	0	0	0	0	0	0	1	1	0	4	100%	
	Visitor: Meter	4	3	1	1	1	1	1	0	0	1	1	0	4	100%	
	Reserved															
	Allocated:															
	Allocated:															
	Allocated: Total															
Accessible	1	0	0	0	0	0	0	0	0	1	1	0	1	100%		
UC Vehicle																
Service Yard	2	2	2	1	1	1	1	1	1	1	1	1	1	50%		
Loading	1	1	1	0	1	1	1	0	0	0	0	0	1	100%		
Total	12	6	4	2	3	3	3	1	1	4	4	1	11	92%		
P107	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated: Total															
Accessible																
UC Vehicle																
Service Yard	2	1	0	0	0	0	0	0	0	0	1	0	2	100%		
Loading	1	0	0	0	0	0	0	0	0	0	1	0	1	100%		
Total	3	1	0	0	0	0	0	0	0	0	2	0	3	100%		
P108	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated: TC	4	2	2	1	1	1	2	1	0	1	1	0	4	100%	
	Allocated:															
	Allocated: Total	4	2	2	1	1	1	2	1	0	1	1	0	4	100%	
Accessible	1	1	1	1	1	0	0	0	0	0	1	0	1	100%		
UC Vehicle	6	1	2	1	0	1	1	1	2	2	2	0	6	100%		
Service Yard	7	3	2	1	0	1	1	1	1	1	1	0	7	100%		
Loading																
Total	18	7	7	4	2	3	4	3	3	4	5	2	16	89%		
P110	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated: Total															
Accessible																
UC Vehicle																
Service Yard	4	1	1	1	1	0	0	1	1	2	2	0	4	100%		
Loading	1	1	1	1	0	0	0	0	0	0	0	0	1	100%		
Total	5	2	2	2	1	0	0	1	1	2	2	0	5	100%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P111	A	5	1	2	1	0	0	0	0	0	1	0	0	5	100%	
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total	5	1	2	1	0	0	0	0	0	1	0	0	5	100%	
P112	A	8	2	2	2	1	1	2	1	1	2	3	1	7	88%	
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total	8	2	2	2	1	1	2	1	1	2	3	1	7	88%	
P113	A	26	19	11	0	0	0	0	0	2	1	1	0	26	100%	
	B															
	S															
	Visitor: Meter															
	Reserved	1	1	1	1	0	0	0	0	0	0	0	0	1	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	3	3	2	0	0	0	1	0	1	1	0	0	3	100%	
	UC Vehicle															
	Service Yard	2	2	1	1	0	0	0	1	1	1	1	0	2	100%	
	Loading	3	2	1	0	0	0	0	0	0	0	0	0	3	100%	
	Total	35	27	16	2	0	0	1	1	4	3	2	0	35	100%	
P114	A	3	3	3	2	1	1	1	1	1	1	1	1	2	67%	
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated: CC															
	Allocated:															
	Allocated:															
	Allocated: Total	3	3	3	2	1	1	1	1	1	1	1	1	2	67%	
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading	1	1	1	1	1	0	1	0	0	0	0	0	1	100%	
	Total	4	4	4	3	2	1	2	1	1	1	1	1	3	75%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak					
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied			
P115	A	2																
	B		0	0	0	0	0	0	0	1	1	1	0	2	100%			
	S																	
	Visitor: Meter Reserved																	
	Allocated:																	
Allocated:																		
Allocated:																		
Allocated: Total																		
Accessible	4		1	1	1	1	2	1	1	1	1	1	1	3	75%			
UC Vehicle	10		1	1	1	1	1	0	0	2	3	3	0	10	100%			
Service Yard																		
Loading																		
Total		16	2	2	2	2	3	1	1	4	5	5	1	15	94%			
P116	A																	
	B																	
	S																	
	Visitor: Meter Reserved																	
	Allocated:																	
Allocated:																		
Allocated:																		
Allocated: Total																		
Accessible	3		1	1	1	1	1	2	1	1	1	2	1	2	67%			
UC Vehicle	3		1	1	1	1	1	1	0	1	2	2	0	3	100%			
Service Yard																		
Loading																		
Total		6	2	2	2	2	2	3	1	2	3	4	1	5	83%			
P201	A	10																
	B		7	5	1	1	1	1	1	1	0	0	0	10	100%			
	S		2	1	1	1	1	1	2	1	2	2	1	1	50%			
	Visitor: Meter Reserved																	
	Allocated:																	
	Allocated:																	
	Allocated:																	
	Allocated: Total																	
	Accessible		3	1	1	0	0	1	0	1	2	2	2	0	3	100%		
	UC Vehicle		1	0	0	0	0	0	1	0	0	0	0	0	1	100%		
Service Yard	3	2	1	2	1	1	2	2	1	1	1	1	2	67%				
Loading	4	1	1	1	0	0	1	1	1	0	0	0	4	100%				
Total		23	12	9	5	3	4	6	7	6	5	5	3	20	87%			
P202	A	5																
	B		2	0	0	0	0	0	0	0	1	0	0	5	100%			
	S		3	2	1	1	1	1	1	1	1	1	1	1	2	67%		
	Visitor: Meter Reserved																	
	Allocated:																	
	Allocated:																	
	Allocated:																	
	Allocated: Total																	
	Accessible		2	1	1	1	1	0	0	1	1	1	1	0	2	100%		
	UC Vehicle		5	2	1	0	1	1	1	1	1	1	0	0	5	100%		
Service Yard																		
Loading	6	4	2	1	1	1	1	1	1	0	0	0	6	100%				
Total		21	11	5	3	4	3	3	4	4	4	2	2	19	90%			

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P203	A														
	B														
	S														
	Visitor: Meter Reserved	3	1	1	2	1	1	1	1	1	1	1	1	2	67%
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard	2	1	1	1	1	2	1	1	1	2	2	1	1	50%	
Loading															
Total		5	2	2	3	2	3	2	2	2	3	3	2	3	60%
P204	A														
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard	2	1	0	1	1	1	0	1	1	1	2	0	2	100%	
Loading															
Total		2	1	0	1	1	1	0	1	1	1	2	0	2	100%
P205	A														
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard	4	2	2	2	1	2	2	2	3	3	3	1	3	75%	
Loading															
Total		4	2	2	2	1	2	2	2	3	3	3	1	3	75%
P206	A														
	B														
	S														
	Visitor: Meter Reserved	81	20	4	0	0	0	1	0	3	3	2	0	81	100%
	Allocated: FC	2	1	1	1	1	1	1	1	1	1	1	1	1	50%
	Allocated:	50	44	39	35	33	22	16	29	33	33	34	16	34	68%
	Allocated:														
	Allocated:														
	Allocated: Total	50	44	39	35	33	22	16	29	33	33	34	16	34	68%
Accessible	10	6	3	2	1	1	1	2	3	4	5	1	9	90%	
UC Vehicle															
Service Yard															
Loading	3	1	1	1	1	0	1	1	1	1	1	0	3	100%	
Total		146	72	48	39	36	24	20	33	41	42	43	20	126	86%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P207	A	276	212	151	78	38	17	13	14	27	47	54	13	263	95%	
	B	245	98	35	1	0	1	2	2	9	31	57	0	245	100%	
	S															
	Visitor: Meter															
	Reserved	4	4	3	2	2	2	3	3	3	3	3	2	2	50%	
	Allocated: ACP	2	2	1	1	1	1	1	1	1	1	1	1	1	1	50%
	Allocated: BCP	7	6	4	2	1	1	1	1	1	2	3	1	6	86%	
	Allocated:															
	Allocated:															
	Allocated: Total	9	8	5	3	2	2	2	2	2	3	4	2	7	78%	
Accessible	3	3	2	2	1	0	1	1	1	1	2	0	3	100%		
UC Vehicle																
Service Yard																
Loading																
Total		537	325	196	86	43	22	21	22	42	85	120	21	516	96%	
P208	A	37	27	16	3	0	0	0	1	5	8	9	0	37	100%	
	B	477	0	0	0	0	0	0	0	5	5	21	0	477	100%	
	S															
	Visitor: Meter															
	Reserved															
	Allocated: MIB	2	2	1	1	1	1	1	1	2	2	2	1	1	50%	
	Allocated: SCP	23	12	5	2	0	0	1	2	2	3	5	0	23	100%	
	Allocated:															
	Allocated:															
	Allocated: Total	25	14	6	3	1	1	2	3	4	5	7	1	24	96%	
Accessible	4	2	2	1	1	1	1	1	2	3	3	1	3	75%		
UC Vehicle																
Service Yard																
Loading																
Total		543	43	24	7	2	2	3	5	16	21	40	2	541	100%	
P301	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	2	0	0	0	0	1	0	0	0	1	1	0	2	100%	
UC Vehicle	2	0	0	0	0	0	0	0	1	1	1	0	2	100%		
Service Yard																
Loading																
Total		4	0	0	0	0	1	0	0	1	2	2	0	4	100%	
P302	A	34	29	18	6	2	2	2	3	6	11	13	2	32	94%	
	B	74	61	38	8	1	0	0	1	2	6	14	0	74	100%	
	S															
	Visitor: Meter	4	3	1	1	1	1	1	0	0	0	0	0	4	100%	
	Reserved	1	1	1	1	1	1	0	0	0	0	0	0	1	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total	5	4	4	4	2	2	2	2	2	4	5	2	3	60%	
	Accessible															
UC Vehicle																
Service Yard																
Loading																
Total		118	98	62	20	7	6	5	6	10	21	32	5	113	96%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty Spaces	Occupied Spaces	% Occupied	
			am	am	am	am	pm	pm	pm	pm	pm	pm				
P303	A	34	25	16	3	1	4	2	1	3	11	17	1	33	97%	
	B	67	48	25	7	0	1	5	1	4	12	20	0	67	100%	
	S															
	Visitor: Meter	17	16	5	2	1	1	1	0	1	3	5	0	17	100%	
	Reserved	1	1	0	0	0	1	1	1	0	0	0	0	1	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	3	3	2	0	0	0	0	0	1	2	2	0	3	100%	
UC Vehicle																
Service Yard	2	1	1	1	2	1	1	1	1	1	1	1	1	50%		
Loading	2	2	1	0	0	0	0	0	1	1	0	0	2	100%		
Total	126	96	50	13	4	8	10	4	11	30	45	4	122	97%		
P304	A		18	7	3	2	1	2	2	3	7	10	1	31	97%	
	B	32	0	0	0	0	0	0	0	1	0	0	0	32	100%	
	S	32	0	0	0	0	0	0	0	1	0	0	0	32	100%	
	Visitor: Meter	6	2	2	1	0	0	1	1	1	3	2	0	6	100%	
	Reserved	4	2	2	2	3	2	2	2	3	3	3	2	2	50%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	2	2	2	1	1	1	1	1	1	1	1	1	1	50%	
UC Vehicle																
Service Yard	2	1	1	1	1	1	1	1	1	1	0	0	2	100%		
Loading	2	1	1	0	0	0	0	0	1	1	1	0	2	100%		
Total	80	26	15	8	7	5	7	7	7	11	16	17	5	75	94%	
P306	A															
	B															
	S															
	Visitor: Meter	2	1	1	0	0	0	0	1	0	0	0	0	2	100%	
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	1	1	1	1	0	1	1	1	0	0	0	0	1	100%	
UC Vehicle																
Service Yard																
Loading																
Total	3	2	2	1	0	1	1	2	0	0	0	0	0	3	100%	
P308	A	28	19	11	5	1	2	2	1	3	4	6	1	27	96%	
	B	48	8	0	0	0	1	1	0	1	2	7	0	48	100%	
	S	23	0	0	0	0	0	0	0	0	0	0	0	23	100%	
	Visitor: Meter	8	5	2	2	1	1	0	1	1	0	0	0	8	100%	
	Reserved	2	2	1	1	0	2	1	1	1	1	0	0	2	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
UC Vehicle																
Service Yard	3	3	2	2	2	2	2	2	2	3	3	2	1	33%		
Loading	2	1	1	1	0	1	1	0	0	0	0	0	2	100%		
Total	114	38	17	11	4	9	7	5	8	10	16	4	110	96%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P309	A	72	0	0	0	0	1	0	0	2	7	9	0	72	100%
	B														
	S														
	Visitor: Meter	13	8	4	0	0	0	2	1	1	0	0	0	13	100%
	Reserved	2	1	1	1	1	1	1	1	1	1	1	1	1	50%
	Allocated:														
	Allocated: Total														
Accessible	2	2	2	1	1	1	1	1	1	2	1	1	1	50%	
UC Vehicle															
Service Yard															
Loading															
Total		89	11	7	2	2	3	4	3	5	10	11	2	87	98%
P310	A														
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated: Total														
Accessible	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
UC Vehicle															
Service Yard															
Loading	2	0	0	1	0	0	0	0	0	0	0	0	2	100%	
Total		3	0	0	1	0	0	0	0	0	0	0	0	3	100%
P351	A														
	B	36	33	26	15	8	5	5	6	6	8	10	5	31	86%
	S	118	60	33	10	1	1	0	4	5	6	9	0	118	100%
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated: Total														
Accessible	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
UC Vehicle															
Service Yard															
Loading															
Total		156	95	61	27	11	8	7	12	13	16	21	7	149	96%
P352	A														
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated: Total														
Accessible	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
UC Vehicle															
Service Yard	2	1	1	2	1	1	2	1	1	1	1	1	1	50%	
Loading	1	0	1	1	1	1	1	1	1	1	1	0	1	100%	
Total		4	2	3	4	3	3	4	3	3	3	3	2	2	50%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P354	A															
	B															
	S															
	Visitor: Meter	22	16	11	4	5	4	5	5	6	6	3	3	19	86%	
	Reserved	4	2	3	2	2	1	1	1	2	2	2	1	3	75%	
	Allocated: SDSC	87	35	3	0	0	2	1	1	3	6	7	0	87	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total	87	35	3	0	0	2	1	1	3	6	7	0	87	100%	
	Accessible	6	5	3	2	1	1	1	1	2	2	1	1	5	83%	
UC Vehicle	3	2	2	2	2	1	1	2	2	2	2	1	2	67%		
Service Yard	2	2	1	1	0	0	0	1	1	1	1	0	2	100%		
Loading	3	2	1	1	1	1	2	1	1	0	0	0	3	100%		
Total	127	64	24	12	11	10	11	12	17	19	16	10	117	92%		
P355	A															
	B															
	S	412	405	392	372	344	325	313	317	336	353	372	313	99	24%	
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
UC Vehicle																
Service Yard																
Loading																
Total	412	405	392	372	344	325	313	317	336	353	372	313	99	24%		
P356	A															
	B															
	S	369	296	220	163	107	81	85	100	135	166	211	81	288	78%	
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
UC Vehicle																
Service Yard																
Loading																
Total	369	296	220	163	107	81	85	100	135	166	211	81	288	78%		
P357	A															
	B	144	123	107	81	67	58	56	54	57	57	67	54	90	63%	
	S	405	339	280	219	159	128	119	129	154	177	223	119	286	71%	
	Visitor: Meter	21	18	17	17	15	15	13	13	13	14	13	13	8	38%	
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total	5	5	5	5	5	5	5	5	4	5	5	4	1	20%	
	Accessible															
UC Vehicle																
Service Yard																
Loading																
Total	575	485	409	322	246	206	193	201	228	253	308	193	382	66%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P358	A														
	B														
	S														
	Visitor: Meter Reserved	9	9	9	9	8	8	8	9	8	8	9	8	1	11%
	Allocated: NIC														
Allocated:															
Allocated:															
Allocated: Total	9	9	9	9	8	8	8	9	8	8	9	8	1	11%	
Accessible	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
UC Vehicle															
Service Yard															
Loading															
Total		10	10	10	10	9	9	9	10	9	9	10	9	1	10%
P359	A														
	B														
	S	52	37	36	33	33	30	28	22	10	13	18	10	42	81%
	Visitor: Meter Reserved	6	5	5	4	4	3	4	5	4	3	3	3	3	50%
	Allocated:														
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		58	42	41	37	37	33	32	27	14	16	21	14	44	76%
P371	A														
	B														
	S	126	107	87	39	13	7	6	15	29	41	53	6	120	95%
	Visitor: Meter Reserved														
	Allocated:														
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		126	107	87	39	13	7	6	15	29	41	53	6	120	95%
P372	A														
	B														
	S	185	99	45	19	8	5	6	15	28	42	54	5	180	97%
	Visitor: Meter Reserved														
	Allocated:														
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		185	99	45	19	8	5	6	15	28	42	54	5	180	97%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P373	A	189	21	5	0	0	0	1	2	8	12	19	0	189	100%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	189	21	5	0	0	0	1	2	8	12	19	0	189	100%
P374	A	188	169	157	136	107	102	98	97	98	106	120	97	91	48%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	188	169	157	136	107	102	98	97	98	106	120	97	91	48%
P375	A	160	143	134	122	115	108	107	106	106	108	119	106	54	34%
	B														
	S														
	Visitor: Meter														
	Reserved	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible	7	7	7	7	7	6	6	6	6	6	6	6	1	14%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	168	151	142	130	123	115	114	113	113	115	126	113	55	33%
P376	A	53	0	0	0	0	0	0	0	1	0	2	0	53	100%
	B														
	S														
	Visitor: Meter	52	50	49	47	44	45	43	45	46	47	48	43	9	17%
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible	10	10	10	10	10	10	10	10	10	10	10	10	0	0%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	115	60	59	57	54	55	53	55	57	57	60	53	62	54%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P381	A	117	58	36	31	27	36	37	34	32	42	66	27	90	77%	
	B		2	1	1	1	2	3	1	1	1	2	1	4	80%	
	S		1	0	1	1	0	0	0	0	0	0	0	0	1	100%
	Visitor: Meter		1	1	1	1	1	1	1	1	0	0	0	0	1	100%
	Reserved		1	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: ACT		2	2	2	2	1	2	1	1	2	2	2	1	1	50%
	Allocated: BE		5	3	4	4	2	3	2	2	2	2	2	2	3	60%
	Allocated: ERV		6	3	2	2	1	2	2	2	2	3	4	1	5	83%
	Allocated: PM		1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated: Total		134	67	44	39	32	44	45	40	38	49	75	32	102	76%
	Accessible															
UC Vehicle																
Service Yard																
Loading																
Total																
P382	A	282	145	75	55	53	73	83	67	80	98	144	53	229	81%	
	B		23	20	14	10	9	10	12	8	11	13	16	8	15	65%
	S		1	1	1	0	0	0	1	0	0	0	0	0	1	100%
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total		4	3	1	1	1	1	2	2	2	2	3	1	3	75%
	Accessible															
	UC Vehicle															
Service Yard																
Loading																
Total		310	169	91	66	63	84	98	77	93	113	163	63	247	80%	
P383	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total		1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Accessible		11	7	6	7	6	5	8	5	5	7	7	5	6	55%
	UC Vehicle		3	2	1	1	1	1	2	2	1	2	2	1	2	67%
Service Yard	4	4	3	2	3	3	3	3	2	3	3	2	2	50%		
Loading																
Total		19	14	11	11	11	10	14	11	9	13	13	9	10	53%	
P391	A	31	9	2	2	2	5	5	3	5	10	17	2	29	94%	
	B		4	4	3	2	2	3	2	2	3	3	2	2	50%	
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total		2	2	2	2	1	1	2	1	2	1	2	1	1	50%
	Accessible		1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	UC Vehicle		3	3	2	3	3	3	3	3	3	3	3	2	1	33%
Service Yard																
Loading																
Total		41	19	10	10	9	13	13	10	14	18	26	9	32	78%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P392	A	84	52	23	11	8	13	19	11	16	26	41	8	76	90%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	84	52	23	11	8	13	19	11	16	26	41	8	76	90%
P393	A	44	42	36	33	33	33	35	33	33	34	35	33	11	25%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	44	42	36	33	33	33	35	33	33	34	35	33	11	25%
P394	A	15	13	10	9	7	8	8	7	9	8	11	7	8	53%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	15	13	10	9	7	8	8	7	9	8	11	7	8	53%
P401	A	93	0	0	0	0	2	0	1	1	1	0	0	93	100%
	B														
	S														
	Visitor: Meter	2	1	1	1	1	1	1	1	1	1	0	0	2	100%
	Reserved	2	0	1	1	1	1	1	1	1	1	1	0	2	100%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	UC Vehicle														
	Service Yard														
	Loading	2	1	1	1	1	1	1	1	1	1	1	1	1	50%
	Total	100	3	4	4	4	6	4	5	5	5	3	3	97	97%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P402	A	2	1	1	1	0	0	1	1	1	0	0	0	2	100%	
	B															
	S															
	Visitor: Meter	3	1	1	2	1	1	1	1	0	1	0	0	3	100%	
	Reserved	6	1	1	1	2	2	2	3	2	3	4	1	5	83%	
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	3	3	3	3	3	3	3	3	3	3	3	3	0	0%		
UC Vehicle																
Service Yard																
Loading	10	8	7	7	6	4	6	6	5	5	6	4	6	60%		
Total	24	14	13	14	12	10	13	14	11	12	13	10	14	58%		
P403	A	45	35	19	7	2	2	2	1	3	4	9	1	44	98%	
	B	112	30	0	0	0	0	1	0	1	4	12	0	112	100%	
	S															
	Visitor: Meter	11	5	2	0	1	1	1	0	1	3	3	0	11	100%	
	Reserved	2	2	2	1	1	1	1	1	1	1	2	1	1	50%	
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	5	5	4	4	4	3	2	3	3	3	3	2	3	60%		
UC Vehicle																
Service Yard																
Loading																
Total	175	77	27	12	8	7	7	5	9	15	29	5	170	97%		
P404	A															
	B	2	1	0	0	0	0	0	0	0	0	0	0	2	100%	
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible																
UC Vehicle																
Service Yard	2	1	1	1	1	1	0	0	0	1	0	0	2	100%		
Loading	4	4	3	2	2	2	2	2	2	1	1	1	3	75%		
Total	8	6	4	3	3	3	2	2	2	2	1	1	7	88%		
P405	A	22	1	0	0	0	0	0	0	0	2	1	0	22	100%	
	B															
	S															
	Visitor: Meter															
	Reserved	9	7	7	6	5	5	5	5	4	4	4	4	5	56%	
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	1	0	0	0	1	1	1	0	0	0	1	0	1	100%		
UC Vehicle																
Service Yard																
Loading																
Total	32	8	7	6	6	6	6	5	4	6	6	4	28	88%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak																
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied														
P406	A	322	0	0	0	0	1	1	3	5	8	18	0	322	100%														
	B																												
	S																												
	Visitor: Meter																												
	Reserved															2	0	0	0	0	0	0	0	0	0	0	0	2	100%
	Allocated: SCP															11	9	7	4	2	1	2	2	3	4	6	1	10	91%
	Allocated:																												
	Allocated:																												
	Allocated:																												
	Allocated: Total															11	9	7	4	2	1	2	2	3	4	6	1	10	91%
Accessible	4	3	3	3	3	4	3	3	3	3	3	3	1	25%															
UC Vehicle																													
Service Yard																													
Loading	2	1	1	0	1	0	1	1	0	0	1	0	2	100%															
Total	341	13	11	7	6	6	7	9	11	15	28	6	335	98%															
P407	A	5	4	1	1	3	3	2	2	1	2	4	1	4	80%														
	B																												
	S																												
	Visitor: Meter																												
	Reserved																												
	Allocated:																												
	Allocated:																												
	Allocated:																												
	Allocated:																												
	Allocated: Total															2	2	2	2	2	2	2	2	2	2	2	2	0	0%
Accessible	5	3	3	3	4	4	3	2	1	1	2	1	4	80%															
UC Vehicle	1	0	1	1	1	1	1	1	1	1	1	0	1	100%															
Service Yard																													
Loading																													
Total	13	9	7	7	10	10	8	7	5	6	9	5	8	62%															
P408	A	13	0	0	0	0	0	0	0	1	3	3	0	13	100%														
	B																												
	S																												
	Visitor: Meter																												
	Reserved															3	3	2	1	1	1	1	1	1	2	2	1	2	67%
	Allocated: ACP															1	1	1	1	1	0	1	1	1	1	1	0	1	100%
	Allocated: BCP															7	0	0	0	0	0	0	0	0	1	2	0	7	100%
	Allocated: RA															2	1	1	1	0	0	1	1	1	2	2	0	2	100%
	Allocated:																												
	Allocated:																												
Allocated: Total	10	2	2	2	1	0	2	2	2	4	5	0	10	100%															
Accessible	1	0	0	0	0	1	0	0	0	0	1	0	1	100%															
UC Vehicle	1	0	0	0	0	1	1	0	0	1	1	0	1	100%															
Service Yard																													
Loading																													
Total	28	5	4	3	2	3	4	3	4	10	12	2	26	93%															
P410	A	34	15	0	0	0	0	0	0	1	2	5	7	0	34	100%													
	B																												
	S																												
	Visitor: Meter																												
	Reserved																												
	Allocated:																												
	Allocated:																												
	Allocated:																												
	Allocated:																												
	Allocated: Total																66	0	0	0	0	0	0	0	0	8	26	0	66
Accessible																													
UC Vehicle																													
Service Yard																													
Loading																													
Total	100	15	0	0	0	0	0	0	0	1	2	13	33	0	100	100%													

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
P411	A																
	B																
	S																
	Visitor: Meter Reserved	88	51	22	11	5	4	3	3	2	1	0	0	88	100%		
	Allocated: BS	1	1	1	0	0	0	1	1	1	1	1	0	1	100%		
	Allocated: EV	1	1	1	1	1	1	1	1	1	1	1	1	0	0%		
	Allocated: IMP	3	1	1	1	1	0	1	1	1	1	1	0	3	100%		
	Allocated:																
	Allocated: Total	5	3	3	2	2	1	3	3	3	3	3	1	4	80%		
	Accessible	6	4	3	1	1	1	1	1	2	3	3	1	5	83%		
UC Vehicle																	
Service Yard	4	2	1	0	0	0	0	1	1	2	2	0	4	100%			
Loading	1	1	0	0	0	0	0	0	0	0	0	0	1	100%			
Total	104	61	29	14	8	6	7	8	8	9	8	6	98	94%			
P412	A	9	0	0	0	1	1	0	0	0	1	5	0	9	100%		
	B																
	S																
	Visitor: Meter Reserved	24	15	10	9	9	8	8	8	8	10	14	8	16	67%		
	Allocated: IC	3	2	2	2	1	1	1	1	2	2	2	1	2	67%		
	Allocated:																
	Allocated:																
	Allocated: Total	3	2	2	2	1	1	1	1	2	2	2	1	2	67%		
	Accessible	5	3	2	2	1	1	1	1	1	2	2	1	4	80%		
	UC Vehicle																
Service Yard																	
Loading																	
Total	41	20	14	13	12	11	10	10	11	15	23	10	31	76%			
P413	A																
	B																
	S																
	Visitor: Meter Reserved	1	1	1	1	1	1	1	1	0	0	1	0	1	100%		
	Allocated: OSD																
	Allocated:																
	Allocated:																
	Allocated: Total	1	1	1	1	1	1	1	1	0	0	1	0	1	100%		
	Accessible	2	2	1	1	1	1	1	1	1	1	1	1	1	50%		
	UC Vehicle																
Service Yard																	
Loading																	
Total	3	3	2	2	2	2	2	2	2	1	1	2	1	2	67%		
P414	A	1	0	0	0	0	0	0	0	0	0	0	0	1	100%		
	B																
	S																
	Visitor: Meter Reserved	5	4	4	3	2	2	1	2	1	1	2	1	4	80%		
	Allocated:																
	Allocated:																
	Allocated: Total																
	Accessible																
	UC Vehicle																
	Service Yard	3	1	1	0	0	0	0	0	1	2	1	0	3	100%		
Loading	7	3	1	0	0	0	0	0	0	1	1	0	7	100%			
Total	16	8	6	3	2	2	1	2	2	4	4	1	15	94%			

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P415	A															
	B															
	S															
	Visitor: Meter	5	3	1	1	0	0	0	0	0	0	0	0	0	5	100%
	Reserved	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: SHAS	4	3	2	1	1	1	2	1	2	2	2	3	1	3	75%
	Allocated: SHPV	7	6	4	3	4	4	2	2	2	4	4	2	2	5	71%
	Allocated:															
	Allocated:															
	Allocated: Total	11	9	6	4	5	5	4	3	4	6	7	3	8	73%	
	Accessible	1	1	1	1	1	1	1	0	1	0	1	0	1	1	100%
UC Vehicle	1	1	1	1	1	1	1	1	1	1	1	1	0	0	0%	
Service Yard	2	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
Loading																
Total	21	16	10	8	8	8	7	5	7	8	11	5	16	76%		
P416	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated: IC	19	17	10	5	2	0	2	4	5	3	8	0	19	100%	
	Allocated: RS	1	1	1	0	0	0	0	0	0	0	1	0	1	100%	
	Allocated:															
	Allocated:															
	Allocated: Total	20	18	11	5	2	0	2	4	5	3	9	0	20	100%	
	Accessible															
UC Vehicle																
Service Yard																
Loading	7	6	1	1	0	1	1	0	1	1	2	0	7	100%		
Total	27	24	12	6	2	1	3	4	6	4	11	1	26	96%		
P418	A															
	B															
	S															
	Visitor: Meter															
	Reserved	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
	Allocated: PC	2	1	0	0	1	1	1	1	0	0	0	0	2	100%	
	Allocated: POL	19	12	11	11	12	11	11	11	11	12	12	11	8	42%	
	Allocated:															
	Allocated:															
	Allocated: Total	21	13	11	11	13	12	12	12	11	12	12	11	10	48%	
	Accessible	5	4	4	3	2	1	1	1	0	2	3	0	5	100%	
UC Vehicle																
Service Yard																
Loading																
Total	28	18	16	15	16	14	14	14	12	15	16	12	16	57%		
P451	A															
	B	50	35	14	2	0	0	1	0	1	5	9	0	50	100%	
	S															
	Visitor: Meter	55	39	37	29	21	15	11	16	20	29	28	11	44	80%	
	Reserved															
	Allocated: CUS	2	2	1	1	1	1	1	1	1	1	1	1	1	50%	
	Allocated: CUV	19	18	16	14	15	14	14	14	13	13	12	12	7	37%	
	Allocated:															
	Allocated:															
	Allocated: Total	21	20	17	15	16	15	15	15	14	14	13	13	8	38%	
	Accessible	10	10	10	9	9	9	10	10	9	9	9	9	1	10%	
UC Vehicle																
Service Yard																
Loading																
Total	136	104	78	55	46	39	37	41	44	57	59	37	99	73%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P452	A	55	51	48	38	27	20	17	17	20	25	30	17	38	69%
	B														
	S														
	Visitor: Meter														
	Reserved	41	30	25	19	10	6	7	10	11	15	11	6	35	85%
	Allocated: GPO	11	11	9	9	9	10	9	9	8	10	10	8	3	27%
	Allocated:														
	Allocated:														
	Allocated: Total	11	11	9	9	9	10	9	9	8	10	10	8	3	27%
	Accessible	7	6	6	6	5	5	4	5	5	6	6	4	3	43%
UC Vehicle	17	7	8	9	9	8	8	9	9	5	5	5	12	71%	
Service Yard															
Loading															
Total		131	105	96	81	60	49	45	50	53	61	62	45	86	66%
P453	A	92	78	65	44	32	23	22	19	23	31	41	19	73	79%
	B	67	52	13	1	0	0	2	0	2	8	15	0	67	100%
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
UC Vehicle															
Service Yard															
Loading															
Total		159	130	78	45	32	23	24	19	25	39	56	19	140	88%
P454	A														
	B	130	91	47	17	4	4	6	6	11	23	43	4	126	97%
	S	28	0	0	0	0	0	0	0	0	0	2	0	28	100%
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
UC Vehicle															
Service Yard															
Loading															
Total		158	91	47	17	4	4	6	6	11	23	45	4	154	97%
P455	A														
	B														
	S	156	0	0	0	0	0	0	0	0	2	7	0	156	100%
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
UC Vehicle															
Service Yard															
Loading															
Total		156	0	0	0	0	0	0	0	0	2	7	0	156	100%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P456	A	123	2	0	0	0	0	0	0	0	5	12	24	0	123	100%
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total	123	2	0	0	0	0	0	0	0	5	12	24	0	123	100%
P501	A	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	4	3	3	2	2	2	2	2	2	2	2	3	2	2	50%
	UC Vehicle	4	1	1	1	1	1	1	2	1	1	1	1	1	3	75%
	Service Yard															
	Loading															
	Total	9	4	4	3	3	3	3	4	3	3	3	4	3	6	67%
P502	A	156	37	4	2	1	0	1	0	2	8	21	0	156	100%	
	B	185	0	0	0	0	0	0	0	0	0	2	0	185	100%	
	S	4	2	2	0	1	0	1	0	1	1	1	0	4	100%	
	Visitor: Meter	4	2	2	0	1	0	1	0	1	1	1	0	4	100%	
	Reserved	4	2	2	2	1	1	1	1	2	2	2	1	3	75%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading	6	4	4	4	2	1	1	0	1	1	0	0	6	100%	
	Total	355	45	12	8	5	2	4	1	6	12	26	1	354	100%	
P503	A	129	108	79	44	30	22	21	22	25	26	33	21	108	84%	
	B															
	S															
	Visitor: Meter	4	3	1	1	1	0	1	0	1	0	0	0	4	100%	
	Reserved	8	7	6	4	3	3	2	2	2	2	2	2	6	75%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	5	5	4	4	3	2	2	3	3	4	4	2	3	60%	
	UC Vehicle															
	Service Yard	2	2	1	1	1	1	1	1	2	2	2	1	1	50%	
	Loading															
	Total	148	125	91	54	38	28	27	28	33	34	41	27	121	82%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P504	A														
	B														
	S	35	0	0	0	0	0	0	0	0	0	0	0	35	100%
	Visitor: Meter	7	2	2	1	1	1	1	0	1	0	0	0	7	100%
	Reserved	2	1	1	1	1	1	1	1	1	1	1	1	1	50%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible UC Vehicle Service Yard	6	4	4	4	4	4	4	4	4	4	4	4	2	33%
Loading	5	3	3	3	2	2	2	1	2	2	2	1	4	80%	
Total		55	10	10	9	8	8	8	6	8	7	7	6	49	89%
P505	A														
	B														
	S														
	Visitor: Meter														
	Reserved	4	3	2	1	1	1	1	1	1	1	1	1	3	75%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible UC Vehicle Service Yard	1	1	0	0	0	0	0	0	0	0	1	0	1	100%
Loading															
Total		5	4	2	1	1	1	1	1	1	1	2	1	4	80%
P506	A	47	31	29	18	10	7	5	4	9	15	14	4	43	91%
	B														
	S														
	Visitor: Meter	6	1	0	1	1	0	0	0	1	1	0	0	6	100%
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible UC Vehicle	3	3	3	3	3	3	3	3	3	3	3	3	0	0%
Service Yard	3	3	3	3	2	2	2	2	2	2	2	2	1	33%	
Loading	3	2	2	1	1	2	1	1	1	1	1	1	2	67%	
Total		62	40	37	26	17	14	11	10	16	22	20	10	52	84%
P507	A														
	B														
	S														
	Visitor: Meter	19	6	4	3	5	6	6	5	6	4	2	2	17	89%
	Reserved	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated: ACT	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated: IMP	4	1	3	2	2	2	3	2	2	2	2	1	3	75%
	Allocated: TPSS	33	27	27	27	27	24	23	23	24	25	29	23	10	30%
	Allocated:														
	Allocated:														
	Allocated: Total	38	29	31	30	30	27	27	26	27	28	32	26	12	32%
	Accessible UC Vehicle	9	3	2	2	2	3	4	4	4	5	5	2	7	78%
	Service Yard	280	105	130	123	116	115	115	121	113	104	99	99	181	65%
Loading	12	4	2	2	1	3	2	3	3	3	4	1	11	92%	
Total		364	151	173	164	157	158	157	162	157	147	146	146	218	60%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P508	A	25	14	1	0	0	3	1	0	0	0	0	4	0	25	100%
	B															
	S															
	Visitor: Meter	3	1	0	0	0	0	0	0	0	0	0	0	0	3	100%
	Reserved	6	6	6	4	3	2	2	2	2	1	2	1	5	83%	
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	2	2	2	1	0	0	0	0	0	0	1	1	0	2	100%	
UC Vehicle																
Service Yard																
Loading																
Total		36	23	9	5	3	5	3	2	2	2	7	2	34	94%	
P509	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	5	3	3	3	3	2	3	2	2	2	2	3	2	3	60%	
UC Vehicle																
Service Yard																
Loading																
Total		5	3	3	3	3	2	3	2	2	2	3	2	3	60%	
P510	A	104	1	0	0	0	2	0	1	10	26	49	0	104	100%	
	B	88	0	0	0	0	0	0	0	0	1	0	0	88	100%	
	S	17	6	9	11	11	6	5	4	6	11	8	4	13	76%	
	Visitor: Meter															
	Reserved															
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		209	7	9	11	11	8	5	5	16	38	57	5	204	98%	
P601	A	97	14	2	1	1	0	1	0	1	5	7	0	97	100%	
	B															
	S															
	Visitor: Meter	43	21	10	4	2	2	1	1	4	5	2	1	42	98%	
	Reserved	13	11	9	8	6	6	6	5	7	7	7	5	8	62%	
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	6	5	5	3	2	2	2	3	2	2	3	2	4	67%		
UC Vehicle	2	1	1	1	1	1	1	1	1	1	1	1	1	1	50%	
Service Yard	2	1	1	0	0	0	0	0	0	0	0	0	2	100%		
Loading																
Total		163	53	28	17	12	11	11	10	15	20	20	10	153	94%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P602	A	59	30	8	2	1	4	3	3	5	9	14	1	58	98%	
	B	154	23	0	0	0	3	1	1	6	23	78	0	154	100%	
	S															
	Visitor: Meter	8	6	4	2	2	2	1	2	4	3	4	1	7	88%	
	Reserved	1	1	0	0	0	0	0	0	1	1	1	0	1	100%	
	Allocated: BCP	4	0	0	0	0	0	1	0	1	1	1	0	4	100%	
	Allocated:															
	Allocated:															
	Allocated: Total	4	0	0	0	0	0	1	0	1	1	1	0	4	100%	
	Accessible	4	3	2	2	1	1	2	2	2	2	3	1	3	75%	
	UC Vehicle	2	2	1	1	1	2	2	2	1	2	2	1	1	50%	
Service Yard Loading																
Total	232	65	15	7	5	12	10	10	20	41	103	5	227	98%		
P603	A	233	189	131	98	80	72	79	77	79	87	114	72	161	69%	
	B	259	118	42	14	7	18	22	18	30	52	105	7	252	97%	
	S															
	Visitor: Meter	23	11	8	4	5	5	5	5	8	10	9	4	19	83%	
	Reserved	4	3	3	2	2	2	1	2	2	2	3	1	3	75%	
	Allocated: EV	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
	Allocated: MG	27	21	17	13	14	18	16	17	18	18	19	13	14	52%	
	Allocated:															
	Allocated:															
	Allocated: Total	28	22	18	14	15	19	17	18	19	19	20	14	14	50%	
	Accessible	11	9	9	7	7	7	8	8	8	9	10	7	4	36%	
UC Vehicle																
Service Yard Loading	5	4	3	3	3	2	3	3	3	3	4	2	3	60%		
	4	2	1	2	1	1	3	1	2	2	2	1	3	75%		
Total	567	358	215	144	120	126	138	132	151	184	267	120	447	79%		
P604	A	213	149	97	61	37	38	43	42	48	67	94	37	176	83%	
	B	224	81	6	0	0	0	0	3	19	36	76	0	224	100%	
	S															
	Visitor: Meter															
	Reserved															
	Allocated: SCP	5	4	3	2	0	0	1	1	2	2	2	0	5	100%	
	Allocated:															
	Allocated:															
	Allocated: Total	5	4	3	2	0	0	1	1	2	2	2	0	5	100%	
	Accessible															
	UC Vehicle															
Service Yard Loading																
Total	442	234	106	63	37	38	44	46	69	105	172	37	405	92%		
P605	A	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
	B															
	S															
	Visitor: Meter															
	Reserved	6	3	2	1	0	0	1	1	1	1	2	0	6	100%	
	Allocated: AR	2	1	1	1	0	0	0	1	0	0	0	0	2	100%	
	Allocated:															
	Allocated:															
	Allocated: Total	2	1	1	1	0	0	0	1	0	0	0	0	2	100%	
	Accessible															
	UC Vehicle	4	0	0	0	0	0	1	0	0	0	0	0	4	100%	
Service Yard Loading	1	0	0	1	0	1	0	0	0	0	0	0	1	100%		
Total	14	4	3	3	0	1	2	2	1	1	2	0	14	100%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P606	A															
	B															
	S															
	Visitor: Meter	2	1	0	1	0	0	0	0	0	0	0	0	0	2	100%
	Reserved	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated:															
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible	2	2	1	1	1	1	0	0	0	0	1	1	0	2	100%	
UC Vehicle																
Service Yard	2	1	0	0	0	0	1	0	0	0	0	1	0	2	100%	
Loading																
Total		7	4	1	2	1	2	0	0	0	0	1	2	0	7	100%
P607	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible																
UC Vehicle																
Service Yard	2	0	0	0	0	0	0	0	0	0	0	0	0	2	100%	
Loading																
Total		2	0	0	0	0	0	0	0	0	0	0	0	0	2	100%
P608	A															
	B															
	S	393	371	290	195	119	93	95	105	144	177	231	93	300	76%	
	Visitor: Meter															
	Reserved															
	Allocated:															
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total																
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		393	371	290	195	119	93	95	105	144	177	231	93	300	76%	
P609	A															
	B															
	S															
	Visitor: Meter															
	Reserved															
	Allocated: GIC	4	3	3	2	3	3	3	2	3	3	3	2	2	50%	
	Allocated:															
Allocated:																
Allocated:																
Allocated: Total	4	3	3	2	3	3	3	2	3	3	3	2	2	50%		
Accessible	1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
UC Vehicle																
Service Yard																
Loading																
Total		5	4	4	3	4	4	4	3	4	4	4	3	2	40%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P701	A	136	126	122	121	118	116	117	117	118	120	124	116	20	15%
	B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	247	212	199	198	194	192	189	190	191	192	197	189	58	23%
	Total	383	338	321	319	312	308	306	307	309	312	321	306	77	20%
P702	A	653	502	345	221	141	107	106	127	161	225	317	106	547	84%
	B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading														
	Total	653	502	345	221	141	107	106	127	161	225	317	106	547	84%
P703	A	977	922	786	673	537	474	425	420	462	531	640	420	557	57%
	B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading														
	Total	977	922	786	673	537	474	425	420	462	531	640	420	557	57%
P704	A	575	440	263	163	91	68	67	79	109	145	234	67	508	88%
	B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading														
	Total	575	440	263	163	91	68	67	79	109	145	234	67	508	88%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P705	A B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	161	160	157	144	112	97	88	83	95	103	119	83	78	48%
	Total	161	160	157	144	112	97	88	83	95	103	119	83	78	48%
P751	A B S Visitor: Meter Reserved Allocated: TPV Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	219	144	84	33	19	70	56	46	39	64	104	19	200	91%
	219 20	144 10	84 5	33 1	19 1	70 3	56 3	46 1	39 2	64 5	104 9	19 1	200 19	91% 95%	
Total	239	154	89	34	20	73	59	47	41	69	113	20	219	92%	
P752	A B S Visitor: Meter Reserved Allocated: TE Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	106	51	33	26	23	28	29	31	33	35	41	23	83	78%
	8	5	3	3	2	1	1	1	1	2	2	1	7	88%	
8 5	5 3	3 2	3 1	2 0	1 1	1 0	1 1	1 2	1 2	2 1	1 0	7 5	88% 100%		
Total	119	59	38	30	25	30	30	33	36	39	44	25	94	79%	
P753	A B S Visitor: Meter Reserved Allocated: EV Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	337	122	71	55	47	49	49	51	62	93	138	47	290	86%
	1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
1 11	1 9	1 7	1 5	1 3	1 4	1 4	1 3	1 4	1 5	1 7	1 3	0 8	0% 73%		
1	1	1	0	1	0	1	1	1	1	1	1	0	1	100%	
Total	350	133	80	61	52	54	55	56	68	100	147	52	298	85%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P754	A															
	B															
	S															
	Visitor: Meter Reserved															
	Allocated: Allocated: Allocated: Allocated: Total															
Accessible UC Vehicle Service Yard	12	8	5	4	4	5	4	5	6	8	10	4	8	67%		
Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%		
Total	13	9	6	5	5	6	5	6	7	9	11	5	8	62%		
P755	A	5	2	1	2	2	2	2	2	1	2	3	1	4	80%	
	B	94	22	4	1	2	5	4	5	6	16	43	1	93	99%	
	S															
	Visitor: Meter Reserved															
	Allocated: RCEC Allocated: Allocated: Allocated: Total	5	4	3	2	2	3	2	2	3	4	5	2	3	60%	
Accessible UC Vehicle Service Yard	5	4	3	2	2	3	2	2	3	4	5	2	3	60%		
Loading	4	3	3	3	3	3	3	4	4	4	4	3	1	25%		
Total	108	31	11	8	9	13	11	13	14	26	55	8	100	93%		
P756	A															
	B															
	S	109	96	80	67	67	72	71	69	68	70	77	67	42	39%	
	Visitor: Meter Reserved															
	Allocated: Allocated: Allocated: Allocated: Total															
Accessible UC Vehicle Service Yard																
Loading																
Total	109	96	80	67	67	72	71	69	68	70	77	67	42	39%		
P757	A															
	B															
	S															
	Visitor: Meter Reserved															
	Allocated: SEPH Allocated: SEPV Allocated: Allocated: Allocated: Total	11	7	6	6	6	6	6	6	5	6	8	5	6	55%	
Accessible UC Vehicle Service Yard	28	10	3	2	5	7	4	3	5	15	20	2	26	93%		
Loading																
Total	39	17	9	8	11	13	10	9	10	21	28	8	31	79%		
Accessible UC Vehicle Service Yard	2	1	0	0	0	1	0	0	1	1	1	0	2	100%		
Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%		
Total	42	19	10	9	12	15	11	10	12	23	30	9	33	79%		

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P758	A B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	61	28	24	22	22	22	22	24	24	29	39	22	39	64%
	Total	61	28	24	22	22	22	22	24	24	29	39	22	39	64%
P901	A B S Visitor: Meter Reserved Allocated: HPV Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	41	41	40	26	15	22	25	18	15	19	26	15	26	63%
	Total	41	41	40	26	15	22	25	18	15	19	26	15	26	63%
P902	A B S Visitor: Meter Reserved Allocated: HPV Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	41	39	33	2	1	9	12	6	5	6	15	1	40	98%
	Total	41	39	33	2	1	9	12	6	5	6	15	1	40	98%
P903	A B S Visitor: Meter Reserved Allocated: HPV Allocated: Allocated: Allocated: Allocated: Total Accessible UC Vehicle Service Yard Loading	39	38	20	0	0	8	3	0	0	2	8	0	39	100%
	Total	39	38	20	0	0	8	3	0	0	2	8	0	39	100%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P904	A														
	B														
	S														
	Visitor: Meter Reserved	2	2	2	1	1	0	0	1	1	1	1	0	2	100%
	Allocated: CTC	37	24	6	0	0	2	1	0	0	1	3	0	37	100%
Allocated: HPV															
Allocated:															
Allocated:															
Allocated: Total	39	26	8	1	1	2	1	1	1	2	4	1	38	97%	
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total	39	26	8	1	1	2	1	1	1	2	4	1	38	97%	
P905	A														
	B														
	S														
	Visitor: Meter Reserved	39	9	1	0	0	1	0	0	0	0	3	0	39	100%
	Allocated: HPV														
Allocated:															
Allocated:															
Allocated: Total	39	9	1	0	0	1	0	0	0	0	3	0	39	100%	
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total	39	9	1	0	0	1	0	0	0	0	3	0	39	100%	
P906	A														
	B														
	S														
	Visitor: Meter Reserved	39	0	0	0	0	0	0	0	0	1	1	0	39	100%
	Allocated: HPV														
Allocated:															
Allocated:															
Allocated: Total	39	0	0	0	0	0	0	0	0	1	1	0	39	100%	
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total	39	0	0	0	0	0	0	0	0	0	1	1	0	39	100%
P907	A														
	B														
	S														
	Visitor: Meter Reserved	28	0	0	0	0	0	0	0	0	0	0	0	28	100%
	Allocated: HPV														
Allocated:															
Allocated:															
Allocated: Total	28	0	0	0	0	0	0	0	0	0	0	0	28	100%	
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total	28	0	0	0	0	0	0	0	0	0	0	0	0	28	100%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P908	A														
	B														
	S														
	Visitor: Meter Reserved	4	2	3	2	1	3	3	2	2	2	3	1	3	75%
Allocated: APO															
Allocated:															
Allocated:															
Allocated: Total	4	2	3	2	1	3	3	2	2	2	3	1	3	75%	
Accessible	12	4	1	0	1	1	1	1	1	4	6	0	12	100%	
UC Vehicle															
Service Yard															
Loading															
Total		16	6	4	2	2	4	4	3	3	6	9	2	14	88%
P909	A	26	1	0	0	0	0	1	0	1	1	1	0	26	100%
	B														
	S														
	Visitor: Meter Reserved	13	10	10	9	8	7	9	5	6	8	8	5	8	62%
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		39	11	10	9	8	7	10	5	7	9	9	5	34	87%
P910	A	37	4	0	0	0	1	0	0	0	1	4	0	37	100%
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible	1	1	1	1	0	0	1	0	0	1	1	0	1	100%	
UC Vehicle															
Service Yard															
Loading															
Total		38	5	1	1	0	1	1	0	0	2	5	0	38	100%
P911	A	38	15	4	0	0	1	0	0	1	3	9	0	38	100%
	B														
	S														
	Visitor: Meter Reserved														
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		38	15	4	0	0	1	0	0	1	3	9	0	38	100%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P912	A	36	27	17	4	1	2	3	1	2	4	10	1	35	97%	
	B															
	S															
	Visitor: Meter Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
	UC Vehicle															
	Service Yard															
	Loading															
	Total	37	27	17	4	1	2	3	1	2	4	10	1	36	97%	
P913	A	39	39	38	32	23	20	24	22	21	18	22	18	21	54%	
	B															
	S															
	Visitor: Meter Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total	39	39	38	32	23	20	24	22	21	18	22	18	21	54%	
P914	A	21	17	17	17	12	13	14	14	13	13	13	12	9	43%	
	B	15	0	0	0	0	0	0	0	1	4	7	0	15	100%	
	S															
	Visitor: Meter Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
	UC Vehicle															
	Service Yard															
	Loading															
	Total	37	18	18	18	13	14	15	15	15	18	21	13	24	65%	
P921	A	53	16	8	1	0	0	3	3	4	10	20	0	53	100%	
	B															
	S															
	Visitor: Meter Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated: Total															
	Accessible	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
	UC Vehicle															
	Service Yard															
	Loading															
	Total	55	18	10	3	2	2	5	5	6	12	22	2	53	96%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P922	A	86	24	13	4	1	2	3	6	8	17	30	1	85	99%
	B														
	S														
	Visitor: Meter Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible	5	4	4	4	5	4	4	4	4	4	3	3	2	40%
	UC Vehicle														
	Service Yard Loading														
	Total	91	28	17	8	6	6	7	10	12	21	33	6	85	93%
P923	A	100	51	30	11	7	9	10	13	15	22	38	7	93	93%
	B														
	S														
	Visitor: Meter Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard Loading														
	Total	100	51	30	11	7	9	10	13	15	22	38	7	93	93%
P924	A	103	71	50	25	17	18	18	19	25	33	44	17	86	83%
	B														
	S														
	Visitor: Meter Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard Loading														
	Total	103	71	50	25	17	18	18	19	25	33	44	17	86	83%
P925	A	99	67	56	43	36	36	36	38	43	49	57	36	63	64%
	B														
	S														
	Visitor: Meter Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard Loading														
	Total	99	67	56	43	36	36	36	38	43	49	57	36	63	64%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P926	A B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total	125	0	0	0	0	1	1	1	6	25	39	0	125	100%	
	Accessible UC Vehicle Service Yard Loading	2	1	1	1	1	1	1	1	1	1	2	1	1	50%	
	Total	127	1	1	1	1	2	2	2	7	26	41	1	126	99%	
P927	A B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total	86	0	0	0	0	2	1	2	5	17	31	0	86	100%	
	Accessible UC Vehicle Service Yard Loading															
	Total	86	0	0	0	0	2	1	2	5	17	31	0	86	100%	
P928	A B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total	91	1	0	0	1	1	1	2	4	17	32	0	91	100%	
	Accessible UC Vehicle Service Yard Loading															
	Total	91	1	0	0	1	1	1	2	4	17	32	0	91	100%	
P929	A B S Visitor: Meter Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Total	85	8	2	0	1	2	2	3	7	15	28	0	85	100%	
	Accessible UC Vehicle Service Yard Loading															
	Total	85	8	2	0	1	2	2	3	7	15	28	0	85	100%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P930	A	91	11	5	0	0	2	22	27	25	32	44	0	91	100%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	91	11	5	0	0	2	22	27	25	32	44	0	91	100%
P931	A	104	54	42	31	24	25	24	25	30	37	49	24	80	77%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated: Total														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	104	54	42	31	24	25	24	25	30	37	49	24	80	77%
P941	A	33	28	25	17	12	15	16	12	12	15	19	12	21	64%
	B														
	S														
	Visitor: Meter														
	Reserved														
	Allocated: 140P														
	Allocated:														
	Allocated:														
	Allocated: Total	33	28	25	17	12	15	16	12	12	15	19	12	21	64%
	Accessible	3	2	2	1	1	0	1	1	0	1	1	0	3	100%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	36	30	27	18	13	15	17	13	12	16	20	12	24	67%
P942	A	10	9	8	6	5	4	4	4	4	4	5	4	6	60%
	B	11	2	0	0	0	0	0	0	1	1	4	0	11	100%
	S														
	Visitor: Meter														
	Reserved	7	6	6	5	4	4	4	4	4	4	5	4	3	43%
	Allocated: 140P	3	2	2	1	0	1	1	0	0	1	1	0	3	100%
	Allocated: 140V	13	10	7	5	4	2	2	1	2	3	4	1	12	92%
	Allocated:														
	Allocated:														
	Allocated: Total	16	12	9	6	4	3	3	1	2	4	5	1	15	94%
	Accessible	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	45	30	24	18	14	12	12	10	12	14	20	10	35	78%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P951	A														
	B														
	S														
	Visitor: Meter Reserved	11	11	9	1	0	0	1	0	1	3	6	0	11	100%
Allocated: VAL															
Allocated:															
Allocated:															
Allocated: Total	11	11	9	1	0	0	1	0	1	3	6	0	11	100%	
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total		11	11	9	1	0	0	1	0	1	3	6	0	11	100%
P952	A														
	B														
	S														
	Visitor: Meter Reserved	1	1	1	1	0	0	0	0	0	0	1	0	1	100%
Allocated: VP	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
Allocated:															
Allocated:															
Allocated: Total	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
Accessible															
UC Vehicle															
Service Yard															
Loading	8	2	1	2	3	1	1	1	2	2	4	1	7	88%	
Total		11	4	3	4	4	2	2	2	3	3	6	2	9	82%
P953	A														
	B														
	S														
	Visitor: Meter Reserved	8	4	4	4	3	3	3	3	3	3	2	2	6	75%
Allocated: MRI	6	4	3	2	4	3	3	4	4	4	4	2	4	67%	
Allocated:															
Allocated:															
Allocated: Total	6	4	3	2	4	3	3	4	4	4	4	2	4	67%	
Accessible	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
UC Vehicle															
Service Yard															
Loading															
Total		15	8	7	6	7	6	6	7	7	7	6	6	9	60%
P954	A														
	B														
	S														
	Visitor: Meter Reserved	3	1	1	0	0	1	1	0	1	1	1	0	3	100%
Allocated: BFH	34	24	20	14	12	14	14	14	13	13	18	12	22	65%	
Allocated: MRI	8	2	3	3	3	3	3	2	3	3	3	2	6	75%	
Allocated:	2	2	1	1	1	1	1	1	1	1	1	1	1	50%	
Allocated:															
Allocated: Total	10	4	4	4	4	4	4	3	4	4	4	3	7	70%	
Accessible	4	0	0	0	0	0	1	0	1	2	2	0	4	100%	
UC Vehicle															
Service Yard															
Loading															
Total		51	29	25	18	16	19	20	17	19	20	25	16	35	69%

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P955	A	11	0	0	0	1	0	0	0	1	2	5	0	11	100%
	B														
	S														
	Visitor: Meter														
	Reserved	24	18	14	10	8	9	9	8	8	9	11	8	16	67%
	Allocated:														
	Allocated:														
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle	5	1	1	1	1	1	1	2	1	2	2	1	4	80%	
Service Yard	6	1	1	0	1	1	1	1	0	2	3	0	6	100%	
Loading	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
Total	47	20	16	11	11	11	11	11	10	15	21	10	37	79%	
P956	A	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
	B														
	S														
	Visitor: Meter														
	Reserved	2	2	2	0	1	1	1	1	1	1	1	0	2	100%
	Allocated: OAR	2	0	0	0	0	0	0	0	0	0	0	0	2	100%
	Allocated:														
Allocated:															
Allocated:															
Allocated: Total	2	0	0	0	0	0	0	0	0	0	0	0	2	100%	
Accessible															
UC Vehicle															
Service Yard	2	1	0	0	0	0	0	0	1	1	1	0	2	100%	
Loading	3	2	0	1	0	0	0	0	1	0	0	0	3	100%	
Total	10	5	2	1	1	1	1	1	3	2	2	1	9	90%	
P957	A	13	1	0	0	0	0	0	0	0	1	0	0	13	100%
	B														
	S														
	Visitor: Meter	3	1	1	1	0	0	0	0	0	0	1	0	3	100%
	Reserved	25	18	19	14	13	9	11	9	9	9	12	9	16	64%
	Allocated: MD	1	1	0	1	1	1	1	1	1	1	1	0	1	100%
	Allocated: ONC	24	17	12	7	2	6	7	5	7	7	9	2	22	92%
Allocated: RO	4	3	2	2	0	1	1	1	1	2	1	0	4	100%	
Allocated:															
Allocated:															
Allocated: Total	29	21	14	10	3	8	9	7	9	10	11	3	26	90%	
Accessible	8	4	1	0	1	1	1	1	1	1	2	0	8	100%	
UC Vehicle	1	0	0	0	1	1	1	1	1	0	0	0	1	100%	
Service Yard															
Loading															
Total	79	45	35	25	18	19	22	18	20	21	26	18	61	77%	
P958	A														
	B														
S															
Visitor: Meter															
Reserved	11	7	7	5	3	3	4	3	4	4	6	3	8	73%	
Allocated:															
Allocated:															
Allocated:															
Allocated: Total															
Accessible															
UC Vehicle															
Service Yard															
Loading															
Total	11	7	7	5	3	3	4	3	4	4	6	3	8	73%	

Lot	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
P959	A																
	B																
	S																
	Visitor: Meter Reserved	3	1	0	0	0	0	0	0	0	0	0	1	0	3	100%	
	Allocated: HASE	38	8	4	0	2	1	0	2	2	7	7	0	38	100%		
	Allocated:																
	Allocated:																
Allocated: Total	38	8	4	0	2	1	0	2	2	7	7	0	38	100%			
Accessible	2	1	0	0	0	0	0	0	0	0	0	0	2	100%			
UC Vehicle																	
Service Yard																	
Loading																	
Total	43	10	4	0	2	1	0	2	2	7	8	0	43	100%			
P960	A																
	B																
	S																
	Visitor: Meter Reserved	2	0	0	0	0	0	0	0	1	1	1	0	2	100%		
	Allocated: HAS	13	1	0	1	1	1	0	1	1	2	3	0	13	100%		
	Allocated: PR	9	8	6	3	3	3	2	3	4	6	7	2	7	78%		
	Allocated:																
Allocated:																	
Allocated: Total	22	9	6	4	4	4	2	4	5	8	10	2	20	91%			
Accessible	8	0	0	0	0	0	0	0	0	1	1	0	8	100%			
UC Vehicle																	
Service Yard																	
Loading																	
Total	32	9	6	4	4	4	2	4	6	10	12	2	30	94%			
P961	A																
	B																
	S																
	Visitor: Meter Reserved	1	0	0	0	0	0	0	0	0	0	0	0	1	100%		
	Allocated: HE	4	0	0	0	0	0	0	0	0	0	0	0	4	100%		
	Allocated:																
	Allocated:																
Allocated: Total	4	0	0	0	0	0	0	0	0	0	0	0	4	100%			
Accessible																	
UC Vehicle																	
Service Yard																	
Loading																	
Total	5	0	0	0	0	0	0	0	0	0	0	0	5	100%			
P962	A																
	B																
	S	118	31	15	5	4	5	7	9	12	22	44	4	114	97%		
	Visitor: Meter Reserved																
	Allocated:																
	Allocated:																
	Allocated: Total																
Accessible																	
UC Vehicle																	
Service Yard																	
Loading																	
Total	118	31	15	5	4	5	7	9	12	22	44	4	114	97%			

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
By Structure

Structure	Parking Space	Parking Spaces	Average Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Pangea	A	160	143	134	122	115	108	107	106	106	108	119	106	54	34%
	B	188	169	157	136	107	102	98	97	98	106	120	97	91	48%
	S	553	227	137	58	21	12	13	32	66	95	128	12	541	98%
	Visitor	52	50	49	47	44	45	43	45	46	47	48	43	9	17%
	Reserved	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated														
	Accessible	17	17	17	17	17	16	16	16	16	16	16	16	1	6%
	UC Vehicle Service Yard Loading														
Total		971	607	495	381	305	284	278	297	333	373	432	278	693	71%
Torrey Pines Center South	A														
	B	399	203	111	86	80	109	120	101	112	140	210	80	319	80%
	S														
	Visitor	23	20	14	10	9	10	12	8	11	13	16	8	15	65%
	Reserved	6	3	2	1	1	2	4	1	1	1	2	1	5	83%
	Allocated	5	3	4	4	2	3	2	2	2	2	2	2	3	60%
	Accessible	10	6	3	3	2	3	4	4	4	5	7	2	8	80%
	UC Vehicle Service Yard Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
Total		444	236	135	105	95	128	143	117	131	162	238	95	349	79%
Torrey Pines Center North	A														
	B	159	103	61	46	43	51	59	47	54	70	93	43	116	73%
	S														
	Visitor														
	Reserved	4	4	3	2	2	3	2	2	3	3	3	2	2	50%
	Allocated														
	Accessible	2	2	2	2	1	1	2	1	2	1	2	1	1	50%
	UC Vehicle Service Yard Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
Total		169	113	69	54	50	59	67	54	63	78	102	50	119	70%
Gilman	A	147	129	113	82	59	43	39	36	43	56	71	36	111	76%
	B	247	178	74	20	4	4	9	6	14	36	67	4	243	98%
	S	307	2	0	0	0	0	0	0	5	14	33	0	307	100%
	Visitor	96	69	62	48	31	21	18	26	31	44	39	18	78	81%
	Reserved														
	Allocated	32	31	26	24	25	25	24	24	22	24	23	22	10	31%
	Accessible	17	16	16	15	14	14	14	15	14	15	15	14	3	18%
	UC Vehicle Service Yard Loading	17	7	8	9	9	8	8	9	9	5	5	5	12	71%
Total		863	432	299	198	142	115	112	116	138	194	253	112	751	87%
Arbor	A	197	103	76	53	36	37	42	37	38	40	59	36	161	82%
	B	15	0	0	0	0	0	0	0	1	4	7	0	15	100%
	S														
	Visitor														
	Reserved	13	10	10	9	8	7	9	5	6	8	8	5	8	62%
	Allocated	270	155	105	31	18	45	44	27	23	32	60	18	252	93%
	Accessible	15	6	3	2	2	2	3	2	2	6	8	2	13	87%
	UC Vehicle Service Yard Loading														
Total		510	274	194	95	64	91	98	71	70	90	142	64	446	87%

Structure	Parking Space	Parking Spaces	Average Empty Parking Spaces											At Peak					
			8:00	9:00	10:00	11:00	12:00	1:00	2:00	3:00	4:00	5:00	Empty Spaces	Occupied Spaces	% Occupied				
			am	am	am	am	pm	pm	pm	pm	pm	pm							
Bachman	A	1023	303	206	115	87	98	121	139	172	274	412	87	936	91%				
	B																		
	S																		
	Visitor																		
	Reserved																		
Allocated																			
Accessible	4		3	3	3	3	3	3	3	3	3	4	3	1	25%				
UC Vehicle	5		4	4	4	5	4	4	4	4	4	3	3	2	40%				
Service Yard																			
Loading																			
Total		1032	310	213	122	95	105	128	146	179	281	419	95	937	91%				
140 Arbor	A	10	9	8	6	5	4	4	4	4	4	5	4	6	60%				
	B	11	2	0	0	0	0	0	0	1	1	4	0	11	100%				
	S																		
	Visitor																		
	Reserved	7	6	6	5	4	4	4	4	4	4	5	4	3	43%				
Allocated	49	40	34	23	16	18	19	13	14	19	24	13	36	73%					
Accessible	4	3	3	2	2	1	2	2	1	2	2	1	3	75%					
UC Vehicle																			
Service Yard																			
Loading																			
Total		81	60	51	36	27	27	29	23	24	30	40	23	58	72%				

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
Parking Spaces Closed

Lot	Parking Space	Average Parking Spaces Closed										
		8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	
P001	Allocated: SIO	7	7	7	7	7	7	7	7	7	7	7
P001	Accessible	1	1	1	1	1	1	1	1	1	1	1
P001	Loading	2	2	2	2	2	2	2	2	2	2	2
P001	Reserved	1	1	1	1	1	1	1	1	1	1	1
P003	Accessible	1	1	1	1	1	1	1	1	1	1	1
P007	UC Vehicle	2	2	2	2	2	2	2	2	2	2	2
P017	Accessible	2	2	2	2	2	2	2	2	2	2	2
P018	B	1	1	1	1	1	1	1	1	1	1	1
P111	A	1	1	1	1	1	1	1	1	1	1	1
P115	Service Yard	4	4	4	4	4	4	4	4	4	4	4
P202	UC Vehicle	1	1	1	1	1	1	1	1	1	1	1
P206	Visitor: Meter	17	17	17	17	17	17	17	17	17	17	17
P206	Loading	1	1	1	1	1	1	1	1	1	1	1
P207	A	2	2	2	2	2	2	2	2	2	2	2
P207	B	2	2	2	2	2	2	2	2	2	2	2
P308	A	1	1	1	1	1	1	1	1	1	1	1
P354	Visitor: Meter	3	3	3	3	3	3	3	3	3	3	3
P359	S	2	2	2	2	2	2	2	2	2	2	2
P381	B	1	1	1	1	1	1	1	1	1	1	1
P403	Visitor: Meter	4	4	4	4	4	4	4	4	4	4	4
P411	Visitor: Meter	9	9	9	9	9	9	9	9	9	9	9
P414	Loading	3	3	3	3	3	3	3	3	3	3	3
P451	Visitor: Meter	13	13	13	13	13	13	13	13	13	13	13
P503	A	1	1	1	1	1	1	1	1	1	1	1
P503	Visitor: Meter	1	1	1	1	1	1	1	1	1	1	1
P506	Visitor: Meter	1	1	1	1	1	1	1	1	1	1	1
P507	Visitor: Meter	1	1	1	1	1	1	1	1	1	1	1
P508	Visitor: Meter	1	1	1	1	1	1	1	1	1	1	1
P601	A	3	3	3	3	3	3	3	3	3	3	3
P601	Visitor: Meter	4	4	4	4	4	4	4	4	4	4	4
P603	Visitor: Meter	3	3	3	3	3	3	3	3	3	3	3
P605	UC Vehicle	2	2	2	2	2	2	2	2	2	2	2
P930	B	24	24	24	24	24	5	0	0	0	0	0
P956	A	1	1	1	1	1	1	1	1	1	1	1
P959	Allocated: HASE	1	1	1	1	1	1	1	1	1	1	1
P961	Reserved	1	1	1	1	1	1	1	1	1	1	1
P961	Allocated: HE	4	4	4	4	4	4	4	4	4	4	4
Total		129	129	129	129	129	110	105	105	105	105	105

Includes parking spaces blocked off for special events, occupied by equipment, or undergoing minor maintenance. Excludes parking spaces lost (removed from inventory) for an extended time due to construction. A closed parking space was classified as occupied.

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
Allocated Parking Spaces

Abbreviation	Allocated Parking Space
140P	140 Arbor Patient
140V	140 Arbor Visitor
ACP	A Carpool
ACT	Administrative Computing and Telecommunications Vehicle
APO	Arbor Parking Office Visitor
AR	Animal Resources Vehicle
BA	Birch Aquarium Visitor
BAB	Birch Aquarium Visitor: Bus
BCP	B Carpool
BE	Building Engineer
BFH	Bannister Family House Patient/Visitor
BS	Bookstore
CC	Crafts Center Staff
CTC	Clinical Trials Center Patient/Visitor
CUS	Credit Union Staff
CUV	Credit Union Visitor
ERV	Emergency Response Vehicle
EV	Electric Vehicle
FC	Faculty Club Visitor
GIC	Gilman Information Center Visitor
GPO	Gilman Parking Office Visitor
HAS	Medical Center Hillcrest Attending Staff
HASE	Medical Center Hillcrest Attending Staff / Emergency Patient/Visitor
HE	Medical Center Hillcrest Emergency Patient/Visitor
HPV	Medical Center Hillcrest Patient/Visitor
IC	International Center Visitor
IMP	Imprints Visitor
LG	Lifeguard
LJP	La Jolla Playhouse Staff
MD	Mail Drop
MG	Medical Group Patient/Visitor
MIB	Muir Information Board Visitor
MRI	Magnetic Resonance Institute Patient/Visitor
NIC	Northpoint Information Center Visitor
OAR	OAR Visitor
ONC	Oncology Patient/Visitor
OSD	Office of Students with Disabilities Visitor
PC	Price Center
PM	Property Management
POL	Police Vehicle
PR	Pulmonary Rehabilitation Patient/Visitor
RA	Retirement Association Visitor
RCEC	Ratner Children's Eye Center Patient/Visitor
RIB	Revelle Information Board Visitor
RO	Radiation Oncology Patient/Visitor
RS	Resale Shop Volunteer
SCP	S Carpool
SDSC	San Diego Supercomputer Staff
SEPH	Shiley Eye Center Physician
SEPV	Shiley Eye Center Patient/Visitor
SHAS	Student Health Attending Staff
SHPV	Student Health Patient/Visitor
SIO	Scripps Institution of Oceanography Staff
TC	Telephone Company Vehicle
TE	Thornton Hospital Emergency Patient/Visitor
TPSS	Transportation and Parking Services Shuttle
TPV	Thornton Hospital Patient/Visitor
VAL	Valet
VP	Vanpool Vehicle

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
Key to Locations, Areas, Neighborhoods, Lots, and Structures

University of California, San Diego																	
Location	La Jolla Campus																Medical Center Hillcrest
Area	Scripps Institution of Oceanography															East Campus	Medical Center Hillcrest
Neighborhood	SIO South	SIO West	SIO Hillside	Aquarium	Theatre District	Revelle College	Muir College	Marshall College	North Campus	Warren College	Campus Services Complex	Roosevelt College	School of Medicine	University Center	East Campus Academic	Health Sciences	Medical Center Hillcrest
Lot	P001 P002 P003 P005 P006 P007 P008	P010 P011 P012 P013	P014 P016	P017 P018	P105	P101 P102 P103 P104 P106 P107 P108 P110 P111 P112 P115 P116	P113 P114 P201 P202 P203 P204 P205 P206 P207 P208 P414	P301 P302 P303 P304 P308 P309 P310	P306 P351 P352 P354 P355 P356 P357 P358 P359 P371 P372 P373 P374 P375 P376 P381 P382 P383 P391 P392 P393 P394	P502 P503 P504 P505 P508 P509	P507 P510	P401 P402 P404 P406 P451 P452 P453 P454 P455 P456 P506	P601 P602 P603 P604 P605 P606 P607 P608 P609	P403 P405 P407 P408 P410 P411 P412 P413 P415 P416 P418 P501	P701 P702 P703 P704 P705	P751 P752 P753 P754 P755 P756 P757 P758	P901 P902 P903 P904 P905 P906 P907 P908 P909 P910 P911 P912 P913 P914 P921 P922 P923 P924 P925 P926 P927 P928 P929 P930 P931 P941 P942 P951 P952 P953 P954 P955 P956 P957 P958 P959 P960 P961 P962
Structure									Pangea (P371-6) TPC South (P381-2) TPC North (P391-3)			Gilman (P451-6)					Arbor (P901-14) Bachman (P921-31) 140 Arbor (P941-2)

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring 2001
Schedule

Lots	Count 1		Count 2		Count 3		Count 4		Count 5	
	Week 1 Beginning April 2	Week 2 Beginning April 9	Week 3 Beginning April 16	Week 4 Beginning April 23	Week 5 Beginning April 30	Week 6 Beginning May 7	Week 7 Beginning May 14	Week 8 Beginning May 21	Week 9 Beginning May 28	Week 10 Beginning June 4
P001 - P017	Monday			Thursday		Wednesday		Tuesday		Monday
P101 - P116	Tuesday		Monday			Thursday		Wednesday		Tuesday
P201 - P208	Tuesday		Monday			Thursday		Wednesday		Tuesday
P301 - P310	Wednesday		Tuesday			Monday	Thursday			Wednesday
P351 - P359	Wednesday		Tuesday			Monday	Thursday			Wednesday
P371 - P376	Wednesday		Tuesday			Monday	Thursday			Wednesday
P381 - P383	Wednesday		Tuesday			Monday	Thursday			Wednesday
P391 - P394	Wednesday		Tuesday			Monday	Thursday			Wednesday
P401 - P418	Thursday		Wednesday		Tuesday		Monday			Thursday
P451 - P456	Thursday		Wednesday		Tuesday		Monday			Thursday
P501 - P510		Monday	Thursday		Wednesday		Tuesday		Wednesday	
P601 - P609	Monday			Thursday		Wednesday		Tuesday		Monday
P701 - P705		Monday	Thursday		Wednesday		Tuesday		Wednesday	
P751 - P760		Monday	Thursday		Wednesday		Tuesday		Wednesday	
P901 - P914		Tuesday		Monday	Thursday		Wednesday		Tuesday	
P921 - P931		Tuesday		Monday	Thursday		Wednesday		Tuesday	
P941 - P942		Tuesday		Monday	Thursday		Wednesday		Tuesday	
P952 - P963		Tuesday		Monday	Thursday		Wednesday		Tuesday	