

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
University-wide

	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
University of California, San Diego	A	2673	1490	943	404	266	235	256	278	393	538	757	235	2438	91%
	B	7079	2593	1488	806	587	595	580	651	924	1452	2063	580	6499	92%
	S	3391	1521	1162	1042	844	691	653	690	711	981	1046	653	2738	81%
	Visitor	2297	1319	986	566	357	395	418	467	562	695	930	357	1940	84%
	Reserved	599	461	393	333	306	318	318	301	323	354	399	301	298	50%
	Allocated	1386	879	707	429	382	359	381	409	440	476	569	359	1027	74%
	Accessible	657	324	243	163	147	157	152	147	191	219	291	147	510	78%
	UC Vehicle	280	52	110	92	118	105	106	87	93	85	91	52	228	81%
	Service Yard	133	62	47	34	32	30	36	33	44	44	64	30	103	77%
	Loading	165	121	87	52	52	51	52	57	79	73	94	51	114	69%
	Total	18660	8822	6166	3921	3091	2936	2952	3120	3760	4917	6304	2936	15724	84%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Location

Location	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
La Jolla Campus	A	2410	1340	838	322	189	157	182	209	301	430	626	157	2253	93%
	B	5852	2143	1134	501	307	311	358	394	614	989	1381	307	5545	95%
	S	3391	1521	1162	1042	844	691	653	690	711	981	1046	653	2738	81%
	Visitor	1932	1076	787	394	204	219	240	304	394	486	695	204	1728	89%
	Reserved	504	385	330	273	256	263	265	257	268	289	331	256	248	49%
	Allocated	1265	780	624	340	303	278	307	334	362	406	488	278	987	78%
	Accessible	603	307	231	154	135	146	140	140	180	204	271	135	468	78%
	UC Vehicle	264	48	108	85	107	96	98	84	90	83	87	48	216	82%
	Service Yard	120	62	47	31	30	28	34	29	43	42	61	28	92	77%
	Loading	152	118	86	51	48	48	49	55	77	69	89	48	104	68%
	Total	16493	7780	5347	3193	2423	2237	2326	2496	3040	3979	5075	2237	14256	86%
Medical Center Hillcrest	A	263	150	105	82	77	78	74	69	92	108	131	69	194	74%
	B	1227	450	354	305	280	284	222	257	310	463	682	222	1005	82%
	S														
	Visitor	365	243	199	172	153	176	178	163	168	209	235	153	212	58%
	Reserved	95	76	63	60	50	55	53	44	55	65	68	44	51	54%
	Allocated	121	99	83	89	79	81	74	75	78	70	81	70	51	42%
	Accessible	54	17	12	9	12	11	12	7	11	15	20	7	47	87%
	UC Vehicle	16	4	2	7	11	9	8	3	3	2	4	2	14	88%
	Service Yard	13	0	0	3	2	2	2	4	1	2	3	0	13	100%
Loading	13	3	1	1	4	3	3	2	2	4	5	1	12	92%	
	Total	2167	1042	819	728	668	699	626	624	720	938	1229	624	1543	71%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Area

Area	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Scripps Institution of Oceanography	A														
	B	121	100	83	47	45	41	37	14	20	40	43	14	107	88%
	S	139	104	85	54	36	36	46	35	42	48	53	35	104	75%
	Visitor	4	4	4	3	3	3	2	2	2	3	3	2	2	50%
	Reserved	1	1	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated	461	386	318	156	143	98	106	117	140	154	167	98	363	79%
	Accessible	29	26	23	20	19	11	11	12	21	20	20	11	18	62%
	UC Vehicle	7	2	2	2	2	1	1	2	3	3	3	1	6	86%
	Service Yard	5	1	3	3	3	3	3	3	3	2	3	1	4	80%
	Loading	13	9	9	8	6	8	8	8	10	10	10	6	7	54%
Total	780	633	527	293	257	201	214	193	241	280	302	193	587	75%	
West Campus	A	1882	1161	710	233	111	75	102	115	196	290	453	75	1807	96%
	B	3549	1302	723	316	189	197	219	239	371	646	909	189	3360	95%
	S	1990	385	319	280	222	198	185	225	225	242	298	185	1805	91%
	Visitor	977	655	506	267	113	71	89	141	186	244	409	71	906	93%
	Reserved	386	315	267	215	197	203	209	199	216	233	270	197	189	49%
	Allocated	497	293	234	138	122	125	133	148	154	178	220	122	375	75%
	Accessible	351	198	159	102	85	82	84	82	108	126	184	82	269	77%
	UC Vehicle	232	36	102	78	99	85	86	71	76	69	72	36	196	84%
	Service Yard	101	59	43	28	25	24	29	24	37	36	53	24	77	76%
	Loading	112	95	67	40	33	28	31	37	57	47	66	28	84	75%
Total	10077	4499	3130	1697	1196	1088	1167	1281	1626	2111	2934	1088	8989	89%	
East Campus	A	528	179	128	89	78	82	80	94	105	140	173	78	450	85%
	B	2182	741	328	138	73	73	102	141	223	303	429	73	2109	97%
	S	1262	1032	758	708	586	457	422	430	444	691	695	422	840	67%
	Visitor	951	417	277	124	88	145	149	161	206	239	283	88	863	91%
	Reserved	117	69	63	58	59	60	56	58	52	56	61	52	65	56%
	Allocated	307	101	72	46	38	55	68	69	68	74	101	38	269	88%
	Accessible	223	83	49	32	31	53	45	46	51	58	67	31	192	86%
	UC Vehicle	25	10	4	5	6	10	11	11	11	11	12	4	21	84%
	Service Yard	14	2	1	0	2	1	2	2	3	4	5	0	14	100%
	Loading	27	14	10	3	9	12	10	10	10	12	13	3	24	89%
Total	5636	2648	1690	1203	970	948	945	1022	1173	1588	1839	945	4691	83%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Area

Area	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Medical Center Hillcrest	A	263	150	105	82	77	78	74	69	92	108	131	69	194	74%
	B	1227	450	354	305	280	284	222	257	310	463	682	222	1005	82%
	S														
	Visitor	365	243	199	172	153	176	178	163	168	209	235	153	212	58%
	Reserved	95	76	63	60	50	55	53	44	55	65	68	44	51	54%
	Allocated	121	99	83	89	79	81	74	75	78	70	81	70	51	42%
	Accessible	54	17	12	9	12	11	12	7	11	15	20	7	47	87%
	UC Vehicle	16	4	2	7	11	9	8	3	3	2	4	2	14	88%
	Service Yard	13	0	0	3	2	2	2	4	1	2	3	0	13	100%
	Loading	13	3	1	1	4	3	3	2	2	4	5	1	12	92%
Total		2167	1042	819	728	668	699	626	624	720	938	1229	624	1543	71%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
SIO South	A														
	B														
	S														
	Visitor														
	Reserved	1	1	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated	173	109	87	24	23	9	7	8	16	22	19	7	166	96%
	Accessible	9	6	5	3	3	2	2	1	4	5	5	1	8	89%
	UC Vehicle	7	2	2	2	2	1	1	2	3	3	3	1	6	86%
	Service Yard	3	1	2	1	1	1	1	1	1	0	1	0	3	100%
Loading	9	5	6	4	3	4	4	4	6	6	6	3	6	67%	
Total		202	124	102	34	32	17	15	16	30	36	34	15	187	93%
SIO West	A														
	B	52	41	31	14	13	12	12	12	15	15	16	12	40	77%
	S														
	Visitor														
	Reserved														
	Allocated	26	20	8	0	0	2	3	5	5	6	6	0	26	100%
	Accessible	5	5	4	3	3	4	4	4	4	4	4	3	2	40%
	UC Vehicle														
	Service Yard	2	0	1	2	2	2	2	2	2	2	2	0	2	100%
Loading	2	2	2	2	1	2	2	2	2	2	2	1	1	50%	
Total		87	68	46	21	19	22	23	25	28	29	30	19	68	78%
SIO Hillside	A														
	B	69	59	52	33	32	29	25	2	5	25	27	2	67	97%
	S	68	57	46	32	22	19	24	22	23	25	27	19	49	72%
	Visitor	4	4	4	3	3	3	2	2	2	3	3	2	2	50%
	Reserved														
	Allocated	2	2	1	2	2	2	2	2	2	2	2	1	1	50%
	Accessible	6	6	6	6	6	5	5	5	5	5	5	5	1	17%
	UC Vehicle														
	Service Yard														
Loading	2	2	1	2	2	2	2	2	2	2	2	1	1	50%	
Total		151	130	110	78	67	60	60	35	39	62	66	35	116	77%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Aquarium	A	71	47	39	22	14	17	22	13	19	23	26	13	58	82%
	B														
	S														
	Visitor														
	Reserved														
Allocated	260	255	222	130	118	85	94	102	117	124	140	85	175	67%	
Accessible	9	9	8	8	7	0	0	2	8	6	6	0	9	100%	
UC Vehicle Service Yard Loading															
Total		340	311	269	160	139	102	116	117	144	153	172	102	238	70%
Theatre District	A	8	8	7	7	5	7	8	7	6	6	7	5	3	38%
	B														
	S														
	Visitor														
	Reserved														
Allocated	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
Accessible															
UC Vehicle Service Yard Loading															
Total		10	10	9	9	7	9	10	9	8	8	9	7	3	30%
Revelle College	A	306	233	125	1	0	0	6	6	9	27	49	0	306	100%
	B	424	228	23	0	0	0	3	4	9	40	65	0	424	100%
	S	38	1	0	0	0	0	0	0	0	0	0	0	38	100%
	Visitor	17	11	4	1	1	0	1	3	4	6	9	0	17	100%
	Reserved	12	8	7	7	7	7	6	4	3	3	3	3	9	75%
	Allocated	32	21	18	16	13	7	17	16	13	10	14	7	25	78%
	Accessible	42	24	20	11	11	8	4	6	9	15	22	4	38	90%
	UC Vehicle	6	3	2	3	2	0	0	0	1	0	0	0	6	100%
	Service Yard	26	11	9	6	7	6	5	8	8	8	10	5	21	81%
	Loading	7	5	4	2	3	0	2	1	2	2	4	0	7	100%
Total		910	545	212	47	44	28	44	48	58	111	176	28	882	97%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Muir College	A	56	21	9	1	0	0	0	3	7	1	16	0	56	100%
	B	10	5	1	0	0	0	0	0	0	0	0	0	10	100%
	S														
	Visitor	26	0	0	0	0	0	0	0	0	0	0	0	26	100%
	Reserved	23	18	21	16	5	6	5	6	8	15	18	5	18	78%
	Allocated	57	50	38	5	6	3	3	3	13	12	14	3	54	95%
	Accessible	23	4	2	0	0	0	0	2	4	4	12	0	23	100%
	UC Vehicle	2	0	1	0	0	2	2	1	2	1	2	0	2	100%
	Service Yard	11	26	12	0	1	1	3	1	11	3	14	0	11	100%
	Loading	22	31	22	6	4	2	3	7	20	6	20	2	20	91%
Total	230	155	106	28	16	14	16	23	65	42	96	14	216	94%	
Marshall College	A	214	170	130	59	49	36	41	14	53	58	71	14	200	93%
	B	171	38	1	3	5	0	0	0	9	14	17	0	171	100%
	S														
	Visitor	28	25	8	0	0	1	1	1	12	14	19	0	28	100%
	Reserved	9	5	4	5	6	6	4	4	4	5	5	4	5	56%
	Allocated	5	5	5	2	2	4	2	3	3	3	4	2	3	60%
	Accessible	29	24	20	8	8	8	10	6	8	11	11	6	23	79%
	UC Vehicle														
	Service Yard	7	1	2	1	1	3	3	1	2	2	2	1	6	86%
	Loading	9	7	4	1	1	0	1	2	2	2	4	0	9	100%
Total	472	275	174	79	72	58	62	31	93	109	133	31	441	93%	
Roosevelt College	A	175	140	122	81	0	0	7	12	19	22	28	0	175	100%
	B	819	471	384	123	0	0	19	26	47	56	72	0	819	100%
	S	1003	17	14	0	0	0	0	0	0	3	3	0	1003	100%
	Visitor	240	170	151	119	16	11	21	33	41	51	60	11	229	95%
	Reserved	19	13	7	9	9	9	10	10	13	13	13	7	12	63%
	Allocated	50	26	26	20	12	13	15	18	23	25	28	12	38	76%
	Accessible	51	35	33	32	22	22	20	23	29	30	32	20	31	61%
	UC Vehicle	21	9	8	8	9	9	4	5	9	8	9	4	17	81%
	Service Yard	8	6	4	4	0	0	2	0	0	4	4	0	8	100%
	Loading	17	14	12	10	7	9	6	10	10	11	13	6	11	65%
Total	2403	901	761	406	75	73	104	137	191	223	262	73	2330	97%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
North Campus	A	24	16	2	0	0	0	0	0	0	3	3	5	0	24	100%
	B	169	93	30	15	12	13	7	0	15	19	24	0	169	100%	
	S															
	Visitor	13	9	7	1	1	1	2	0	2	3	5	0	13	100%	
	Reserved	9	6	4	4	4	3	3	3	3	2	4	2	7	78%	
	Allocated	13	12	10	6	6	6	9	8	6	6	9	6	7	54%	
	Accessible	7	6	6	2	2	3	5	1	2	2	3	1	6	86%	
	UC Vehicle	7	0	0	0	0	1	2	1	1	1	1	0	7	100%	
	Service Yard	2	2	0	1	1	0	1	0	0	0	1	0	2	100%	
	Loading	0	0	0	0	0	0	0	0	0	0	0	0	0	#DIV/0!	
Total	244	144	59	29	26	27	29	13	32	36	52	13	231	95%		
North Torrey Pines and Glider Port	A															
	B	711	371	262	168	170	179	175	179	226	281	351	168	543	76%	
	S	407	365	304	280	222	198	185	217	212	221	230	185	222	55%	
	Visitor	249	196	148	64	44	24	17	47	67	71	163	17	232	93%	
	Reserved	20	18	17	17	17	17	18	20	20	20	20	17	3	15%	
	Allocated	86	26	18	13	17	20	14	22	23	27	33	13	73	85%	
	Accessible	24	21	20	15	16	15	16	16	15	17	18	15	9	38%	
	UC Vehicle	22	4	7	4	7	5	6	4	7	8	8	4	18	82%	
	Service Yard	1	0	0	0	0	0	0	0	0	0	1	0	1	100%	
	Loading	11	7	4	4	4	4	4	1	6	5	7	1	10	91%	
Total	1531	1008	780	565	497	462	435	506	576	650	831	435	1096	72%		
Warren College	A	157	120	76	16	2	0	3	13	15	33	76	0	157	100%	
	B	216	89	13	0	0	0	4	3	4	19	30	0	216	100%	
	S	29	0	0	0	0	0	0	1	0	0	0	0	29	100%	
	Visitor	31	9	8	0	1	0	2	2	3	3	4	0	31	100%	
	Reserved	60	51	39	29	26	30	30	29	35	32	37	26	34	57%	
	Allocated															
	Accessible	28	13	4	0	0	0	0	0	1	1	12	0	28	100%	
	UC Vehicle															
	Service Yard	9	6	6	4	4	2	2	2	3	4	4	2	7	78%	
	Loading	12	9	8	3	1	0	0	3	3	3	5	0	12	100%	
Total	542	297	154	52	34	32	41	53	64	95	168	32	510	94%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces									At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Campus Services Complex	A	29	-	5	0	1	0	1	0	3	3	7	0	29	100%
	B	217	-	9	7	2	2	4	11	20	25	41	2	215	99%
	S														
	Visitor	25	-	13	4	7	7	2	5	4	4	4	2	23	92%
	Reserved	0	-	0	0	0	0	0	0	0	0	0	0	0	#DIV/0!
	Allocated	24	-	16	11	12	11	9	10	8	9	11	8	16	67%
	Accessible	9	-	2	2	3	3	3	3	4	4	4	2	7	78%
	UC Vehicle	129	-	64	47	64	53	57	45	43	38	34	34	95	74%
	Service Yard	8	-	0	2	1	1	1	1	0	2	2	0	8	100%
	Loading	8	-	1	4	4	3	0	2	2	3	3	0	8	100%
Total	449	0	110	77	94	80	77	77	84	88	106	0	449	100%	
Sixth College	A	408	342	212	62	54	32	32	48	65	85	112	32	376	92%
	B	234	7	0	0	0	1	4	3	13	26	43	0	234	100%
	S	85	0	0	0	0	0	0	0	0	0	0	0	85	100%
	Visitor	239	172	130	65	33	8	25	28	32	70	112	8	231	97%
	Reserved	12	7	4	3	5	8	8	8	8	8	9	3	9	75%
	Allocated	64	56	39	35	28	25	23	30	27	32	38	23	41	64%
	Accessible	30	8	7	6	4	4	4	4	9	11	17	4	26	87%
	UC Vehicle	18	6	5	5	5	6	7	7	4	4	5	4	14	78%
	Service Yard	5	1	2	2	2	2	2	3	3	3	3	1	4	80%
	Loading	12	8	5	7	5	6	5	3	5	9	7	3	9	75%
Total	1107	607	404	185	136	92	110	134	166	248	346	92	1015	92%	
School of Medicine	A	423	111	28	12	5	5	9	16	22	53	82	5	418	99%
	B	556	0	0	0	0	2	3	13	28	166	266	0	556	100%
	S	428	2	1	0	0	0	0	7	13	18	65	0	428	100%
	Visitor	90	55	37	10	10	18	18	20	21	22	27	10	80	89%
	Reserved	141	111	103	81	76	78	84	72	78	91	108	72	69	49%
	Allocated	125	70	40	12	10	18	20	16	19	32	42	10	115	92%
	Accessible	69	38	33	20	15	17	18	18	22	22	35	15	54	78%
	UC Vehicle	24	12	13	11	11	8	7	6	7	7	11	6	18	75%
	Service Yard	12	3	3	2	2	4	4	3	4	3	4	2	10	83%
	Loading	11	11	4	1	2	2	8	7	5	4	1	1	10	91%
Total	1879	413	262	149	131	152	171	178	219	418	641	131	1748	93%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
University Center	A	90	8	1	1	0	2	3	3	0	5	7	0	90	100%
	B	22	0	0	0	0	0	0	0	0	0	0	0	22	100%
	S														
	Visitor	19	8	0	3	0	1	0	2	0	0	6	0	19	100%
	Reserved	81	78	61	44	42	39	41	43	44	44	53	39	42	52%
	Allocated	33	19	17	11	11	11	13	15	13	16	20	11	22	67%
	Accessible	37	23	10	4	2	0	2	1	3	7	16	0	37	100%
	UC Vehicle	3	2	2	0	1	1	1	2	2	2	2	0	3	100%
	Service Yard	12	3	5	6	6	5	6	5	6	7	8	3	9	75%
	Loading	3	3	3	2	2	2	2	1	2	2	2	1	2	67%
Total	300	144	99	71	64	61	68	72	70	83	114	61	239	80%	
East Campus Academic	A														
	B	424	392	180	103	51	40	45	53	76	104	160	40	384	91%
	S	1019	821	550	501	377	251	219	232	251	518	524	219	800	79%
	Visitor														
	Reserved	14	1	0	0	0	0	0	0	0	0	0	0	14	100%
	Allocated	92	63	39	31	20	29	38	42	43	46	66	20	72	78%
	Accessible	16	4	5	6	6	6	6	6	6	5	5	4	12	75%
	UC Vehicle	10	8	2	2	4	5	6	7	7	8	8	2	8	80%
	Service Yard														
Loading	5	5	3	2	2	2	2	2	2	2	2	2	3	60%	
Total	1580	1294	779	645	460	333	316	342	385	683	765	316	1264	80%	
Health Sciences	A	528	179	128	89	78	82	80	94	105	140	173	78	450	85%
	B	1296	331	148	35	22	33	57	88	147	199	269	22	1274	98%
	S														
	Visitor	951	417	277	124	88	145	149	161	206	239	283	88	863	91%
	Reserved	103	68	63	58	59	60	56	58	52	56	61	52	51	50%
	Allocated	203	27	25	15	18	24	27	25	23	26	33	15	188	93%
	Accessible	181	73	38	24	20	41	33	34	40	47	57	20	161	89%
	UC Vehicle	15	2	2	3	2	5	5	4	4	3	4	2	13	87%
	Service Yard	14	2	1	0	2	1	2	2	3	4	5	0	14	100%
	Loading	22	9	7	1	7	10	8	8	8	10	11	1	21	95%
Total	3313	1108	689	349	296	401	417	474	588	724	896	296	3017	91%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Neighborhood

Neighborhood	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
Science Research Park	A	462	18	0	0	0	0	0	0	0	0	0	0	0	462	100%
	B	243	211	208	207	209	206	203	198	193	173	171	171	72	30%	
	S															
	Visitor															
	Reserved	12	11	8	0	0	2	3	2	2	2	2	0	12	100%	
	Allocated	26	6	6	2	5	6	6	6	5	6	5	2	24	92%	
	Accessible															
	UC Vehicle Service Yard Loading															
Total	743	246	222	209	214	214	212	206	200	181	178	178	565	76%		
Medical Center Hillcrest	A	263	150	105	82	77	78	74	69	92	108	131	69	194	74%	
	B	1227	450	354	305	280	284	222	257	310	463	682	222	1005	82%	
	S															
	Visitor	365	243	199	172	153	176	178	163	168	209	235	153	212	58%	
	Reserved	95	76	63	60	50	55	53	44	55	65	68	44	51	54%	
	Allocated	121	99	83	89	79	81	74	75	78	70	81	70	51	42%	
	Accessible	54	17	12	9	12	11	12	7	11	15	20	7	47	87%	
	UC Vehicle	16	4	2	7	11	9	8	3	3	2	4	2	14	88%	
	Service Yard	13	0	0	3	2	2	2	4	1	2	3	0	13	100%	
Loading	13	3	1	1	4	3	3	2	2	4	5	1	12	92%		
Total	2167	1042	819	728	668	699	626	624	720	938	1229	624	1543	71%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P001	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	1	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: SIO V1G	1	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
Allocated: EV	4	3	2	1	1	1	2	3	3	3	3	3	1	3	75%	
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle	1	1	0	1	1	0	0	1	1	1	1	1	0	1	100%	
Service Yard Loading																
Total		7	6	2	2	2	1	2	4	4	4	4	1	6	86%	
P002	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: SIO	31	30	28	13	13	6	4	2	1	1	3	3	1	30	97%
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle	2	2	2	0	0	1	1	0	0	1	1	1	0	2	100%	
Service Yard Loading																
Total		33	32	30	13	13	7	5	2	1	2	4	1	32	97%	
P003	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: LG	1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
Allocated: SIO	64	49	33	6	5	0	0	1	6	6	7	7	0	64	100%	
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle	2	1	1	0	0	1	1	0	1	1	1	1	0	2	100%	
Service Yard Loading																
Loading	2	1	1	0	0	0	0	0	1	1	1	1	0	2	100%	
Total		69	52	36	7	6	2	2	2	9	9	10	2	67	97%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P004	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: EV	1	1	1	1	1	1	0	1	1	1	1	0	1	100%	
	Allocated: UCC	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle	5	2	2	2	2	1	1	2	3	3	3	1	4	80%		
Service Yard	1	0	1	1	1	1	1	1	1	0	1	0	1	100%		
Loading: C20m	2	1	1	1	1	1	1	1	1	1	1	1	1	1	50%	
Loading	3	2	2	2	2	2	2	2	3	3	3	2	1	33%		
Total		13	6	7	7	7	6	5	7	9	8	9	5	8	62%	
P005 under construction	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total																
P006	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: SIO	13	10	2	0	0	0	0	0	0	0	0	0	13	100%	
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		13	10	2	0	0	0	0	0	0	0	0	0	13	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak				
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
P007	A																
	B																
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated: SIO	26	10	18	0	0	0	0	0	0	0	3	3	0	26	100%	
	Allocated: UCC	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%	
	Allocated: EV	4	2	2	2	2	0	0	0	1	1	1	0	4	100%		
	Allocated:																
	Allocated:																
	Accessible	2	1	1	1	1	0	0	0	1	1	1	0	2	100%		
	UC Vehicle	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Service Yard	2	1	1	0	0	0	0	0	0	0	0	0	2	100%			
Loading	1	1	1	1	0	1	1	1	1	1	1	0	1	100%			
Loading: Dock	1	0	1	0	0	0	0	0	0	1	0	0	1	100%			
Total	39	15	23	4	3	1	1	1	3	6	6	1	38	97%			
P008	A																
	B																
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated: SIO	26	2	0	0	0	0	0	0	3	6	0	0	26	100%		
	Allocated:																
	Allocated:																
	Allocated:																
Accessible	2	1	1	1	1	0	0	0	1	1	1	0	2	100%			
UC Vehicle																	
Service Yard																	
Loading	1	0	1	0	0	0	0	0	0	0	0	0	1	100%			
Total	29	3	2	1	1	0	0	0	4	7	1	0	29	100%			
P009	A																
	B																
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated:																
	Allocated:																
	Allocated:																
	Allocated:																
Accessible																	
UC Vehicle																	
Service Yard	2	0	1	2	2	2	2	2	2	2	2	0	2	100%			
Loading																	
Total	2	0	1	2	2	2	2	2	2	2	2	0	2	100%			

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P010	A	20												0	20	100%
	B															
	S															
	Visitor: Reserved															
P010	Allocated: SIO	1	16	7	0	0	0	0	2	2	3	3	0	1	100%	
	Allocated:															
	Allocated:															
	Allocated:															
P010	Accessible UC Vehicle Service Yard Loading	1	1	0	0	0	0	0	0	0	0	0	0	1	100%	
	Total		21	17	7	0	0	0	0	2	2	3				3
P011	A	28	19	17	12	11	10	8	9	11	11	11	8	20	71%	
	B															
	S															
	Visitor: Reserved															
P011	Allocated: CA	4	3	1	0	0	2	3	3	3	3	3	0	4	100%	
	Allocated:															
	Allocated:															
	Allocated:															
P011	Accessible UC Vehicle Service Yard Loading	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
	Total		36	26	22	16	14	16	15	16	18	18				18
P012	A	12	11	9	2	2	1	1	2	3	3	3	1	11	92%	
	B															
	S															
	Visitor: Reserved															
P012	Allocated:	1	1	1	0	0	1	1	1	1	1	1	0	1	100%	
	Allocated:															
	Allocated:															
	Allocated:															
P012	Accessible UC Vehicle Service Yard Loading	1	1	1	0	0	1	1	1	1	1	1	0	1	100%	
	Total		13	12	10	2	2	2	2	3	4	4				4

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P013	A	12	11	5	0	0	1	3	1	1	1	2	0	12	100%	
	B															
	S															
	Visitor: Reserved															
	Allocated: EV		2	1	0	0	0	0	0	0	0	0	0	0	2	100%
Allocated:																
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle Service Yard Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%		
Total		15	13	6	1	1	2	4	2	2	2	3	1	14	93%	
P014	A	69	59	52	33	32	29	25	2	5	25	27	2	67	97%	
	B	26	23	18	12	10	10	12	12	12	13	14	10	16	62%	
	S	4	4	4	3	3	3	2	2	2	3	3	2	2	50%	
	Visitor: Parkmobile															
	Visitor: Reserved															
	Allocated: EV	2	2	1	2	2	2	2	2	2	2	2	1	1	50%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible UC Vehicle Service Yard Loading	4	4	4	4	4	3	3	3	3	3	3	3	1	25%		
Total		105	92	79	54	51	47	44	21	24	46	49	21	84	80%	
P015	A															
	B															
	S															
	Visitor:															
	Visitor: Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible UC Vehicle Service Yard Loading	2	2	1	2	2	2	2	2	2	2	2	1	1	50%		
Total		2	2	1	2	2	2	2	2	2	2	2	1	1	50%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P016	A	42	34	28	20	12	9	12	10	11	12	13	9	33	79%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible	2	2	2	2	2	2	2	2	2	2	2	2	0	0%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	44	36	30	22	14	11	14	12	13	14	15	11	33	75%
P017	A	258	253	222	130	118	85	94	102	116	123	139	85	173	67%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated: BA														
	Allocated: EV	2	2	0	0	0	0	0	0	1	1	1	0	2	100%
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible	9	9	8	8	7	0	0	2	8	6	6	0	9	100%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	269	264	230	138	125	85	94	104	125	130	146	85	184	68%
P021	A	71	47	39	22	14	17	22	13	19	23	26	13	58	82%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	71	47	39	22	14	17	22	13	19	23	26	13	58	82%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P101	A															
	B															
	S															
	Visitor: Reserved	2	1	1	1	1	1	1	1	1	1	1	1	1	1	50%
	Allocated: Allocated: Allocated: Allocated:	10	0	0	0	0	0	0	0	0	3	4	5	0	10	100%
Accessible UC Vehicle Service Yard Loading	2	2	0	2	2	0	0	1	1	1	2	0	2	100%		
Total		14	3	1	3	3	1	1	2	5	6	8	1	13	93%	
P102	A	347	228	23	0	0	0	2	2	5	23	36	0	347	100%	
	B	38	1	0	0	0	0	0	0	0	0	0	0	38	100%	
	S															
	Visitor: Visitor: Reserved															
	Allocated: LJP	6	6	6	5	3	1	4	4	3	4	3	1	5	83%	
	Allocated: SCP	9	9	8	5	4	1	5	4	2	2	4	1	8	89%	
	Allocated: Allocated: Allocated:															
	Accessible UC Vehicle	10	10	9	9	9	8	4	3	4	6	8	3	7	70%	
	Service Yard	4	3	3	1	2	1	1	1	1	1	1	1	3	75%	
	Loading															
Total		414	257	49	20	18	11	16	14	15	36	52	11	403	97%	
P103	A	296	233	125	1	0	0	6	6	9	27	49	0	296	100%	
	B	77	0	0	0	0	0	1	2	4	17	29	0	77	100%	
	S															
	Visitor: Parkmobile	12	7	3	0	0	0	1	0	1	2	4	0	12	100%	
	Visitor: Reserved	9	6	5	5	5	5	4	2	1	1	1	1	8	89%	
	Allocated: EV	2	1	0	0	0	0	1	1	0	0	1	0	2	100%	
	Allocated: ZIP	4	2	2	2	2	2	3	2	2	2	3	2	2	50%	
	Allocated: Allocated: Allocated:															
	Accessible UC Vehicle	19	14	9	2	2	0	0	2	1	4	7	0	19	100%	
	Service Yard	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
	Loading	4	3	3	0	1	0	2	0	1	0	1	0	4	100%	
Total		424	266	147	10	10	7	18	15	19	53	95	7	417	98%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P105	A															
	B															
	S															
	Visitor: Reserved Allocated: RIB Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	8	8	7	7	5	7	8	7	6	6	7	5	3	38%	
		2	2	2	2	2	2	2	2	2	2	2	0	0%		
Total		10	10	9	9	7	9	10	9	8	8	9	7	3	30%	
P106	A															
	B															
	S															
	Visitor: Parkmobile Visitor: Reserved Accessible Allocated: Allocated: Allocated: Allocated: Allocated: UC Vehicle Service Yard Loading	5	4	1	1	1	0	0	3	3	4	5	0	5	100%	
	1	1	1	1	1	1	1	1	1	1	1	1	0	0%		
	1	0	0	0	0	0	0	0	0	0	1	0	1	100%		
Total		7	5	2	2	2	1	1	4	4	5	7	1	6	86%	
P107	A															
	B															
	S															
	Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	2	0	1	2	2	2	2	2	2	2	2	0	2	100%	
	1	0	1	0	0	0	0	0	0	1	1	0	1	100%		
Total		3	0	2	2	2	2	2	2	2	3	3	0	3	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P108	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible	2	0	2	0	0	0	0	1	1	1	1	0	2	100%		
UC Vehicle	4	3	2	3	2	0	0	0	1	0	0	0	4	100%		
Service Yard	11	6	3	3	3	3	2	4	3	4	5	2	9	82%		
Loading																
Total		17	9	7	6	5	3	2	5	5	5	6	2	15	88%	
P110 under construction	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total																
P111	A	10	0	0	0	0	1	0	0	0	0	0	0	10	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		10	0	0	0	0	1	0	0	0	0	0	0	10	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P112	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	8	2	2	0	0	0	0	1	2	1	2	0	8	100%
	Total	8	2	2	0	0	0	0	1	2	1	2	0	8	100%
P113	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	26	21	10	0	0	0	2	0	5	0	4	0	26	100%
	2	1	0	0	0	0	0	0	1	0	2	0	2	100%	
	1	0	0	0	0	0	0	0	1	0	1	0	1	100%	
	Total	29	22	10	0	0	0	2	0	7	0	7	0	29	100%
P114	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	2	1	1	0	0	0	0	0	2	2	2	0	2	100%
	2	0	1	0	0	0	0	2	2	2	2	0	2	100%	
	Total	4	1	2	0	0	0	0	2	4	4	2	0	4	100%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P116	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: CAT	5	2	2	2	3	1	3	3	5	2	3	1	4	80%	
Allocated: HDH	5	1	0	1	0	1	1	2	1	0	0	0	5	100%		
Allocated: V0796	1	0	0	1	1	1	0	0	0	0	0	0	1	100%		
Allocated:																
Allocated:																
Accessible																
UC Vehicle	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Service Yard																
Loading																
Total		13	3	2	4	4	3	4	5	6	2	3	2	11	85%	
P201	A	11	0	1	0	0	0	0	0	2	0	5	0	11	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
Allocated:																
Allocated:																
Allocated:																
Accessible	3	0	0	0	0	0	0	2	0	0	2	0	3	100%		
UC Vehicle																
Service Yard																
Loading	8	2	4	2	3	0	0	4	3	0	4	0	8	100%		
Total		22	2	5	2	3	0	0	6	5	0	11	0	22	100%	
P202	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
Allocated:																
Allocated:																
Allocated:																
Accessible	3	0	1	0	0	0	0	0	1	1	2	0	3	100%		
UC Vehicle	2	0	1	0	0	2	2	1	1	1	1	0	2	100%		
Service Yard	2	1	1	0	1	1	1	1	1	1	2	0	2	100%		
Loading	4	2	2	0	0	1	1	1	2	3	3	0	4	100%		
Total		11	3	5	0	1	4	4	3	5	6	8	0	11	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P203	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	5	1	4	2	2	2	2	1	1	4	4	1	4	80%	
	Total	5	1	4	2	2	2	2	1	1	4	4	1	4	80%	
P204	A B S Visitor: Visitor: Reserved Allocated: HDM Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	2	2	2	1	2	2	2	2	2	2	2	1	1	50%	
	Total	2	2	2	1	2	2	2	2	2	2	2	1	1	50%	
P205	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	4	1	0	0	0	0	0	0	0	0	0	0	4	100%	
	Total	4	1	0	0	0	0	0	0	0	0	0	0	4	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P206	A	22	3	0	0	0	0	0	2	2	0	5	0	22	100%
	3 hr A	20	17	8	1	0	0	0	0	2	1	4	0	20	100%
	3 hr B	10	5	1	0	0	0	0	0	0	0	0	0	10	100%
	S														
	Visitor:														
	Visitor:														
	Reserved	15	15	15	12	2	3	3	3	5	10	12	2	13	87%
	Allocated: EV	2	0	0	2	2	1	1	1	0	0	0	0	2	100%
	Allocated: FC	53	47	36	2	2	0	0	0	10	10	10	0	53	100%
	Allocated:														
	Allocated:														
Accessible	15	3	1	0	0	0	0	0	2	3	6	0	15	100%	
UC Vehicle															
Service Yard															
Loading															
Total		137	90	61	17	6	4	4	6	21	24	37	4	133	97%
P302	A	35	28	17	0	0	0	0	0	5	6	9	0	35	100%
	B	74	19	0	0	0	0	0	0	2	5	6	0	74	100%
	S														
	Visitor:	2	1	1	0	0	0	0	1	1	1	1	0	2	100%
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible	5	5	3	3	3	4	4	4	4	4	4	3	2	40%
UC Vehicle															
Service Yard															
Loading															
Total		116	53	21	3	3	4	4	5	12	16	20	3	113	97%
P303	A	77	63	49	16	10	2	6	2	11	14	20	2	75	97%
	B														
	S														
	Visitor: PAD	26	24	7	0	0	1	1	0	11	13	18	0	26	100%
	Visitor:														
	Reserved	5	3	2	2	2	3	2	1	0	1	1	0	5	100%
	Allocated: ESPP	2	2	2	2	2	2	1	0	1	1	1	0	2	100%
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible	8	8	8	2	2	3	1	0	2	3	4	0	8	100%
UC Vehicle															
Service Yard	2	1	1	1	1	1	1	1	1	1	1	1	1	50%	
Loading	2	2	1	0	0	0	0	0	0	0	1	0	2	100%	
Total		122	103	70	23	17	12	12	4	26	33	46	4	118	97%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak					
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied			
P304	A	72	68	63	43	38	34	33	12	33	35	39	12	60	83%			
	B																	
	S																	
	Visitor:																	
	Visitor:																	
	Reserved																	
Allocated:	2	1	1	0	0	0	1	1	1	2	1	0	2	100%				
Allocated:																		
Allocated:																		
Allocated:																		
Allocated:																		
Accessible UC Vehicle																		
Service Yard	2	0	0	0	0	0	0	0	0	0	0	0	2	100%				
Loading		2	1	1	1	0	1	1	1	1	1				0	2	100%	
Total	78	71	65	44	39	34	35	14	35	38	41	14	64	82%				
P306	A	4	2	0	0	0	1	1	1	2	2	2	0	4	100%			
	B																	
	S																	
	Visitor:																	
	Visitor:																	
	Reserved																	
Allocated:	3	2	1	1	0	0	0	1	1	1	1	0	3	100%				
Allocated:																		
Allocated:																		
Allocated:																		
Allocated:																		
Accessible UC Vehicle																		
Service Yard	3	2	1	1	0	1	1	1	1	1	1	0	3	100%				
Loading		4	1	1	0	1	1	2	2	2	2				0	4	100%	
Total	14	8	3	3	0	3	3	5	6	6	6	0	14	100%				
P308	A	97	19	1	3	5	0	0	0	7	9	11	0	97	100%			
	B																	
	S																	
	Visitor:																	
	Visitor:																	
	Reserved		1	0	1	1	1	1	1	1	1	1				1	0	1
Allocated: CAT	3	3		3	0	0	2	1	3	2	2	3	0	3	100%			
Allocated:																		
Allocated:																		
Allocated:																		
Allocated:																		
Accessible UC Vehicle																		
Service Yard	3	1	0	0	0	0	2	1	1	1	1	0	3	100%				
Loading		2	0	1	0	0	2	2	0	1	1				1	0	3	100%
Total	109		24	7	4	6	5	6	5	13	15	18	4	105	96%			

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P309	A	30	11	1	0	1	0	2	0	4	3	3	0	30	100%
	B														
	S														
	Visitor: Reserved	3	2	1	2	3	2	1	2	3	3	3	1	2	67%
	Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard	9	7	6	2	2	0	1	0	0	1	1	0	9	100%
Loading	1	1	1	0	0	0	0	1	0	0	1	0	1	100%	
Total		43	21	9	4	6	2	4	3	7	7	8	2	41	95%
P310	A														
	B														
	S														
	Visitor: Reserved														
	Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard	2	2	2	1	1	1	1	0	0	0	0	0	2	100%
Loading	2	1	0	0	0	0	0	0	0	0	0	0	2	100%	
Total		4	3	2	1	1	1	1	0	0	0	0	4	100%	
P341	A	228	0	0	0	0	0	0	0	0	0	0	0	228	100%
	B														
	S														
	Visitor: Reserved														
	Allocated: Allocated: Allocated: Allocated: Allocated: Allocated: V2G	2	2	2	1	1	1	1	1	1	1	1	1	1	50%
Accessible UC Vehicle Service Yard	6	1	1	1	1	1	0	0	2	2	2	0	6	100%	
Loading															
Total		236	3	3	2	2	2	1	1	3	3	3	1	235	100%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak																																																																																																																		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied																																																																																																																
P342	A	168	17	14	0	0	0	0	0	0	3	3	0	168	100%																																																																																																																
	B															5	2	2	3	3	3	2	2	3	3	3	2	3	60%																																																																																																		
	S																													1	1	1	1	1	0	0	0	0	0	0	1	100%																																																																																					
	Visitor:																																										10	5	5	4	1	1	1	2	3	3	4	1	9	90%																																																																							
	Visitor: Reserved																																																								3	2	2	2	2	2	2	2	2	2	2	2	1	33%																																																									
	Allocated: HO																																																																						5	3	3	2	1	1	2	2	3	3	3	1	4	80%																																											
	Allocated: EV																																																																																				3	2	2	2	2	2	2	2	2	2	2	2	1	33%																													
	Allocated: TO																																																																																																		3	2	2	2	2	2	2	2	2	2	2	2	1	33%															
	Allocated: V2G																																																																																																																3	2	2	2	2	2	2	2	2	2	2	2	2	1	33%
	Allocated:																																																																																																																														
Accessible	3	3	2	1	1	2	2	3	3	3	3	1	4	80%																																																																																																																	
UC Vehicle															3	3	2	1	1	2	2	3	3	3	3	1	4	80%																																																																																																			
Service Yard																													3	3	2	1	1	2	2	3	3	3	3	1	4	80%																																																																																					
Loading																																											3	3	2	1	1	2	2	3	3	3	3	1	4	80%																																																																							
Total																																																									192	30	27	12	8	8	7	8	11	14	15	7	185	96%																																																									
P343																																																									A	211	0	0	0	0	0	0	0	0	0	0	0	211	100%																																																								
																																																									B															1	0	0	0	0	0	0	0	1	1	0	1	100%																																											
																																																									S																												1	0	0	0	0	0	0	0	1	1	0	1	100%																														
																																																									Visitor:																																									1	0	0	0	0	0	0	0	1	1	0	1	100%																	
																																																									Visitor: Reserved																																																						1	0	0	0	0	0	0	0	1	1	0	1	100%				
	Allocated: EV	1	0	0	0	0	0	0	0	1	1	0	1	100%																																																																																																																	
	Allocated:														1	0	0	0	0	0	0	0	1	1	0	1	100%																																																																																																				
	Allocated:																											1	0	0	0	0	0	0	0	1	1	0	1	100%																																																																																							
	Allocated:																																								1	0	0	0	0	0	0	0	1	1	0	1	100%																																																																										
	Allocated:																																																					1	0	0	0																																																																			0	0	0	0
Accessible	1																																																									0	0	0	0	0	0	0	1	1	0	1	100%																																																										
UC Vehicle																																																																						1	0	0	0	0	0	0	0	1	1	0	1	100%																																													
Service Yard																																																																																			1	0	0	0	0	0	0	0	1	1	0	1	100%																																
Loading																																																																																																1	0	0	0	0	0	0	0	1	1	0	1	100%																			
Total																																																																																																													212	0	0	0	0	0	0	0	0	1	1	0	212	100%					
P344		A	153	123	119	30	0	0	0	0	3	3	6	0																																																																																															153	100%																	
		B													56	0	0	0	0	0	0	0	0	0	0	0	56																																																																																				100%																
		S																										56	0	0	0	0	0	0	0	0	0	0	0	56																																																																								100%															
		Visitor:																																							56	0	0	0	0	0	0	0	0	0	0	0	56																																																												100%														
		Visitor: Reserved																																																				56	0	0	0																																																									0	0	0	0	0	0	0	0	56	100%				
	Allocated:	56																																																								0	0	0	0	0	0	0	0	0	0	0	56																																																							100%			
	Allocated:																																																																					56	0	0	0	0	0	0	0	0	0	0	0	56																																											100%		
	Allocated:																																																																																		56	0	0	0	0	0	0	0	0	0	0	0	56																															100%	
	Allocated:																																																																																															56	0	0	0	0	0	0	0	0	0	0	0	56																			100%
	Accessible																																																																																																																														
UC Vehicle	56		0	0	0	0	0	0	0	0	0	0	0	56																																																																																															100%																		
Service Yard															56	0	0	0	0	0	0	0	0	0	0	0	56																																																																																			100%																	
Loading																												56	0	0	0	0	0	0	0	0	0	0	0	56																																																																							100%																
Total																																									209	123	119	30	0	0	0	0	0	3	3	6	0																																																											209	100%														

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P345	A	197	55	50	24	0	0	7	7	9	11	13	0	197	100%	
	B		4	4	1	0	0	2	3	5	5	6				
	S		1	1	1	1	1	1	1	1	1	1				
	Visitor: Reserved															
	Allocated: SCP															
P346	A	145	61	58	3	0	0	4	6	10	12	14	0	145	100%	
	B		14	12	3	1	0	3	5	6	9	11				
	S		16	12	11	13	9	8	8	8	9	9				10
	Visitor: Reserved															
	Allocated: SCP															
P347	A	84	69	63	32	0	0	5	7	11	13	15	0	84	100%	
	B		26	23	14	0	0	3	5	6	9	11				
	S		2	1	1	0	0	1	1	1	1	1				
	Visitor: PAD															
	Visitor: Reserved															
Total			60	55	26	1	1	10	11	15	17	20	1	209	100%	
Total			87	81	19	10	8	15	19	25	30	35	8	182	96%	
Total			99	90	47	0	0	9	13	19	24	28	0	155	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P351	A	24	16	2	0	0	0	0	0	0	3	3	5	0	24	100%
	B															
	S															
	Visitor:															
	Visitor: Reserved	7	5	3	3	3	2	2	2	2	2	1	3	1	6	86%
	Allocated: EV	3	2	2	2	2	2	2	2	2	2	2	2	2	1	33%
Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading																
Total		34	23	7	5	5	4	4	4	4	7	6	10	4	30	88%
P352	A															
	B															
	S															
	Visitor:															
	Visitor: Reserved															
	Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	1	1	1	1	1	1	1	1	1	1	1	1	1	1	0
Total		1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
P353	A															
	B															
	S															
	Visitor:															
	Visitor: Reserved															
	Allocated: FEV	1	0	0	0	0	0	0	0	0	0	1	1	0	1	100%
Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	4	1	1	2	2	2	1	1	2	2	2	2	1	3	75%	
	1	0	0	0	1	1	0	0	1	1	1	1	0	1	100%	
	13	12	11	9	7	8	5	8	8	8	9	11	5	8	62%	
Total		19	13	12	11	10	11	6	9	11	13	15	6	13	68%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak				
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
P354	A																
	B																
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated:																
	Allocated:																
	Allocated:																
	Allocated:																
Accessible	4	3	3	3	2	3	2	2	2	2	3	3	2	2	50%		
UC Vehicle	2	2	1	0	0	0	0	0	0	0	0	0	0	2	100%		
Service Yard	8	6	4	4	0	0	2	0	0	0	4	4	0	8	100%		
Loading																	
Total		14	11	8	7	2	3	4	2	2	7	7	2	12	86%		
P357	A	120	55	0	0	0	3	0	0	4	6	8	0	120	100%		
	B																
	S																
	Visitor: PAD	13	9	7	1	1	1	2	0	2	3	5	0	13	100%		
	Visitor:																
	Reserved	2	1	1	1	1	1	1	1	1	1	1	1	1	1	50%	
	Allocated: EV	8	8	6	2	2	2	5	4	2	2	5	2	6	75%		
	Allocated: V2G	2	2	2	2	2	2	2	2	2	2	2	2	0	0%		
	Allocated:																
	Allocated:																
Allocated:																	
Accessible	6	5	5	1	1	2	4	0	1	1	2	0	6	100%			
UC Vehicle																	
Service Yard	2	2	0	1	1	0	1	0	0	0	1	0	2	100%			
Loading																	
Total		153	82	21	8	8	11	15	7	12	15	24	7	146	95%		
P358	A																
	B																
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated:																
	Allocated:																
	Allocated:																
	Allocated:																
Accessible																	
UC Vehicle	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%		
Service Yard																	
Loading																	
Total		1	0	0	0	0	0	0	0	0	0	0	0	1	100%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P359	A	49	38	30	15	12	10	7	0	11	13	16	0	49	100%	
	B															
	S															
	Visitor:															
P359	Visitor:	6	0	0	0	0	1	2	1	1	1	1	0	6	100%	
	Reserved															
	Allocated:															
	Allocated:															
P359	Allocated:	55	38	30	15	12	11	9	1	12	14	17	1	54	98%	
	Allocated:															
	Accessible															
	UC Vehicle															
P371	Service Yard	126	0	0	0	0	0	0	0	0	0	0	0	126	100%	
	Loading															
	Total															
	Total															
P371	A	126	0	0	0	0	0	0	0	0	0	0	0	126	100%	
	B															
	S															
	Visitor:															
P371	Visitor:	126	0	0	0	0	0	0	0	0	0	0	0	126	100%	
	Reserved															
	Allocated:															
	Allocated:															
P371	Allocated:	126	0	0	0	0	0	0	0	0	0	0	0	126	100%	
	Allocated:															
	Accessible															
	UC Vehicle															
P371	Service Yard	126	0	0	0	0	0	0	0	0	0	0	0	126	100%	
	Loading															
	Total															
	Total															
P372	A	184	0	0	0	0	0	0	0	0	0	0	0	184	100%	
	B															
	S															
	Visitor:															
P372	Visitor:	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
	Reserved															
	Allocated:															
	Allocated:															
P372	Allocated:	185	1	1	1	1	1	1	1	1	1	1	1	184	99%	
	Allocated:															
	Accessible															
	UC Vehicle															
P372	Service Yard	185	1	1	1	1	1	1	1	1	1	1	1	184	99%	
	Loading															
	Total															
	Total															

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak				
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
P373	A	159 30	153	134	59	0	0	8	11	19	21	26	0 0	159 30	100% 100%		
	B		0	0	0	0	0	0	0	0	0	0					
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated:																
	Allocated:																
	Allocated:																
	Allocated:																
Accessible																	
UC Vehicle																	
Service Yard																	
Loading																	
Total		189	153	134	59	0	0	8	11	19	21	26	0	189	100%		
P374	A	165 10	79	23	7	0	0	0	2	6	9	13	0 3	165 7	100% 70%		
	B																
	S																
	Visitor:																
	Visitor:																
	Reserved																
	Allocated: EV			9	8	8	3	3	4	4	5	5				6	
	Allocated:																
	Allocated:																
	Allocated:																
Accessible																	
UC Vehicle																	
Service Yard																	
Loading																	
Total		175	88	31	15	3	3	4	6	11	14	19	3	172	98%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P375	A	91	71	59	49	0	0	2	5	8	9	13	0	91	100%	
	B															
	S															
	Visitor: PAD	46	42	36	33	13	10	4	8	9	11	11	4	42	91%	
	Visitor: Reserved	8	8	4	6	6	5	6	6	7	7	7	4	4	50%	
	Allocated: COMP															
	Allocated: EV	6	3	3	2	2	3	2	3	4	4	4	2	4	67%	
	Allocated:															
	Allocated:															
	Accessible	5	0	0	0	0	0	3	4	4	4	4	0	5	100%	
UC Vehicle	8	3	4	5	6	5	2	3	4	3	4	2	6	75%		
Service Yard Loading																
Total		164	127	106	95	27	23	19	29	36	38	43	19	145	88%	
P376	A															
	B															
	S															
	Visitor: PAD	99	88	80	69	2	1	11	15	20	22	27	1	98	99%	
	Visitor: Reserved															
	Allocated: ZIP	4	0	1	1	2	2	3	3	3	3	3	0	4	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible	10	10	10	9	7	7	3	4	6	6	7	3	7	70%	
UC Vehicle																
Service Yard Loading																
Total		113	98	91	79	11	10	17	22	29	31	37	10	103	91%	
P381	A	102	71	56	56	55	54	47	48	62	59	53	47	55	54%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
	Allocated: BCP	2	0	0	1	1	1	1	1	1	1	1	1	0	2	100%
	Allocated: BE	1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated: EHS	3	2	2	2	2	2	2	1	1	1	1	1	1	2	67%
	Allocated: ERV	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: PM	2	2	2	2	2	2	2	2	2	2	2	2	0	0	0%
	Allocated: UCEV	6	1	1	1	1	1	1	1	1	1	1	1	1	5	83%
	Accessible	6	5	4	4	4	4	3	3	3	3	3	3	3	3	50%
	UC Vehicle	7	3	3	3	3	3	3	2	2	2	2	2	2	5	71%
Service Yard Loading	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%	
Total		133	87	71	72	71	70	62	61	75	72	66	61	72	54%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P382	A	275	109	87	48	58	67	60	72	80	92	110	48	227	83%
	B	4	3	3	3	2	1	1	3	3	3	3	1	3	75%
	S	9	6	7	8	4	2	1	1	3	3	3	1	8	89%
	Visitor:														
	Visitor:														
	Reserved	2	1	1	1	1	1	1	2	2	2	2	1	1	50%
	Allocated: BCP	6	5	4	5	4	5	5	5	5	5	5	4	2	33%
	Allocated: ERV	1	1	0	0	0	0	0	0	0	0	1	0	1	100%
	Allocated: EV	10	8	7	0	5	7	0	7	7	7	7	0	10	100%
	Allocated:														
	Allocated:														
	Accessible UC Vehicle Service Yard Loading	4	2	2	0	2	2	3	2	2	2	3	0	4	100%
	Total		311	135	111	65	77	86	71	90	102	114	134	65	246
P383	A														
	B														
	S														
	Visitor:	8	3	3	2	0	2	1	3	4	5	6	0	8	100%
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible UC Vehicle Service Yard Loading	1	1	1	1	0	1	1	1	1	1	1	0	1	100%
Total		28	7	10	6	6	6	5	7	12	14	15	5	23	82%
P384	A	134	113	70	42	36	31	30	34	40	65	91	30	104	78%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated: SCRM	52	5	0	0	0	0	0	3	5	8	13	0	52	100%
	Allocated:														
	Allocated:														
	Accessible UC Vehicle Service Yard Loading														
Total		186	118	70	42	36	31	30	37	45	73	104	30	156	84%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak																
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied														
P385	A	222	182	134	54	39	20	15	43	60	63	152	15	207	93%														
	B																												
	S																												
	Visitor: PBS																												
	Visitor: Reserved															6	6	6	6	6	6	6	6	6	6	6	6	6	0
Allocated:	10	10	10	8	8	6	7	8	7	8	9	6	4	40%															
Allocated:																													
Allocated:																													
Allocated:																													
Accessible UC Vehicle Service Yard Loading	10	10	10	8	8	6	7	8	7	8	9	6	4	40%															
Total		238	198	150	68	53	32	28	57	73	77	167	28	210	88%														
P386	A	398	361	300	277	219	195	183	216	208	217	226	183	215	54%														
	B																												
	S																												
	Visitor:																												
	Visitor: Reserved																												
Allocated:																													
Allocated:																													
Allocated:																													
Allocated:																													
Allocated:																													
Accessible UC Vehicle Service Yard Loading	398	361	300	277	219	195	183	216	208	217	226	183	215	54%															
Total		398	361	300	277	219	195	183	216	208	217	226	183	215	54%														
P391	A	18	0	0	0	0	2	0	0	0	0	5	0	18	100%														
	B																												
	S																												
	Visitor:																												
	Visitor: Reserved															7	6	5	5	5	6	6	7	7	7	7	5	2	29%
	Allocated:															3	3	3	2	2	2	2	2	2	3	2	2	1	33%
	Allocated:																												
Allocated:																													
Allocated:																													
Accessible UC Vehicle Service Yard	1	0	0	0	0	0	0	0	0	0	0	1	0	1	100%														
Oversized Loading	5	4	2	2	0	3	3	0	3	2	4	0	5	100%															
Loading	1	1	0	0	2	0	1	0	1	1	1	0	1	100%															
Total		34	14	10	9	9	13	12	9	13	13	20	9	25	74%														

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak					
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied				
P392	A	80	4	0	0	0	2	3	1	5	10	15	0	80	100%				
	B																		
	S																		
	Visitor: Reserved																		
	Allocated: ACP		1	1	1	1	1	1	1	0	0	1				1	0	1	100%
Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading																			
Total		81	5	1	1	1	3	4	1	5	11	16	1	80	99%				
P393	A	39	16	3	0	0	7	5	2	9	15	29	0	39	100%				
	B		5	1	1	0	0	1	1	0	1	1				1	0	5	100%
	S																		
	Visitor: Visitor: Reserved																		
	Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading																		
Total		44	17	4	0	0	8	6	2	10	16	30	0	44	100%				
P394	A	62	58	46	22	21	16	30	22	30	40	47	16	46	74%				
	B																		
	S																		
	Visitor: Visitor: Reserved																		
	Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading																		
Total		62	58	46	22	21	16	30	22	30	40	47	16	46	74%				

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P395	A	1	0	0	0	0	0	0	0	0	0	1	0	1	100%
	B														
	S														
	Visitor:	10	5	4	0	1	0	0	0	0	0	2	0	10	100%
	Visitor:														
	Reserved	3	3	3	3	3	2	3	3	3	3	3	2	1	33%
	Allocated: VP	1	0	0	0	0	0	1	1	0	0	0	0	1	100%
	Allocated:														
	Allocated:														
	Allocated:														
Accessible UC Vehicle Service Yard Loading															
Total		15	8	7	3	4	2	4	4	3	3	6	2	13	87%
P401	A														
	B														
	S	85	0	0	0	0	0	0	0	0	0	0	0	85	100%
	Visitor:	2	0	1	1	1	2	2	2	2	2	1	0	2	100%
	Visitor:														
	Reserved														
	Allocated: SCP	9	8	7	7	5	5	5	3	4	4	5	3	6	67%
	Allocated:														
	Allocated:														
	Allocated:														
Accessible UC Vehicle Service Yard Loading	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
Total		97	9	9	9	7	8	8	6	7	7	7	6	91	94%
P402	A	4	3	3	3	3	2	3	2	4	4	4	2	2	50%
	B														
	S														
	Visitor:	3	2	2	2	1	1	1	1	1	1	0	0	3	100%
	Visitor:														
	Reserved	4	2	1	1	1	1	1	1	1	1	2	1	3	75%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
Accessible UC Vehicle Service Yard Loading	3	1	1	1	1	1	1	1	2	2	3	1	2	67%	
UC Vehicle	2	1	1	1	1	1	2	2	0	0	0				
Service Yard	2	0	1	1	1	1	0	1	1	1	1	0	2	100%	
Loading	8	4	3	5	3	4	4	2	5	6	5	2	6	75%	
Total		26	13	12	14	11	11	12	10	14	15	15	10	16	62%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P403 Closed For Construction	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: EV															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total															
P404 Closed For Construction	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total															
P405	A	23	1	0	0	0	0	1	0	0	2	4	0	23	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	20	26	22	8	9	8	8	9	8	7	9	7	13	65%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible	7	1	1	0	0	0	0	0	0	0	3	0	7	100%	
	UC Vehicle															
	Service Yard															
	Loading															
	Total	50	28	23	8	9	8	9	9	8	9	16	8	42	84%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P406a	A	93	1	0	0	0	0	2	3	7	11	15	0	93	100%	
	B		0	0	0	0	1	1	1	1	1	1				
	S		0	0	0	0	0	0	0	0	1	1				
	Visitor:		2	2	2	2	2	1	1	0	2	2				
	Visitor:		2	2	2	2	2	1	1	0	2	2				
Reserved	2	0	0	0	0	1	1	1	1	1	1	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	1	1	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	1	1	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	1	1	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	1	1	0	2	100%		
Accessible UC Vehicle	2	0	0	0	0	0	0	0	0	1	1	0	2	100%		
Service Yard	2	2	2	2	2	2	1	1	0	2	2	0	2	100%		
Loading	2	2	2	2	2	2	1	1	0	2	2	0	2	100%		
Total		99	3	2	2	2	3	4	5	8	15	19	2	97	98%	
P406b	A	18	3	0	0	0	1	2	0	4	7	11	0	18	100%	
	B		0	0	0	0	0	0	0	0	0	0				
	S		0	0	0	0	0	0	0	0	0	0				
	Visitor:		2	2	0	0	0	0	0	0	1	0				
	Visitor:		2	2	0	0	0	0	0	0	1	0				
Reserved	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Allocated:	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Accessible UC Vehicle	2	0	0	0	0	0	0	0	0	0	0	0	2	100%		
Service Yard	2	2	0	0	0	0	0	0	0	1	0	0	2	100%		
Loading	2	2	0	0	0	0	0	0	0	1	0	0	2	100%		
Total		22	5	0	0	0	1	2	0	4	8	11	0	22	100%	
P407	A	3	0	1	0	0	0	0	0	0	0	2	0	3	100%	
	B		0	0	0	0	0	0	0	0	0	0				
	S		0	0	0	0	0	0	0	0	0	0				
	Visitor:		2	2	2	2	2	2	2	2	2	2				
	Visitor:		2	2	2	2	2	2	2	2	2	2				
Reserved	2	2	2	2	2	2	2	2	2	2	2	2	0	0%		
Allocated:	1	1	1	0	0	0	0	0	0	1	1	3	18	86%		
Allocated: ACP	1	1	1	0	0	0	0	0	0	1	1	3	18	86%		
Allocated: BCP	21	11	8	3	3	4	4	5	6	7	9	0	2	100%		
Allocated: RA	2	2	1	1	2	0	1	2	2	2	2	0	2	100%		
Allocated:	2	2	1	1	2	0	1	2	2	2	2	0	2	100%		
Allocated:	2	2	1	1	2	0	1	2	2	2	2	0	2	100%		
Accessible UC Vehicle	2	2	2	2	2	2	2	2	2	2	2	2	0	0%		
Service Yard	3	0	1	0	0	0	0	0	0	0	2	0	3	100%		
Loading	3	0	1	0	0	0	0	0	0	0	2	0	3	100%		
Total		3	0	1	0	0	0	0	0	0	0	2	0	3	100%	
P408	A	2	2	2	2	2	2	2	2	2	2	2	2	0	0%	
	B		1	1	1	0	0	0	0	0	1	1				
	S		21	11	8	3	3	4	4	5	6	7				9
	Visitor:		2	2	1	1	2	0	1	2	2	2				2
	Visitor:		2	2	1	1	2	0	1	2	2	2				2
Reserved	2	2	2	2	2	2	2	2	2	2	2	2	0	0%		
Allocated: ACP	1	1	1	0	0	0	0	0	0	1	1	3	18	86%		
Allocated: BCP	21	11	8	3	3	4	4	5	6	7	9	0	2	100%		
Allocated: RA	2	2	1	1	2	0	1	2	2	2	2	0	2	100%		
Allocated:	2	2	1	1	2	0	1	2	2	2	2	0	2	100%		
Allocated:	2	2	1	1	2	0	1	2	2	2	2	0	2	100%		
Accessible UC Vehicle	2	2	2	2	2	2	2	2	2	2	2	2	0	0%		
Service Yard	3	0	1	0	0	0	0	0	0	0	2	0	3	100%		
Loading	3	0	1	0	0	0	0	0	0	0	2	0	3	100%		
Total		3	0	1	0	0	0	0	0	0	0	2	0	3	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
	Service Yard	1	0	0	0	0	1	1	0	1	1	1	0	1	100%
	Loading	1	1	1	0	1	0	1	0	1	1	1	0	1	100%
	Total	28	17	13	6	8	7	9	9	12	14	16	6	22	79%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P410	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	3	3	3	3	3	3	3	3	3	3	3	3	3	0	0%
	Allocated: HM	2	0	2	1	0	1	2	2	0	0	1	1	0	2	100%
	Allocated:															
	Allocated:															
	Allocated:															
Accessible	1	1	0	0	0	0	0	0	0	0	1	1	0	1	100%	
UC Vehicle	2	1	1	0	0	0	0	1	1	1	1	1	0	2	100%	
Service Yard	2	1	0	1	0	0	1	1	0	1	1	0	0	2	100%	
Loading	2	2	2	2	1	2	1	1	1	1	1	1	1	1	50%	
Total		12	8	8	7	4	6	7	8	5	7	7	4	8	67%	
P411	A	9	7	1	1	0	2	2	3	0	3	3	0	9	100%	
	B															
	S															
	Visitor: PAD	19	8	0	3	0	1	0	2	0	0	6	0	19	100%	
	Visitor:															
	Reserved	15	15	14	12	12	10	11	12	13	13	13	10	5	33%	
	Allocated: EV															
	Allocated: V2G	1	0	0	0	0	0	0	1	1	1	1	0	1	100%	
	Allocated:															
	Allocated:															
Accessible	12	9	2	0	0	0	1	0	0	0	3	0	12	100%		
UC Vehicle	1	1	1	0	1	1	1	1	1	1	1	0	1	100%		
Service Yard																
Loading																
Total		57	40	18	16	13	14	15	19	15	18	27	13	44	77%	
P412	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	35	28	18	18	15	14	15	15	15	16	20	14	21	60%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible	5	2	2	1	1	0	0	1	1	2	3	0	5	100%		
UC Vehicle																
Service Yard																
Loading																
Total		40	30	20	19	16	14	15	16	16	18	23	14	26	65%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak						
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied				
P413	A	1												0	1	100%			
	B																		
	S																		
	Visitor:																		
Reserved		0	0	0	0	0	0	0	0	0	0	1							
Allocated:																			
Allocated:																			
Allocated:																			
Allocated:																			
Accessible	2	2	1	1	0	0	1	0	0	1	1	0	2	100%					
UC Vehicle																			
Service Yard																			
Loading																			
Total		3	2	1	1	0	0	1	0	0	1	2	0	3	100%				
P414	A	3	1	0	0	0	0	0	1	1	0	2	0	3	100%				
	B																		
	S																		
	Visitor:																		
	Visitor:																		
	Reserved		3	2	2	2	1	1	0	2	2	1				2	0	3	100%
	Allocated:																		
Allocated:																			
Allocated:																			
Allocated:																			
Accessible	3	1	0	0	0	0	0	0	0	0	2	0	3	100%					
UC Vehicle																			
Service Yard																			
Loading	7	5	5	4	1	1	0	0	5	1	3	0	7	100%					
Total		16	9	7	6	2	2	0	3	8	2	9	0	16	100%				
P415	A	2											1	1	50%				
	B																		
	S																		
	Visitor:																		
	Visitor:																		
	Reserved			1	1	1	1	2	2	2	1	1				2			
	Allocated: SHAS		1	1	1	1	1	1	1	1	1	1				1	1	0	0%
	Allocated: SHP		5	4	4	5	5	5	5	4	3	4				5	3	2	40%
	Allocated:																		
Allocated:																			
Allocated:																			
Accessible	1	0	0	0	0	0	0	0	0	0	1	0	1	100%					
UC Vehicle																			
Service Yard																			
Loading																			
Total		9	6	6	7	7	8	8	7	5	6	9	5	4	44%				

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P416	A	58					VALET									
	B	22					VALET									
	S															
	Visitor: Reserved	3	3	1	0	0	0	0	0	0	2	2	3	0	3	100%
	Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	4	3	2	1	0	0	0	0	0	1	2	3	0	4	100%
Total		87	6	3	1	0	0	0	0	0	3	4	6	0	87	100%
P418	A															
	B															
	S															
	Visitor: Reserved															
	Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	6	3	0	0	0	0	0	0	0	0	0	2	0	6	100%
	1	0	0	0	0	0	0	0	0	0	0	0	0	1	100%	
Total		7	3	0	0	0	0	0	0	0	0	0	2	0	7	100%
P451	A															
	B															
	S															
	Visitor: PAD	100	54	31	18	2	2	7	0	8	11	16	0	100	100%	
	Visitor: Reserved	3	3	1	0	1	3	3	3	3	3	3	0	3	100%	
	Allocated: CUS	10	10	1	1	0	0	0	1	0	0	0	0	10	100%	
	Allocated: CUV	10	10	9	9	10	9	6	9	8	7	9	6	4	40%	
	Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	10	2	0	1	0	1	1	1	4	2	7	0	10	100%	
	Total		133	79	42	29	13	15	17	14	23	23	35	13	120	90%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak																
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied														
P452	A	70	61	48	17	6	0	7	7	6	27	49	0	70	100%														
	B																												
	S																												
	Visitor: PAD																												
	Visitor:																												
	Reserved: ZIP															3	2	2	2	3	3	3	3	3	3	3	2	1	33%
	Allocated: EV															7	1	0	0	0	0	0	1	0	3	3	0	7	100%
	Allocated: GPO															6	5	5	6	2	1	0	3	2	3	5	0	6	100%
	Allocated: BCP															12	9	7	6	6	4	6	6	7	9	10	4	8	67%
	Allocated:																												
	Allocated:																												
Allocated:																													
Accessible	10	4	4	1	1	0	0	0	1	3	4	0	10	100%															
UC Vehicle + Cart	3	1	0	0	0	1	1	1	1	1	1	0	3	100%															
Service Yard Loading																													
Total	111	83	66	32	18	9	17	21	20	49	75	9	102	92%															
P453	A	93	50	7	0	0	1	0	1	2	9	21	0	93	100%														
	B																												
	S																												
	Visitor: PAD															52	50	40	19	21	2	6	14	13	23	38	2	50	96%
	Visitor:																												
	Reserved																												
	Allocated: EV															6	4	2	0	0	0	0	1	1	1	1	0	6	100%
	Allocated: V1G															4	4	3	2	1	1	1	1	1	1	1	1	3	75%
	Allocated:																2	2	2	2	2	2	2	1	1	1			
	Allocated:																												
	Allocated:																												
Accessible																													
UC Vehicle + Cart	4											0	4	100%															
Service Yard Loading																													
Total	159	110	54	23	24	6	9	19	18	35	62	6	153	96%															
P454	A	153	135	59	0	0	0	2	7	13	19	26	0	153	100%														
	B																												
	S																												
	Visitor:																												
	Visitor:																												
	Reserved																												
	Allocated:															3	3	2	2	3	3	3	3	3	3	3			
	Allocated:																												
	Allocated:																												
	Allocated:																												
	Allocated:																												
Accessible																													
UC Vehicle + Cart	4											0	4	100%															
Service Yard Loading																													
Total	157	138	62	2	2	3	5	10	16	22	29	2	155	99%															

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P455	A	155	154	142	59	51	29	27	38	46	52	59	27	128	83%
	B														
	S														
	Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle + Cart Service Yard Loading	3	3	3	3	3	3	3	3	3	3	3	3	3	0
Total	158	157	145	62	54	32	30	41	49	55	62	30	128	81%	
P456	A	123	3	0	0	0	0	0	0	2	8	17	0	123	100%
	B														
	S														
	Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading														
Total	123	3	0	0	0	0	0	0	2	8	17	0	123	100%	
P501	A														
	B														
	S														
	Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	5	5	2	1	1	0	0	0	1	1	1	0	5	100%
	6	2	4	5	6	4	4	4	5	5	5	2	4	67%	
Total	11	7	6	6	7	4	4	4	6	6	6	4	7	64%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P502	A	146	120	76	16	2	0	3	13	15	30	70	0	146	100%	
	B	185	81	13	0	0	0	4	2	3	17	25	0	185	100%	
	S															
	Visitor: PAD	12	5	5	0	0	0	0	0	1	1	1	0	12	100%	
	Visitor: Reserved	8	2	3	4	4	4	4	5	5	5	5	2	6	75%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible UC Vehicle Service Yard Loading	4	3	3	2	0	0	0	3	2	2	2	0	4	100%	
Total		355	211	100	22	6	4	11	23	26	55	103	4	351	99%	
P503	A	2	0	0	0	0	0	0	0	0	0	1	0	2	100%	
	B															
	S															
	Visitor:	4	1	1	0	1	0	0	0	0	0	2	0	4	100%	
	Visitor: Reserved	34	32	30	21	19	22	20	19	23	20	22	19	15	44%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible UC Vehicle Service Yard Loading	6	3	1	0	0	0	0	0	1	1	4	0	6	100%	
	3	3	3	2	2	1	1	1	1	1	1	1	2	67%		
Total		49	39	35	23	22	23	21	20	25	22	30	20	29	59%	
P504	A															
	B															
	S	29	0	0	0	0	0	0	1	0	0	0	0	29	100%	
	Visitor: PAD	12	2	2	0	0	0	2	2	2	2	1	0	12	100%	
	Visitor: Reserved	3	2	1	2	1	1	3	3	4	4	7	1	2	67%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible UC Vehicle Service Yard Loading	6	0	0	0	0	0	0	0	0	0	2	0	6	100%	
	4	2	1	1	1	0	0	0	1	1	2	0	4	100%		
Total		54	6	4	3	2	1	5	6	7	7	12	1	53	98%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P505	A															
	B															
	S															
	Visitor: Reserved	4	4	4	1	1	2	2	1	2	2	2	2	1	3	75%
Allocated: Allocated: Allocated: Allocated: Accessible																
UC Vehicle Service Yard Loading	1	0	0	1	1	1	0	1	0	1	1	1	0	1	100%	
Total		5	4	4	2	2	3	2	2	2	3	3	2	3	60%	
P506	A	3	0	1	0	0	0	0	0	0	1	2	0	3	100%	
	B															
	S															
	Visitor: PAD	12	5	8	8	2	1	2	4	2	6	8	1	11	92%	
	Visitor: Reserved															
	Allocated: Allocated: Allocated: Allocated: Accessible															
	UC Vehicle	2	0	1	2	1	1	1	1	1	2	1	0	2	100%	
	Service Yard Loading	2 3	1 1	1 1	1 1	1 1	1 1	1 2	1 2	0 2	0 2	1 2	0 1	2 2	100% 67%	
Total		22	7	12	12	5	4	6	8	5	11	14	4	18	82%	
P507	A	51	13	9	7	2	1	2	8	15	20	31	1	50	98%	
	B															
	S															
	Visitor: PAD	16	10	8	0	7	7	1	1	1	1	1	0	16	100%	
	Visitor: Reserved															
	Allocated: KPU	1	1	1	1	0	1	1	1	1	1	1	0	1	100%	
	Allocated: LS	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
	Allocated: PVIS	2	2	2	2	1	2	0	0	0	0	0	0	2	100%	
	Allocated: TMS	2	0	1	1	2	1	1	1	0	0	0	0	2	100%	
	Allocated: TMS Carts	12	9	10	4	6	5	4	7	7	8	9	4	8	67%	
	Allocated: EV	4	2	0	1	1	1	2	1	0	0	0	0	4	100%	
	Accessible	9	2	2	2	3	3	3	3	4	4	4	2	7	78%	
	UC Vehicle	129	41	64	47	64	53	57	45	43	38	34	34	95	74%	
	Service Yard Loading	8 8	2 3	2 1	1 4	1 4	1 3	1 3	0 2	2 2	2 3	2 3	0 1	8 7	100% 88%	
Total		243	85	100	70	91	78	72	69	75	77	85	69	174	72%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P508	A	9	0	0	0	0	0	0	0	0	0	3	5	0	9	100%
	B															
	S															
	Visitor:	3	1	0	0	0	0	0	0	0	0	0	1	0	3	100%
	Visitor: Reserved	10	10	5	3	2	6	3	3	4	4	7	2	8	80%	
	Allocated:															
	Allocated:															
Allocated:																
Allocated:																
Accessible UC Vehicle	10	7	3	0	0	0	0	0	0	0	0	4	0	10	100%	
Service Yard																
Loading	3	3	3	0	0	0	0	0	0	0	0	1	0	3	100%	
Total		35	21	11	3	2	6	3	3	4	7	18	2	33	94%	
P509	A															
	B															
	S															
	Visitor:															
	Visitor: Reserved	1	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated:															
	Allocated:															
Allocated:																
Allocated:																
Accessible UC Vehicle																
Service Yard	4	3	3	1	1	0	1	0	2	2	2	2	0	4	100%	
Loading	1	1	1	0	0	0	0	0	0	0	0	0	0	1	100%	
Total		6	5	5	2	2	1	2	1	3	3	3	1	5	83%	
P510	A	29	11	5	0	1	0	1	0	3	3	7	0	29	100%	
	B	166	5	0	0	0	1	2	3	5	5	10	0	166	100%	
	S															
	Visitor: PAD	9	4	5	4	0	0	1	4	3	3	3	0	9	100%	
	Visitor: Reserved															
	Allocated: BCP	2	2	2	2	2	1	1	0	0	0	1	0	2	100%	
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible UC Vehicle																
Service Yard																
Loading																
Total		206	22	12	6	3	2	5	7	11	11	21	2	204	99%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P511	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	31	8	0	0	0	0	0	0	1	1	2	4	0	31	100%
	Total	31	8	0	0	0	0	0	0	1	1	2	4	0	31	100%
P601	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	10	4	4	1	1	2	2	2	3	2	6	1	9	90%	
	Total	10	4	4	1	1	2	2	2	3	2	6	1	9	90%	
P602	A	124	28	25	11	4	4	2	4	9	11	25	2	122	98%	
	B															
	S															
	Visitor:	5	3	2	2	0	0	1	2	2	2	2	0	5	100%	
	Visitor:															
	Reserved	80	66	63	52	48	51	55	44	44	51	63	44	36	45%	
	Reserved: FM	4	3	3	3	3	3	2	2	2	2	2	2	2	2	50%
	Reserved: SPP	2	2	2	2	2	2	2	2	2	2	2	2	2	0	0%
	Allocated: BCP	7	1	1	0	0	1	1	1	1	1	1	1	0	7	100%
	Allocated: EV	4	2	2	0	0	0	0	0	0	1	1	1	0	4	100%
	Allocated:															
Allocated:																
Accessible	4	1	1	0	0	1	1	1	1	1	1	1	0	4	100%	
UC Vehicle	2	0	1	0	0	0	0	0	0	0	0	1	0	2	100%	
Service Yard Loading																
Total	232	106	100	70	57	62	64	56	62	71	98	56	176	76%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
	Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	2	0	0	0	0	1	2	2	2	2	6	0	2	100%
	Total	8	3	3	3	3	3	6	5	6	7	11	3	5	63%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak				
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied		
P607	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	8	0	0	0	0	0	0	0	0	0	0	0	1	0	8	100%
	Total	8	0	0	0	0	0	0	0	0	0	0	0	1	0	8	100%
P608	A B S Visitor: Visitor: Reserved Allocated: RAR Allocated: ZIP Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	1 2 2 6	1 2 0 6	1 1 0 2	1 2 0 0	1 2 0 1	1 2 0 0	1 2 0 0	1 2 0 0	1 2 0 0	1 2 0 0	1 2 0 0	1 1 0 0	0 1 2 6	0% 50% 100% 100%		
	Total	11	9	4	3	4	3	3	3	3	3	3	3	3	8	73%	
P610	A B S Visitor: Visitor: Reserved Allocated: ACP Allocated: EV Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	120 2 6 5	VALET										1 0 0	1 6 5	50% 100% 100%		
	Total	133	7	5	1	1	2	2	2	3	3	5	1	132	99%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P651	A	250	0	1	0	0	0	0	7	12	18	45	0	250	100%	
	B															
	S															
	Visitor:															
	Visitor: Reserved															
	Allocated: EV		4	5	4	3	2	4	4	4	4	2	3	2	2	50%
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible		1	1	1	1	1	1	1	1	1	1	1	1	0	0%
UC Vehicle + Cart	5	3	3	2	3	2	2	1	1	1	1	1	4	80%		
Service Yard	2	2	2	2	2	2	2	2	2	2	2	2	0	0%		
Loading																
Total		262										0	262	100%		
P652	A	178	2	0	0	0	0	0	0	1	0	20	0	178	100%	
	B															
	S															
	Visitor:															
	Visitor: Reserved															
	Allocated: SCP		63	32	15	0	0	0	1	0	0	8	9	0	63	100%
	Allocated: EV		8	7	7	0	0	2	2	1	1	3	7	0	8	100%
	Allocated:															
	Allocated:															
	Accessible		6	5	6	5	4	2	3	1	1	1	2	1	5	83%
UC Vehicle + Cart	2	1	1	1	0	0	0	0	0	0	0	0	2	100%		
Service Yard																
Loading																
Total		257										0	257	100%		
P653	A	180	0	0	0	0	0	3	4	5	49	70	0	180	100%	
	B															
	S															
	Visitor:		47	24	11	2	0	2	2	5	6	3	5	0	47	100%
	Visitor: Reserved		2	1	2	1	2	2	2	2	2	2	2	1	1	50%
	Allocated: BCP		3	2	0	0	0	0	0	0	0	3	3	0	3	100%
	Allocated: EV		7	3	3	1	0	1	1	1	1	1	2	0	7	100%
	Allocated: PO		3	1	2	2	2	1	3	2	2	3	3	1	2	67%
	Allocated:															
	Allocated:															
	Accessible		6	5	4	1	1	1	1	1	3	3	4	1	5	83%
	UC Vehicle + Cart		5	4	4	3	3	3	3	2	4	4	5	2	3	60%
	Service Yard															
Loading																
Total		253	40	26	10	8	10	15	17	23	68	94	8	245	97%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P654	A	156	79	1	1	0	0	6	12	12	37	50	0	156	100%	
	B	89	0	0	0	0	0	0	3	5	48	72	0	89	100%	
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: EV	8	2	0	1	1	2	2	1	1	1	1	0	8	100%	
	Allocated:															
	Allocated:															
	Allocated:															
Accessible	6	3	3	2	1	1	1	1	1	2	4	1	5	83%		
UC Vehicle + Cart	2	2	2	2	1	2	1	2	2	2	2	1	1	50%		
Service Yard Loading																
Total		261	86	6	6	3	5	10	19	21	90	129	3	258	99%	
P655	A		0	0	0	0	2	0	6	18	69	119	0	253	100%	
	B	253														
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated: EV	6	6	0	0	0	1	1	1	2	3	4	0	6	100%	
	Allocated:															
	Allocated:															
	Allocated:															
Accessible	5	5	4	4	3	3	3	3	3	3	5	3	2	40%		
UC Vehicle + Cart	1	1	1	1	1	1	1	1	0	0	0	0	1	100%		
Service Yard Loading																
Total		265											0	265	100%	
P701	A		62	55	30	3	0	2	4	20	27	50	0	63	100%	
	B	63	179	47	73	33	4	14	20	29	40	77	4	253	98%	
	S	257														
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard Loading																
Total		320	241	102	103	36	4	16	24	49	67	127	4	316	99%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak																
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied															
P703	A	321	294	94	51	32	27	31	35	39	55	80	27	294	92%															
	B																													
	S																													
	Visitor:																													
	Visitor:																													
	Reserved: V2G															8												0	8	100%
	Allocated: AMB															2	8	8	6	3	9	9	8	9	12	13		3	-1	-50%
	Allocated: EV															4	1	2	2	0	1	1	2	2	1	1		0	4	100%
	Allocated: ROC															17	2	2	1	0	2	1	1	1	1	1		0	17	100%
	Allocated:																1	1	0	1	2	2	3	2	1	1				
	Allocated:																9	8	6	5	8	10	10	9	10	11				
	Accessible															12	2	2	2	2	2	2	2	2	2	2		2	10	83%
	UC Vehicle															10	8	2	2	4	5	6	7	7	8	8		2	8	80%
Service Yard																														
Loading	2	2	2	2	1	1	1	1	1	1	1		1	1	50%															
Total		376	327	121	72	48	57	63	69	72	91	118	48	328	87%															
P704	A	40	36	31	22	16	13	12	14	17	22	30	12	28	70%															
	B																													
	S																													
	Visitor:																													
	Visitor:																													
	Reserved																													
	Allocated:																													
	Allocated:																													
	Allocated:																													
	Allocated:																													
	Allocated:																													
	Accessible																													
	UC Vehicle																													
Service Yard																														
Loading																														
Total		618	510	385	302	226	148	137	141	147	356	363	137	481	78%															
P705	A	184	168	149	148	134	112	80	85	92	144	114	80	104	57%															
	B																													
	S																													
	Visitor:																													
	Visitor:																													
	Reserved																													
	Allocated:																													
	Allocated:																													
	Allocated:																													
	Allocated:																													
	Allocated:																													
	Accessible																													
	UC Vehicle																													
Service Yard																														
Loading																														
Total		184	168	149	148	134	112	80	85	92	144	114	80	104	57%															

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P706	A													0	0	#DIV/0!
	B															
	S															
	Visitor: Reserved	6	1	0	0	0	0	0	0	1	2	2	0	6	100%	
	Allocated: Preuss	69	42	18	16	11	7	15	18	20	21	39				
Allocated:																
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle Service Yard Loading	4	2	3	4	4	4	4	4	4	3	3	2	2	50%		
	3	3	1	0	1	1	1	1	1	1	1	0	3	100%		
Total	82	48	22	20	16	12	20	23	26	27	45	12	70	85%		
P721	A	177	122	64	13	12	18	23	28	30	41	47	12	165	93%	
	B															
	S															
	Visitor: Reserved															
	Allocated:															
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle Service Yard Loading																
Total	177	122	64	13	12	18	23	28	30	41	47	12	165	93%		
P722	A	194	0	5	1	1	2	3	7	7	9	11	0	194	100%	
	B															
	S															
	Visitor: Reserved	40	33	27	22	22	21	21	23	23	23	24	21	19	48%	
	Allocated: EV	3	0	0	0	0	1	2	1	1	0	2	0	3	100%	
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle Service Yard Loading	12	5	5	4	5	4	4	4	6	6	7	4	8	67%		
Total	249	38	37	27	28	28	30	35	37	38	44	27	222	89%		

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P723	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	242	18	0	0	0	0	0	0	0	12	17	21	0	242	100%
	Total	242	18	0	0	0	0	0	0	0	12	17	21	0	242	100%
P731	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	91	0	0	0	0	0	0	0	3	6	9	0	91	100%	
	58	56	50	31	8	4	3	10	10	13	13	3	55	95%		
Total	149	56	50	31	8	4	3	10	13	19	22	3	146	98%		
P732	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	181	116	95	33	9	13	17	28	49	50	55	9	172	95%	
	Total	181	116	95	33	9	13	17	28	49	50	55	9	172	95%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P733	A B S Visitor: PBS	136	31	12	0	0	4	3	3	7	7	9	0	136	100%
	Visitor: Reserved														
	Allocated: EV	3	0	0	0	1	1	1	0	0	2	2	0	3	100%
	Allocated: Allocated: Allocated: Allocated:														
	Accessible UC Vehicle Service Yard Loading	25	8	2	1	0	0	0	0	1	1	4	0	25	100%
Total		164	39	14	1	1	5	4	3	8	10	15	1	163	99%
P734	A B S Visitor: PBS	7	0	2	0	0	0	0	1	1	2	3	0	7	100%
	Visitor: Reserved	86	0	0	0	0	0	0	3	4	2	3	0	86	100%
	Reserved	2	2	2	2	2	6	2	2	2	2	2	2	0	0%
	Allocated: EV	2	8	6	5	6	2	5	4	3	3	3	2	0	0%
	Allocated: ER	10	0	0	0	0	1	1	0	0	1	1	0	10	100%
	Allocated: LJPV	1	0	0	0	0	0	0	0	2	1	1	0	1	100%
	Allocated: TO	5	3	3	3	3	4	4	4	4	3	4	3	2	40%
	Allocated: Allocated:						0								
	Accessible UC Vehicle Service Yard Loading	26	0	1	0	0	9	0	0	0	1	1	0	26	100%
	Total		139	13	14	10	11	22	12	14	16	15	18	10	129
P735	A B S Visitor: PBS	182	22	4	0	0	0	0	4	5	7	9	0	182	100%
	Visitor: Reserved														
	Allocated: Allocated: Allocated: Allocated:														
	Accessible UC Vehicle Service Yard Loading														
	Total		182	22	4	0	0	0	0	4	5	7	9	0	182

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P741	A	4	3	2	2	1	2	1	0	1	2	1	0	4	100%	
	B															
	S															
	Visitor: PBS	64	23	2	4	6	22	25	24	26	28	29	2	62	97%	
	Visitor: Reserved	12	0	0	0	1	1	0	1	1	1	1	0	12	100%	
	Allocated: EV	5	1	3	0	2	4	4	4	2	3	3	0	5	100%	
Allocated: LJPV																
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle	58	39	20	7	2	12	14	14	16	17	18	2	56	97%		
Service Yard Loading																
Total		143	66	27	13	12	41	44	43	46	51	52	12	131	92%	
P742	A	17	5	2	9	0	0	0	0	1	3	7	0	17	100%	
	B															
	S															
	Visitor: PBS	155	109	87	31	46	65	64	60	73	90	111	31	124	80%	
	Visitor: Reserved															
	Allocated: EV															
Allocated: LJPV																
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle	10	6	5	6	5	6	5	5	7	8	8	5	5	50%		
Service Yard Loading																
Total		182	120	94	46	51	71	69	65	81	101	126	46	136	75%	
P743	A	57	25	17	12	11	18	15	17	20	25	37	11	46	81%	
	B	103	0	0	0	0	1	1	1	10	17	27	0	103	100%	
	S															
	Visitor: PBS	39	25	20	19	11	21	22	19	20	25	31	11	28	72%	
	Visitor: Reserved															
	Allocated: EV															
Allocated: LJPV																
Allocated:																
Allocated:																
Allocated:																
Accessible UC Vehicle	9	6	5	6	5	5	5	5	6	6	7	5	4	44%		
Service Yard Loading																
Total		208	56	42	37	27	45	43	42	56	73	102	27	181	87%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak					
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied				
P744	A	117	87	70	46	39	35	34	47	50	56	62	39	184	83%				
	B	100	0	0	0	1	1	1	5	10	17	0				100	100%		
	S																		
	Visitor:																		
	Visitor:																		
	Reserved	6	5	4	4	4	4	4	4	5	5	5				4	2	33%	
	Allocated:																		
	Allocated:																		
	Allocated:																		
	Allocated:																		
Accessible UC Vehicle Service Yard Loading																			
Total		223	92	74	50	43	40	39	52	60	71	84							
P745	A	222	17	0	0	1	4	15	17	20	22	37	0	222	100%				
	B																		
	S																		
	Visitor: B2390																		
	Visitor:																		
	Reserved																		
	Allocated:EV		2	0	0	0	0	0	0	0	0	0				0	0	2	100%
	Allocated:																		
	Allocated:																		
	Allocated:																		
Accessible UC Vehicle Service Yard Loading																			
Total		224	17	0	0	1	4	15	17	20	22	37	0	224	100%				
P746	A	150	74	35	16	9	7	7	20	23	29	36	7	143	95%				
	B																		
	S																		
	Visitor:																		
	Visitor:																		
	Reserved																		
	Allocated: EV		8	0	0	0	0	0	0	0	0	0				0	0	8	100%
	Allocated:																		
	Allocated:																		
	Allocated:																		
Accessible UC Vehicle Service Yard Loading																			
Total		158	74	35	16	9	7	7	20	23	29	36	7	151	96%				

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P747	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	100	99	49	6	0	2	10	21	34	37	50	0	100	100%	
	Total	100	99	49	6	0	2	10	21	34	37	50	0	100	100%	
P751	A B S Visitor: PBS Visitor: Reserved Allocated: VAL Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	104											0	104	100%	
													0	0	#DIV/0!	
		13	3	0	0	2	3	4	5	3	3	4	0	13	100%	
		3	1	0	0	0	0	0	0	0	1	2				
	Total	120	4	0	0	2	3	4	5	3	4	6	0	120	100%	
P752	A B S Visitor: Visitor: Reserved Allocated: POC Allocated: VAL Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
		4	4	4	1	1	3	4	3	3	3	4	1	3	75%	
		24											0	24	100%	
		2	1	0	0	0	0	0	0	0	0	0	0	2	100%	
	Total	31	5	4	1	1	3	4	3	3	3	4	1	30	97%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P753	A	14	1	0	0	1	0	1	1	1	3	4	0	14	100%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved	14	6	7	7	7	5	6	6	7	7	7	5	9	64%
	Allocated:														
Allocated:															
Allocated:															
Allocated:															
Accessible	2	0	0	0	0	0	0	0	0	1	1	0	2	100%	
UC Vehicle	3	0	0	0	0	1	1	0	0	1	0	0	3	100%	
Service Yard															
Loading	1	0	0	0	0	1	1	1	1	1	0	0	1	100%	
Total		34	7	7	7	8	7	9	8	9	13	12	7	27	79%
P757	A														
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved	7	6	3	3	3	4	5	5	3	4	2	2	5	71%
	Allocated:														
Allocated:															
Allocated:															
Allocated:															
Accessible															
UC Vehicle	2	0	1	2	0	0	1	2	2	1	2	0	2	100%	
Service Yard															
Loading	4	4	4	1	2	4	4	4	4	3	3	1	3	75%	
Total		13	10	8	6	5	8	10	11	9	8	7	5	8	62%
P758	A														
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated: BCP	1	0	0	0	0	0	0	0	0	1	1	0	1	100%
	Allocated: CAV	1	0	0	0	0	0	0	0	0	0	1	0	1	100%
	Allocated:														
	Allocated:														
Allocated:															
Accessible	2	0	0	0	0	0	0	0	0	1	1	0	2	100%	
UC Vehicle	4	0	0	0	1	2	2	1	1	0	1	0	4	100%	
Service Yard															
Loading	5	0	0	0	0	1	1	1	1	1	3	0	5	100%	
Total		13	0	0	0	1	3	3	2	2	3	7	0	13	100%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak						
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied				
P759	A	44	7	0	0	0	1	1	2	5	11	17	0	44	100%				
	B																		
	S																		
	Visitor:																		
	Visitor:																		
	Reserved		32	15	19	19	20	19	17	17	11	14				20	11	21	66%
	Allocated: ADRC		10	9	7	5	3	6	5	6	6	7				9	3	7	70%
	Allocated: HDCRC		2	2	2	1	1	1	1	2	1	1				1	1	1	50%
	Allocated: VAL		6														0	6	100%
	Allocated:																		
	Allocated:																		
	Accessible		11	0	0	0	0	1	1	1	1	0				0	0	11	100%
	UC Vehicle		2	0	0	0	0	1	1	0	0	0				0	0	2	100%
Service Yard	3	0	0	0	0	0	1	0	0	0	0	0	3	100%					
Loading	6	0	0	0	0	0	0	0	0	1	2	0	6	100%					
Total		116	26	28	25	24	28	26	26	19	23	32	19	97	84%				
P760	A	74	58	30	19	25	25	26	21	24	40	48	19	55	74%				
	B	111	1	0	0	0	0	0	0	10	20	25	0	111	100%				
	S																		
	Visitor: PBS	50	35	7	6	8	16	15	10	12	17	23	6	44	88%				
	Visitor:																		
	Reserved	1	1	1	1	1	1	1	1	1	1	1	1	0	0%				
	Allocated:																		
	Allocated:																		
	Allocated:																		
	Allocated:																		
	Accessible	11	5	0	0	1	1	0	0	0	3	6	0	11	100%				
	UC Vehicle	1	1	1	1	0	1	0	0	1	1	1	0	1	100%				
	Service Yard																		
Loading	4	3	2	0	3	3	2	2	2	2	2	0	4	100%					
Total		252	104	41	27	38	47	44	34	50	84	106	27	225	89%				
P761	A																		
	B																		
	S																		
	Visitor:																		
	Visitor:																		
	Reserved																		
	Allocated:																		
	Allocated:																		
	Allocated:																		
	Allocated:																		
Accessible																			
UC Vehicle	3	1	0	0	1	0	0	1	0	0	0	0	3	100%					
Service Yard	3	0	0	0	0	0	0	1	2	2	1	0	3	100%					
Loading	3	0	1	0	1	2	1	1	1	1	1	0	3	100%					
Total		9	1	1	0	2	2	1	3	3	3	2	0	9	100%				

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P762	A															
	B															
	S															
	Visitor:															
	Visitor:															
Reserved																
Allocated:																
Allocated:																
Allocated:																
Allocated:																
Accessible																
UC Vehicle																
Service Yard		3	2	1	0	2	0	0	0	0	1	1	0	3	100%	
Loading		1	1	0	0	1	0	0	0	0	1	1	0	1	100%	
Total		4	3	1	0	3	0	0	0	0	2	2	0	4	100%	
P782	A															
	B															
	S	243	211	208	207	209	206	203	198	193	173	171	171	72	30%	
	Visitor:															
	Visitor:															
Reserved																
Allocated:																
Allocated:																
Allocated:																
Allocated:																
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		243	211	208	207	209	206	203	198	193	173	171	171	72	30%	
P784	A															
	B	78	0	0	0	0	0	0	0	0	0	0	0	78	100%	
	S															
	Visitor:															
	Visitor:															
Reserved																
Allocated: VAL	12	11	8	0	0	2	3	2	2	2	2	2	0	12	100%	
Allocated:																
Allocated:																
Allocated:																
Accessible	18	0	0	0	2	1	1	1	1	1	1	1	0	18	100%	
UC Vehicle																
Service Yard																
Loading																
Total		108	11	8	0	2	3	4	3	3	3	3	0	108	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P785	A	384	18	0	0	0	0	0	0	0	0	0	0	0	384	100%
	B															
	S															
	Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	8	6	6	2	3	5	5	5	4	5	4	2	6	75%	
	Total	392	24	6	2	3	5	5	5	4	5	4	2	390	99%	
P901	A	41	41	41	41	41	41	41	41	41	41	41	41	0	0%	
	B															
	S															
	Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	41	41	41	41	41	41	41	41	41	41	41	41	0	0%	
	Total	41	41	41	41	41	41	41	41	41	41	41	41	0	0%	
P902	A	41	41	41	41	41	41	41	41	40	41	41	40	1	2%	
	B															
	S															
	Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	41	41	41	41	41	41	41	41	40	41	41	40	1	2%	
	Total	41	41	41	41	41	41	41	41	40	41	41	40	1	2%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P903	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	39	38	38	38	36	37	37	35	36	36	37	35	4	10%
	Total	39	38	38	38	36	37	37	35	36	36	37	35	4	10%
P904	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	39	36	30	29	19	20	17	10	18	28	31	10	29	74%
	Total	39	36	30	29	19	20	17	10	18	28	31	10	29	74%
P905	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	39	32	12	7	0	9	0	1	11	15	25	0	39	100%
	Total	39	32	12	7	0	9	0	1	11	15	25	0	39	100%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P906	A B S Visitor: PBS Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	39	7	9	0	0	0	0	1	0	16	18	0	39	100%
	Total	39	7	9	0	0	0	0	1	0	16	18	0	39	100%
P907	A B S Visitor: PBS Visitor: Reserved Allocated: HPV Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	35	0	0	0	0	0	0	0	0	2	2	0	35	100%
	4	4	3	4	4	4	1	3	2	3	4	1	3	75%	
Total	39	4	3	4	4	4	1	3	2	5	6	1	38	97%	
P908	A B S Visitor: Visitor: Reserved Allocated: TO Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	2	2	2	2	1	1	2	2	2	2	2	1	1	50%
	10	1	1	1	2	1	1	1	2	2	0	0	10	100%	
2	1	0	2	2	1	1	2	2	2	2	2	0	2	100%	
Total	14	4	3	5	5	3	4	5	6	6	4	3	11	79%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P909	A													0	0	#DIV/0!
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	18	15	13	13	8	11	12	11	11	12	12	8	10	56%	
	Allocated: EV	12	6	2	10	3	2	6	5	4	5	10	2	10	83%	
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		30	21	15	23	11	13	18	16	15	17	22	11	19	63%	
P910	A	44	13	0	0	0	3	0	0	2	6	4	0	44	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible	3	2	1	0	0	0	0	0	0	0	0	0	3	100%		
UC Vehicle																
Service Yard																
Loading																
Total		47	15	1	0	0	3	0	0	2	6	4	0	47	100%	
P911	A	47	14	0	0	1	5	2	0	6	8	15	0	47	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard																
Loading																
Total		47	14	0	0	1	5	2	0	6	8	15	0	47	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P912	A	45	25	9	0	1	1	4	2	8	10	19	0	45	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible	1	1	1	1	1	0	1	1	0	0	0	0	1	100%	
	UC Vehicle															
	Service Yard															
	Loading															
	Total	46	26	10	1	2	1	5	3	8	10	19	1	45	98%	
P913	A	47	46	45	30	27	25	24	27	29	31	31	24	23	49%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible															
	UC Vehicle															
	Service Yard															
	Loading															
	Total	47	46	45	30	27	25	24	27	29	31	31	24	23	49%	
P914	A	43	43	43	42	37	37	38	36	36	39	39	36	7	16%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
	Accessible	1	1	1	1	1	1	0	1	1	1	1	0	1	100%	
	UC Vehicle															
	Service Yard															
	Loading															
	Total	44	44	44	43	38	38	38	37	37	40	40	37	7	16%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak						
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied					
P921	A	53	45	27	24	25	26	10	12	13	21	28	10	43	81%					
	B																			
	S																			
	Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading		2	1	1	1	1	1	1	0	0	0				1	0	2	100%	
Total		55	46	28	25	26	27	11	12	13	21	29	11	44	80%					
P922	A	80	2	5	2	2	2	12	13	17	26	35	2	78	98%					
	B																			
	S																			
	Visitor: Visitor: Reserved																			
	Allocated: BPO		4	4	2	3	3	4	4	4	4	4				4	2	2	50%	
	Allocated: EV		5	6	6	6	6	6	6	6	6	5				5	5	0	0%	
	Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading		2	1	2	2	2	2	2	1	1	2				2	1	1	50%	
	Total			91	13	15	13	13	14	24	24	28				37	46	13	78	86%
P923	A	99	52	52	46	40	41	15	19	22	32	54	15	84	85%					
	B																			
	S																			
	Visitor: Visitor: Reserved																			
	Allocated: TO		3	2	2	2	2	3	1	1	1	1				1				
	Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading																			
	Total			102	54	54	48	42	44	16	20	23				33	55	16	86	84%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P924	A	103	58	34	29	20	20	32	34	36	44	60	20	83	81%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	103	58	34	29	20	20	32	34	36	44	60	20	83	81%
P925	A	175	107	125	124	120	116	71	77	79	95	124	71	104	59%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible														
	UC Vehicle														
	Service Yard														
	Loading														
	Total	175	107	125	124	120	116	71	77	79	95	124	71	104	59%
P926	A	125	0	0	0	1	2	3	0	6	14	25	0	125	100%
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible	2	0	0	0	0	0	0	0	0	1	2	0	2	100%
	UC Vehicle														
	Service Yard														
	Loading														
	Total	127	0	0	0	1	2	3	0	6	15	27	0	127	100%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P927	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	86	0	1	0	0	2	2	3	10	28	43	0	86	100%	
	Total	86	0	1	0	0	2	2	3	10	28	43	0	86	100%	
P928	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	91	29	11	1	0	3	3	5	4	25	48	0	91	100%	
	Total	91	29	11	1	0	3	3	5	4	25	48	0	91	100%	
P929	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	85	9	9	6	3	4	0	3	16	33	43	0	85	100%	
	Total	85	9	9	6	3	4	0	3	16	33	43	0	85	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces											At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P930	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	91	49	28	20	15	14	7	16	15	21	42	7	84	92%	
	Total	91	49	28	20	15	14	7	16	15	21	42	7	84	92%	
P931	A B S Visitor: Visitor: Reserved Allocated: Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	28	8	0	0	1	0	6	12	13	28	40	0	28	100%	
	Total	28	8	0	0	1	0	6	12	13	28	40	0	28	100%	
P941	A B S Visitor: Visitor: Reserved Allocated: 140P Allocated: Allocated: Allocated: Allocated: Accessible UC Vehicle Service Yard Loading	32	32	29	30	28	27	18	19	21	18	22	18	14	44%	
	3	3	2	1	3	3	1	0	1	1	1	1	0	3	100%	
Total		35	35	31	31	31	30	19	19	22	19	23	19	16	46%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P942	A	11	8	8	8	8	6	6	3	3	4	9	3	8	73%
	B	21	5	2	1	1	2	0	0	7	9	11	0	21	100%
	S														
	Visitor:														
	Visitor:														
	Reserved	2	2	2	2	2	2	2	2	2	2	2	2	0	0%
	Allocated: 140P	3	3	3	3	3	3	3	3	3	3	3	3	0	0%
	Allocated: 140V	7	7	7	7	7	7	7	7	7	7	7	7	0	0%
	Allocated:														
	Allocated:														
Accessible UC Vehicle Service Yard Loading	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
Total		45	25	22	21	21	20	18	15	22	25	32	15	30	67%
P952	A														
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated: LET	4	2	2	2	2	2	2	2	2	2	2	2	2	50%
	Allocated:												0	0	#DIV/0!
	Allocated:														
	Allocated:														
Accessible UC Vehicle Service Yard Loading	2											0	2	100%	
	4	0	0	1	0	0	0	0	0	0	1	0	4	100%	
	6	1	0	0	1	1	1	1	0	2	2	0	6	100%	
Total		16	0	1	2	2	2	2	3	0	3	3	0	16	100%
P953	A														
	B	7	0	0	1	0	1	0	0	0	0	3	0	7	100%
	S														
	Visitor:														
	Visitor:														
	Reserved	4	0	0	0	0	0	0	0	0	0	0	0	4	100%
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible UC Vehicle Service Yard Loading	3	0	0	0	0	0	0	0	2	0	2	0	3	100%
	3	0	0	1	2	2	1	0	0	0	1	0	3	100%	
Total		17	0	0	2	2	3	1	0	2	0	6	0	17	100%

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak			
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied	
P954	A															
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	24	18	18	17	16	14	14	14	15	16	18	14	10	42%	
	Allocated: AMB	1	1	1	1	1	1	1	1	1	1	1	1	0	0%	
	Allocated: BFH	12	9	9	9	9	10	11	11	10	8	9	8	4	33%	
	Allocated:															
	Allocated:															
Allocated:																
Accessible	3	2	2	2	2	1	1	1	1	1	1	1	2	67%		
UC Vehicle																
Service Yard																
Loading																
Total		40	30	30	29	28	26	27	27	27	26	29	26	14	35%	
P955	A	12	1	0	2	3	1	0	0	2	4	6	0	12	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved	20	17	13	14	13	17	13	7	13	15	15	7	13	65%	
	Allocated: FL	1	0	0	0	0	0	0	0	0	0	0	0	1	100%	
	Allocated: FPM	1	1	1	1	1	0	0	0	0	0	0	0	1	100%	
	Allocated:															
	Allocated:															
Allocated:																
Accessible	1	0	0	0	0	0	0	0	0	0	0	0	1	100%		
UC Vehicle	7	3	2	4	5	5	5	0	0	0	0	0	7	100%		
Service Yard	6	0	0	1	2	1	1	3	0	0	0	0	6	100%		
Loading	2	0	0	1	0	1	1	0	0	0	0	0	2	100%		
Total		50	22	16	23	24	25	20	10	15	19	21	10	40	80%	
P956	A	2	0	0	0	0	0	0	0	2	2	2	0	2	100%	
	B															
	S															
	Visitor:															
	Visitor:															
	Reserved															
	Allocated:															
	Allocated:															
	Allocated:															
	Allocated:															
Accessible																
UC Vehicle																
Service Yard	3	0	0	1	0	1	1	1	1	2	2	0	3	100%		
Loading	3	0	0	0	1	1	0	0	1	1	2	0	3	100%		
Total		8	0	0	1	1	2	1	1	4	5	6	0	8	100%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Lot

Lot	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
P957	A	12	0	0	0	0	0	0	1	4	4	6	0	12	100%
	B	5	0	0	0	0	0	1	1	1	1	3	0	5	100%
	S														
	Visitor:														
	Visitor:														
	Reserved	22	20	14	11	10	8	9	7	12	17	18	7	15	68%
	Allocated: AVRC	16	10	6	0	2	4	6	4	8	4	4	0	16	100%
	Allocated: CTC	3	3	3	3	2	2	1	2	2	2	2	1	2	67%
	Allocated: MV	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: ZIP	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
	Allocated: MD5MIN	1	1	1	1	1	1	1	1	1	1	1	1	0	0%
	Allocated:														
	Accessible	11	0	1	0	0	0	2	2	2	5	7	0	11	100%
	UC Vehicle	2	0	0	0	2	1	1	1	1	0	1	0	2	100%
Service Yard Loading	2	2	1	0	2	0	1	1	1	1	1	0	2	100%	
Total	76	36	26	15	19	16	22	20	32	35	43	15	61	80%	
P958	A														
	B														
	S														
	Visitor:														
	Visitor:														
	Reserved	5	4	3	3	1	3	3	3	2	3	3	1	4	80%
	Reserved: STEMI	6	4	3	4	3	4	4	4	4	4	4	3	3	50%
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible														
	UC Vehicle														
	Service Yard Loading														
Total	11	8	6	7	4	7	7	7	6	7	7	4	7	64%	
P962	A														
	B	118	40	16	8	10	10	19	21	28	40	75	8	110	93%
	S														
	Visitor:														
	Visitor:														
	Reserved														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Allocated:														
	Accessible														
	UC Vehicle														
	Service Yard Loading														
Total	118	40	16	8	10	10	19	21	28	40	75	8	110	93%	

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Structure

Structure	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Hopkins (P341-7)	A	84	69	63	32	0	0	5	7	11	13	15	0	84	100%
	B	495	239	227	57	0	0	11	13	22	26	33	0	495	100%
	S	663	17	14	0	0	0	0	0	0	3	3	0	663	100%
	Visitor	95	40	35	17	1	0	6	10	12	18	22	0	95	100%
	Reserved	7	3	3	3	3	3	3	3	4	4	4	3	4	57%
	Allocated	29	14	14	9	5	5	6	8	11	12	14	5	24	83%
	Accessible	25	19	18	17	11	10	11	11	14	14	15	10	15	60%
	UC Vehicle	6	1	1	1	1	1	0	0	2	2	2	0	6	100%
	Service Yard Loading														
Total		1404	402	375	136	21	19	42	52	76	92	108	19	1385	99%
Pangea (P371-6)	A	91	71	59	49	0	0	2	5	8	9	13	0	91	100%
	B	324	232	157	66	0	0	8	13	25	30	39	0	324	100%
	S	340	0	0	0	0	0	0	0	0	0	0	0	340	100%
	Visitor	145	130	116	102	15	11	15	23	29	33	38	11	134	92%
	Reserved	8	8	4	6	6	5	6	6	7	7	7	4	4	50%
	Allocated	20	12	12	11	7	8	9	10	12	12	13	7	13	65%
	Accessible	15	10	10	9	7	7	6	8	10	10	11	6	9	60%
	UC Vehicle	9	4	5	6	7	6	3	4	5	4	5	3	6	67%
	Service Yard Loading														
Total		952	467	363	249	42	37	49	69	96	105	126	37	915	96%
Torrey Pines Center South (P381-2)	A														
	B	377	180	143	104	113	121	107	120	142	151	163	104	273	72%
	S	4	3	3	3	3	2	1	1	3	3	3	1	3	75%
	Visitor	9	6	7	8	4	2	1	1	3	3	3	1	8	89%
	Reserved	4	3	3	3	3	3	3	4	4	4	4	3	1	25%
	Allocated	32	20	17	12	16	19	12	18	18	18	19	12	20	63%
	Accessible	10	7	6	4	6	6	6	5	5	5	6	4	6	60%
	UC Vehicle	7	3	3	3	3	3	3	2	2	2	2	2	5	71%
	Service Yard Loading	1	0	0	0	0	0	0	0	0	0	0	0	1	100%
Total		444	222	182	137	148	156	133	151	177	186	200	133	311	70%

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Structure

Structure	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Torrey Pines Center North (P391-4)	A	199	78	49	22	21	27	38	25	44	65	96	21	178	89%
	B	5	1	1	0	0	1	1	0	1	1	1	0	5	100%
	S	7	6	5	5	5	6	6	7	7	7	7	5	2	29%
	Visitor	1	1	1	1	1	1	1	0	0	1	1	0	1	100%
	Reserved	3	3	3	2	2	2	2	2	2	3	2	2	1	33%
	Allocated	1	0	0	0	0	0	0	0	0	0	1	0	1	100%
	Accessible	1	1	0	0	2	0	1	0	1	1	1	0	1	100%
	UC Vehicle Service Yard	1	1	0	0	2	0	1	0	1	1	1	0	1	100%
	Loading	1	1	0	0	2	0	1	0	1	1	1	0	1	100%
	Total		217	90	59	30	31	37	49	34	55	78	109	30	187
Gilman (P451-6)	A	401	339	208	59	51	30	29	46	61	80	106	29	372	93%
	B	123	3	0	0	0	0	0	0	2	8	17	0	123	100%
	S	222	165	119	54	29	4	20	21	27	61	103	4	218	98%
	Visitor	6	5	3	2	4	6	6	6	6	6	6	2	4	67%
	Reserved	55	48	32	28	23	20	18	27	23	28	33	18	37	67%
	Allocated	20	6	4	2	1	1	1	1	5	5	11	1	19	95%
	Accessible														
	UC Vehicle Service Yard														
	Loading														
	Total		827	566	366	145	108	61	74	101	124	188	276	61	766
Osler (P651-5)	A	156	79	1	1	0	0	6	12	12	37	50	0	156	100%
	B	522	0	0	0	0	2	3	13	28	166	261	0	522	100%
	S	428	2	1	0	0	0	0	7	13	18	65	0	428	100%
	Visitor	47	24	11	2	0	2	2	5	6	3	5	0	47	100%
	Reserved	102	58	31	7	5	11	14	10	11	24	32	5	97	95%
	Allocated	24	19	18	13	10	8	9	7	9	10	16	7	17	71%
	Accessible	15	11	11	9	8	8	7	6	7	7	8	6	9	60%
	UC Vehicle Service Yard	2	2	2	2	2	2	2	2	2	2	2	2	0	0%
	Loading														
	Total		1296	195	75	34	25	33	43	62	88	267	439	25	1271

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Structure

Structure	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Campus Point East (P721-2)	A	194	0	5	1	1	2	3	7	7	9	11	0	194	100%
	B	177	122	64	13	12	18	23	28	30	41	47	12	165	93%
	S														
	Visitor														
	Reserved	40	33	27	22	22	21	21	23	23	23	24	21	19	48%
	Allocated	3	0	0	0	0	1	2	1	1	0	2	0	3	100%
	Accessible	12	5	5	4	5	4	4	4	6	6	7	4	8	67%
	UC Vehicle Service Yard Loading														
Total	426	160	101	40	40	46	53	63	67	79	91	40	386	91%	
Campus Point West (P731-5)	A	7	0	2	0	0	0	0	1	1	2	3	0	7	100%
	B	91	0	0	0	0	0	0	0	3	6	9	0	91	100%
	S														
	Visitor	643	225	161	64	17	21	23	48	75	79	89	17	626	97%
	Reserved	2	2	2	2	2	6	2	2	2	2	2	2	0	0%
	Allocated	79	67	59	39	18	12	14	18	19	23	24	12	67	85%
	Accessible	51	8	3	1	0	9	0	0	1	2	5	0	51	100%
	UC Vehicle Service Yard Loading														
Total	873	302	227	106	37	48	39	69	101	114	132	37	836	96%	
Athena (P741-7)	A	195	120	91	69	51	55	50	64	72	86	107	50	145	74%
	B	675	190	84	22	10	15	34	60	92	115	167	10	665	99%
	S														
	Visitor	258	157	109	54	63	108	111	103	119	143	171	54	204	79%
	Reserved	6	5	4	4	4	4	4	4	5	5	5	4	2	33%
	Allocated	27	1	3	0	3	5	4	5	3	4	4	0	27	100%
	Accessible	77	51	30	19	12	23	24	24	29	31	33	12	65	84%
	UC Vehicle Service Yard Loading														
Total	1238	524	321	168	143	210	227	260	320	384	487	143	1095	88%	

University of California, San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
By Structure

Structure	Parking Space	Parking Spaces	Empty Parking Spaces										At Peak		
			8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm	Empty Spaces	Occupied Spaces	% Occupied
Arbor (P901-14)	A	226	141	97	72	66	71	68	65	81	94	108	65	161	71%
	B														
	S														
	Visitor	273	195	171	156	137	148	136	129	146	179	195	129	144	53%
	Reserved	18	15	13	13	8	11	12	11	11	12	12	8	10	56%
	Allocated	18	12	7	16	8	7	9	10	8	10	16	7	11	61%
	Accessible	15	5	4	3	4	2	2	3	3	3	1	1	14	93%
	UC Vehicle Service Yard Loading	2	1	0	2	2	1	1	2	2	2	2	0	2	100%
Total	552	369	292	262	225	240	228	220	251	300	334	220	332	60%	
Bachman (P921-31)	A	1016	359	292	252	227	230	161	194	231	367	542	161	855	84%
	B														
	S														
	Visitor														
	Reserved														
	Allocated	12	12	10	11	11	13	11	11	11	10	10	10	2	17%
Accessible	6	2	3	3	3	3	3	1	1	3	5	1	5	83%	
UC Vehicle Service Yard Loading															
Total	1034	373	305	266	241	246	175	206	243	380	557	175	859	83%	
140 Arbor (P941-2)	A	11	8	8	8	8	6	6	3	3	4	9	3	8	73%
	B	21	5	2	1	1	2	0	0	7	9	11	0	21	100%
	S														
	Visitor														
	Reserved	2	2	2	2	2	2	2	2	2	2	2	2	0	0%
	Allocated	42	42	39	40	38	37	28	29	31	28	32	28	14	33%
	Accessible	4	3	2	1	3	3	1	0	1	1	1	0	4	100%
	UC Vehicle Service Yard Loading														
Total	80	60	53	52	52	50	37	34	44	44	55	34	46	58%	

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
Parking Spaces Closed

Lot	Parking Space	Parking Spaces Closed									
		8:00 am	9:00 am	10:00 am	11:00 am	12:00 pm	1:00 pm	2:00 pm	3:00 pm	4:00 pm	5:00 pm
P376	Visitor	20	20	20	20	20	20	20	20	20	20
P395	Visitor	2	2	2	2	2	0	0	0	0	0
P383	Visitors	1	1	1	2	1	1	0	0	0	0
P651	Allocated EV	3	3	3	3	3	3	3	3	3	3
P653	Visitor	5	5	5	5	5	5	5	5	5	5
P653	Allocated PO	2	2	2	2	2	2	2	2	2	2
P503	Visitor	3	0	0	0	0	0	0	0	0	3
P502	Visitor	1	1	1	1	1	1	1	1	1	1
P508	Visitor	1	1	1	1	1	1	1	1	1	1
P510	Visitor	0	0	0	0	0	1	1	1	1	1
Total		38	35	35	36	35	34	33	33	33	36

Includes parking spaces blocked off for special events, occupied by equipment, or undergoing minor maintenance. Excludes parking spaces lost (removed from inventory) for an extended time due to construction. A closed parking space was classified as occupied.

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
Visitor Parking Spaces

Abbreviation	Visitor Parking Space
Meter	Meter
PAD	Pay and Display
PBS	Pay by Space
PUE	Pay upon Exit

University of California San Diego Survey of Parking Space Occupancy Levels, Spring, 2019
Key to Locations, Areas, Neighborhoods, Lots, and Structures

University of California, San Diego																						
Location																						
La Jolla Campus																			Medical Center Hillcrest			
Area																						
Scripps Institution of Oceanography				West Campus												East Campus				Medical Center Hillcrest		
Neighborhood																						
SIO South	SIO West	SIO Hillside	Aquarium	Theatre District	Revelle College	Muir College	Marshall College	North Campus	Roosevelt College	North Torrey Pines and Glider Port	Warren College	Campus Services Complex	Sixth College	University Center	School of Medicine	East Campus Academic	Science Research Park	Health Sciences Structures	Health Sciences Lots	Hillcrest Structures	Hillcrest Lots	
Lot																						
P001	P009	P014	P017	P105	P101	P113		P351	P306	P381		P418	P507	P401	P405	P601	P701	P782	P721	P751	P901	P941
P002	P010	P015	P021		P102	P114		P352	P341	P382		P502	P510	P402	P407	P602	P703	P784	P722	P752	P902	P942
P003	P011	P016			P103	P201		P357	P342	P383		P503		P403	P408	P603	P704	P785	P731	P753	P903	P952
P004	P012				P106	P202		P358	P343	P384		P504		P404	P410	P605	P705		P732	P757	P904	P953
P005	P013				P107	P203		P359	P344	P385		P505		P406	P411	P606	P706		P733	P758	P905	P954
P006					P108	P204			P345	P386		P508		P405	P412	P607			P734	P759	P906	P955
P007					P110	P205			P346	P391		P509		P451	P413	P608			P735	P760	P907	P956
P008					P111	P206			P347	P392		P511		P452	P415	P610			P741	P761	P908	P957
					P112	P207			P353	P393				P453	P416	P651			P742	P762	P909	P958
					P116	P208			P354	P394				P454	P501	P652			P743		P910	
						P414			P371	P395				P455		P653			P744		P911	P964
									P372					P456		P654			P745		P912	P965
									P373					P506		P655			P746		P913	
									P374							P656			P747		P914	
									P375												P921	
									P376												P922	
																					P923	
																					P924	
																					P925	
																					P926	
																					P927	
																					P928	
																					P929	
																					P930	
																					P931	
																					P962	
																					P963	
Structure																						
								Hopkins (P341-7) Pangea (P371-6)		TPC South (P381-2) TPC North (P391-4)			Gilman (P451-6)		Osler (P651-6)		Campus Pt East (P721-2) Campus Pt West (P731-5) Athena (P741-7)				Arbor (P901-14) Bachman (P921-31) 140 Arbor (P941-2)	

University of California San Diego, Survey of Parking Space Inventory, Spring, 2019
Allocated Parking Spaces

Abbreviation	Allocated Parking Space
140P	140 Arbor Patient
140V	140 Arbor Visitor
ACP	A Carpool
ADRC	Alzheimers Disease Research Center Patient
AMB	Ambulance
AVRC	Antiviral Research Center / HIV Neurobehavioral Research Center Patient
BA	Birch Aquarium Visitor
BCP	B Carpool
BE	Building Engineer
BFH	Bannister Family House Patient/Visitor
BPO	Bachman Parking Office Visitor
CA	Coastal Access
CAL	Caltrans Vehicle
CAT	Catering Vehicle
CAV	Clean Air Vehicle
COMP	Compliance Vehicle
CUS	Credit Union Staff
CUV	Credit Union Visitor
ECO	East Campus West Office
EHS	Environment, Health, and Safety Vehicle
ERV	Emergency Response Vehicle
ESPP	Extended Studies and Public Programs Visitor
EV	Electric Vehicle
FC	Faculty Club Visitor
FEV	Fuel-efficient Vehicle
FL	Forklift
FM	Family Medicine Patient
FPM	Facilities Planning and Management Vehicle
GIC	Gilman Information Center Visitor
GPO	Gilman Parking Office Visitor
HDH	Housing, Dining, and Hospitality Vehicle
HDM	Housing/Dining Maintenance Vehicle
HDRC	Huntington's Disease Clinical Research Center
HM	Hazardous Materials Vehicle
HO	Hopkins Office Visitor
HPV	Medical Center Hillcrest Patient/Visitor
IC	International Center
KPU	Key Pickup
LET	Law Enforcement Transport Vehicle

University of California San Diego, Survey of Parking Space Inventory, Spring, 2019
Allocated Parking Spaces

Abbreviation	Allocated Parking Space
LG	Lifeguard
LJP	La Jolla Playhouse Visitor
LJPV	Medical Center La Jolla Patient/Visitor
LS	Live Scan Visitor
MD	Mail Drop
MIB	Muir Information Board Visitor
MOR	Mortuary Vehicle
MV	Mail Vehicle
NIC	North Point Information Center Visitor
NPA	NPA
PM	Property Management
POC	Physician On Call
PVIS	Police Visitor
RA	Retirement Association Visitor
RAR	Rita Atkinson Residences
RIB	Revelle Information Board Visitor
ROC	Radiation Oncology Center Patient/Visitor
RSM	Rady School of Management Visitor
SCP	S Carpool
SCRM	Sanford Consortium for Regenerative Medicine Staff
SHAS	Student Health Attending Staff
SHP	Student Health Patient
SIO	Scripps Institution of Oceanography Staff
SPP	Standardized Patient Program Patient
TH	Thornton Hospital
TO	Transportation Office Vehicle
UCC	UC Cart
UCEV	UC Electric Vehicles
V0796	UC Vehicle #0796
VAL	Valet
VP	Vanpool Vehicle
ZIP	Zipcar

University of California San Diego Survey of Parking Space Inventory, Spring, 2019
Schedule

Neighborhood	Week 1 Monday January 7	Week 2 Monday January 14	Week 3 Monday January 21	Week 4 Monday January 28	Week 5 Monday February 4	Week 6 Monday February 11	Week 7 Monday February 18	Week 8 Monday February 25	Week 9 Monday March 4	Week 10 Tuesday March 11	Week 11 Monday March 18	Week 12 Monday March 25
SIO South									Tuesday			
SIO West									Tuesday			
SIO Hillside									Tuesday			
Aquarium									Tuesday			
Theatre District			Tuesday									
Revelle College			Tuesday									
Muir College									Tuesday			
Marshall College			Wednesday									
Roosevelt College									Monday			
North Campus			Wednesday									
North Torrey Pines and Glider Port											Monday	
Warren College											Tuesday	
Campus Services Complex											Tuesday	
Sixth College							Tuesday					
School of Medicine				Wednesday							Wednesday	
University Center							Tuesday					
East Campus Academic				Wednesday								
Health Sciences 1 (A)												Wednesday
Health Sciences 2 (B)												Wednesday
Science Research Park												Wednesday
Medical Center Hillcrest 1 (a)												Monday
Medical Center Hillcrest 2 (b)												Monday

- (A) Athena Structure, Campus Point Structure East, West
- (B) P751, P752, P757-P762
- (a) Arbor Structure, Bachman Structure, Lot P962, Lot P963
- (b) 140 Arbor, surface lots